



Expertise

Protocol number: 41321961
Order No. / Reference: 25139365
Inspection date: 2 Sept 2025

Manufacturer: Skoda
VIN: TMBJK0NX4PY007100

Model: Octavia Combi 2.0 TDI DSG RS Plus



Vehicle details	
Manufacturer / Type / Model / Equipment	
Skoda Octavia Combi 2.0 TDI DSG RS Plus	
Vehicle Identification number	TMBJK0NX4PY007100
Mileage (Read)	52,115 km
First registration	4 Aug 2022
Number of holders	1
Next periodical technical inspection	08/2025
(Taken from ZBI)	
Power / Engine displacement	147 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic transmission / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Brillant Silber Metallic
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Anthracite-Black
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	4,600 km
Key is / should be	3 / 3	FZG documents	ZB#1 (S) was available (copy), ZB#2 (B) was not available
		Letter No.	GJ945896
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8004 / AVI 00076		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	Fine dust sticker	
Permitted total weight	2,042 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R19 93Y	Summer tyres on Light alloy	Bridgestone	6mm / 6mm
2)	225/40 R19 93Y	Summer tyres on Light alloy	Bridgestone	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Light alloy	Continental	6mm / 6mm
2)	205/60 R16 96H	Winter tyres on Light alloy	Continental	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	125/70 R18 99M	All-season tyres on Steel	Sonstige	7 mm

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel

Equipment

Standard equipment

- Storage compartment in the luggage compartment with cargo element
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Ambient lighting
- Anti-lock braking system (ABS)
- Dashboard center section with microfiber cover in black and red decorative stitching
- Exterior mirrors with memory function
- Heated windscreen washer nozzles including 5l washer fluid reservoir
- Glasses compartment on the roof lining
- Roof rails, black
- diesel particulate filter
- tachometer
- Electronic parking brake
- Electronic Stabilization Control (ESC)
- Driving profile selection
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Luggage net partition
- Transmission: 7-speed direct shift gearbox (DSG)
- Green tec: Automatic start/stop system including brake energy recovery
- Rear spoiler
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- Removable trunk cover
- LED fog lights
- LED license plate lighting
- LED headlights with LED daytime running lights
- Remote release of the rear seat backrests in the trunk
- Steering wheel: height and length adjustable
- Steering wheel: Leather steering wheel with multifunction buttons with shift paddles
- Engine drag torque control (MSR)
- Package: Comfort Plus (Combi RS, Sportline)
- Package: Travel Plus (DSG)
- Pedals in stainless steel look
- Radio accessories: 2 USB-C ports at the front
- Radio accessories: Bluetooth hands-free system
- Radio accessories: SmartLink
- Rain sensor
- Wheels: 19" Altair alloy wheels, anthracite, high-sheen (7.5J x 19, ET 48 with 225/40 R19 tires)
- Seats: Heated rear seats
- Seats: Electrically adjustable Ergo sports seats in the front
- Shelves
- Airbag, driver and passenger
- Airbag, head airbags
- Airbag: Center airbag front
- Trailer coupling preparation including trailer stabilization
- Traction control (ASR)
- Automatically dimming exterior mirror (driver's side)
- Exterior mirrors electrically adjustable and heated
- Exterior mirrors, electrically folding
- hill start assist including auto-hold function
- Hydraulic brake assist (HBA)
- Black headliner
- Dark Carbon decorative strip
- Digital instrument cluster (Virtual Cockpit) 10.2"
- Third brake light
- Electronic transverse differential lock (XDS+)
- Driving light assistant
- Chassis: Sports suspension
- Front radar assistant including city emergency braking function and person and cyclist detection
- Cruise control system
- Tinted windows
- Heated rear window
- Rear window wiper including windscreen washer system
- Interior mirror automatically dimming
- Kessy, keyless entry and start-stop system
- Electronic child lock
- Comfort opening with electric tailgate operation (Combi)
- LED taillights in crystal glass look and animated indicators
- LED matrix headlights and dynamic high beam assistant (AFS)
- Steering wheel: Heated steering wheel in sports design with shift paddles
- Rear center armrest with through-loading option
- Front center armrest, including storage compartment
- Package: Infotainment Columbus Plus
- Package: Parking & Lighting
- Parking sensors front and rear
- Progressive steering
- Radio accessories: 8 speakers
- Radio accessories: Digital radio reception DAB+
- Radio accessories: voice control
- Tire pressure monitoring
- Seat belts
- Safety lights in the front side doors
- Seats: Heated front seats
- Seats: Height-adjustable driver and passenger seats



- Seats: Rear seat backrest 60:40 split folding
- SKODA Care Connect
- Speed limiter
- Lane change and rear traffic assistant as well as exit warning
- Sunset (rear window and rear side windows dark tinted)
- Phone: Wireless SmartLink for Apple CarPlay
- Textile floor mats
- Glazing: Acoustic glazing in the front side windows and Sunset
- Central locking including radio remote control integrated in the key and EASY Start

Extra equipment

- Paint finish: metallic
- Package: Simply Clever PKC
- Radio accessories: CANTON sound system and 18" steel spare wheel (12 speakers (10 speakers, 1 central speaker, 1 subwoofer in the spare wheel well) - 18" steel spare wheel (125/70 R18 tires) including jack and wheel wrench)

- Seats: Sports seats with integrated headrests in the front and height-adjustable headrests in the rear
- Lane keeping assistant (Lane Assist)
- 12-V socket in the trunk
- 230 V socket and USB charging port
- Telephone: Phonebox with inductive charging function (connection via the external antenna)
- Front door sills
- Lashing eyes in the trunk
- Immobiliser

Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate Part 1 (certificate) was available, but the registration certificate Part 2 (letter) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was verified during the inspection by the undersigned.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and a pit were available for examining the vehicle.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Bonnet	Bonnet - dent(s) - Smooth repair work
2	Side panel - rear left side	Wheel arch - dent(s) - Smooth repair work
3	Side panel - rear right side	Sill - Dent / paintcoat damage - Smart repair
4	Wheel / tyres	Alloy rim - front right side - Damaged - Loss in value
5	Wheel / tyres	Alloy rim - rear right side - Damaged - Loss in value
6	Front bumper	Front bumper - Scratch(es) - Smart repair
7	Rear bumper	Rear bumper (Incl. Schwarzer Zierleiste) - Damaged - Smart repair

Wear and tear

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction

The vehicle shows signs of wear commensurate with its age and use.



Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 16 Jan 2024	4.701,23 €
2	Rear, Provided by user / customer, from 19 Jan 2024	6.691,37 €

Repainting

No. Repainting

- | | |
|---|---|
| 1 | Roof rail - right side, Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent |
|---|---|

Paint coat thickness measurement

Roof rail - right side	184 µm	Side panel - rear right side	624 µm
------------------------	--------	------------------------------	--------

Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
(Functional tests of driver assistance systems are not included in the scope of services!)
- a photo documentation of the vehicle

Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Comments

- Das Fahrzeug befand sich zum Besichtigungszeitpunkt in beschädigten, nicht demontierten Zustand. Schadenausweitung möglich, Zusatzkosten können entstehen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.




Figure 19: Misc.



Damage 1: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 2: Side panel - rear left side: Wheel arch - dent(s) - Smooth repair work



Damage 2: Side panel - rear left side: Wheel arch - dent(s) - Smooth repair work



Damage 3: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 4: Wheel / tyres: Alloy rim - front right side - Damaged - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front right side - Damaged - Loss in value



Damage 5: Wheel / tyres: Alloy rim - rear right side - Damaged - Loss in value



Damage 5: Wheel / tyres: Alloy rim - rear right side - Damaged - Loss in value



Damage 5: Wheel / tyres: Alloy rim - rear right side - Damaged - Loss in value



Damage 6: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 6: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 7: Rear bumper: Rear bumper (Incl. Schwarzer Zierleiste) - Damaged - Smart repair



Damage 7: Rear bumper: Rear bumper (Incl. Schwarzer Zierleiste) - Damaged - Smart repair



Damage 7: Rear bumper: Rear bumper (Incl. Schwarzer Zierleiste) - Damaged - Smart repair



Damage 7: Rear bumper: Rear bumper (Incl. Schwarzer Zierleiste) - Damaged - Smart repair



Damage 7: Rear bumper: Rear bumper (Incl. Schwarzer Zierleiste) - Damaged - Smart repair



Roof rail - right side: 184 µm



Roof rail - right side: 184 µm



Side panel - rear right side: 624 µm



Side panel - rear right side: 624 µm