

VIN	TMBJK0NX7 MY111432	Brand	SKODA	Maintenance date -	
Licence Plate	W77949E	Model	OCTAVIA Combi 2,0 TDI RS DSG 147KW	Maintenance mileage	-
Registration date	19/02/2021	Year	1000	Exterior Color	Red Metallic
Odometer	73 459 km	Engine size	1968	interior Color	Black
Fuel	Diesel	Body Type	Estate	Next technical inspection	01/02/2026
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection date	04/03/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------

Inspection date	04/03/2025
-----------------	------------

Inspection loc.	Hödlmayr Logistics GmbH
-----------------	-------------------------




Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Panoramic roof	✓
Xenon projectors	✓
Anti-fog lights	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓

100

User manual	
Log books	
Spare key	
Remote key	

Pirelli 225/45/18 V Winter 7.9 mm		Pirelli 225/45/18 V Winter 7.8 mm	
Pirelli 225/45/18 V Winter 8.4 mm		Pirelli 225/45/18 V Winter 8.3 mm	

Exterior

1		Part Windscreen Position - Damages Stone impact Severity Diameter (mm) > 10 Repair mode Replace	2		Part Bonnet Position - Damages Stone impact Severity - Repair mode For info
3		Part Bumper Position Front Damages Scratched Severity - Repair mode For info	4		Part Spoiler Position Front Damages Scratched Severity - Repair mode For info
5		Part Alloy wheel 18" Position Front left Damages Scratched Severity Length (cm) > 10 Repair mode Smart Repair	6		Part Door Position Front left Damages Scratched Severity - Repair mode Repair
7		Part Door Position Back left Damages Scratched Severity - Repair mode Repair	8		Part Door sill Position Back left Damages Dented Severity - Repair mode Repair
10		Part Bumper Position Back Damages Scratched Severity - Repair mode Repair	11		Part Alloy wheel 18" Position Back right Damages Scratched Severity Length (cm) > 10 Repair mode Smart Repair
12		Part Wing Position Back right Damages Dented Severity - Repair mode Repair	13		Part Door Position Front right Damages Scratched Severity - Repair mode For info
15		Part Alloy wheel 18" Position Front right Damages Scratched Severity Length (cm) > 10 Repair mode Smart Repair	16		Part Roof Position - Damages Stone impact Severity - Repair mode For info

Interior damage

9



● ● ●

Part	Seat back upholstery mixed
Position	Front left
Damages	Cut
Severity	-
Repair mode	Replace

14



● ●

Part	Interior cleaning
Position	-
Damages	Not carried out
Severity	-
Repair mode	Lumpsum

Others

17



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint

18



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks