



## status report

**customer:** BCA Autoauktionen GmbH  
**contract number:**  
**reference:**

### vehicle data

#### Skoda Octavia Combi Ambition

Vehicle identification number	<b>TMBJP7NXXMY039541</b>	mileage read:	<b>96218 km</b>
First Registration / construction year:	<b>19.04.2021 / 2020</b>	Visit Date / place of birth:	<b>18.09.2025 Riedstadt-Goddelau</b>
Bodywork:	<b>cars</b>	Re - import:	<b>no</b>
Body type:	<b>station wagon</b>	KBA no. :	<b>8004//AVO</b>
Fuel / emission class:	<b>gasoline / € 6</b>	transmission type:	<b>automatic</b>
Displacement / power:	<b>999 ccm / 81 kW (110 PS)</b>	Engine:	<b>front-wheel drive</b>
paint:	<b>Quarz-Grau Metallic</b>	Number of previous owners:	<b>2</b>
Doors / seats:	<b>5 / 5</b>	number keys:	<b>2</b>
Next HU / AU:	<b>- / -</b>	cushion type:	<b>substance</b>
Service book available:	<b>digital</b>	Interior Color:	<b>black</b>
smoking vehicle:	<b>no</b>	Last service km / on the:	<b>19375 / 06.05.2022</b>
Vehicle roadworthy:	<b>yes</b>	Vehicle roadworthy:	<b>yes</b>
Submitted vehicle	<b>-</b>	state outside:	<b>3 - Average</b>
documents:		condition inside:	<b>3 - Average</b>
visit condition:	<b>-</b>		
state general:	<b>3 - Average</b>		

### Accessories (presented to the visiting time )

<b>GPS sat nav disk:</b>	<b>Fzg.Schlüssel:</b>	<b>Service book provided /</b>	<b>Last service at / on:</b>
SD Card	2	<b>maintained:</b>	19375 / 06.05.2022
		digital / -	

<input checked="" type="checkbox"/> AHK key	<input checked="" type="checkbox"/> AHK removable	<input checked="" type="checkbox"/> AHK fixed	<input checked="" type="checkbox"/> AHK swivel
<input checked="" type="checkbox"/> Fernbed . entertainment	<input checked="" type="checkbox"/> Fernbed . Auxiliary heating	<input checked="" type="checkbox"/> headphone	<input checked="" type="checkbox"/> LED headlights
<input checked="" type="checkbox"/> Load compartment cover	<input checked="" type="checkbox"/> navigation system	<input checked="" type="checkbox"/> Persenning	<input checked="" type="checkbox"/> partition net
<input checked="" type="checkbox"/> Wind Deflector	<input checked="" type="checkbox"/> Xenon headlights		

☒ **available**      ☒ **not available**

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®  
**Die Gutachter**



mounted tires		
Tyre / wheel type:	<b>All season tires</b>	<b>aluminum</b>
1st axis - Left / states .	<b>Sava</b>	<b>205/60/R16/96H 5 mm</b>
1st axis - right / states .	<b>Sava</b>	<b>205/60/R16/96H 5 mm</b>
2nd axis - Left / states .	<b>Sava</b>	<b>205/60/R16/96H 5 mm</b>
2nd axis - right / states .	<b>Sava</b>	<b>205/60/R16/96H 5 mm</b>
traffic Safety:	<b>roadworthy</b>	
spare wheel:	<b>vorhanden</b>	
state spare wheel:	<b>Vollwertig</b>	

standard equipment	
<ul style="list-style-type: none"> <li>•</li> <li>• Output Stacker Cargo Organizer right ( luggage / cargo area )</li> <li>• Airbag switched off</li> <li>• Anti- lock braking system ( ABS)</li> <li>• Swing audio system with touchscreen</li> <li>• Power side mirrors . adjustable and heated</li> <li>• board computer</li> <li>• Brake Energy Regeneration</li> <li>• Roof sky gray</li> <li>• Double-tone fanfare</li> <li>• Electron. Stability Program (ESP )</li> <li>• Driver assistance system Evasive Assistant</li> <li>• Driving Assistance System Multi Collision Brake</li> <li>• Electric windows front + rear</li> <li>• Front camera</li> <li>• Speed control system (cruise control) incl. Speed limiter system</li> <li>• Taillights LED</li> <li>• Interior Inlays Silver</li> <li>• Isofix admissions for child seat in the passenger seat</li> <li>• Body 5-door</li> <li>• Child safety electr. actuated</li> <li>• Knee airbag , driver's side</li> <li>• Lumbar support front left seat</li> <li>• Steering wheel (leather) with multifunction</li> <li>• Light and rain sensor</li> <li>• LM rims</li> <li>• Rear center armrest</li> <li>•</li> </ul>	<ul style="list-style-type: none"> <li>• Storage compartment for umbrella</li> <li>• Storage bag on front seat backrests</li> <li>• Airbag Driver / passenger side</li> <li>• Acceleration skid control ( ASR)</li> <li>• Power side mirrors . anklappbar</li> <li>• Exterior mirrors and door handles in body color</li> <li>• brake Assist</li> <li>• goggle pocket</li> <li>• roof rails</li> <li>• Electron. Transverse differential lock ( XDS )</li> <li>• Driving Assistance System Collision Warning with City Emergency Braking ( Front Radar Assistant )</li> <li>• Driving Assistance System Hill Start Assist ( Hill Holder )</li> <li>• Driver assistance system Lane Assist</li> <li>• Hands-free phone with Bluetooth</li> <li>• Luggage compartment cover / shade</li> <li>• Transmission 7 - speed dual - clutch gearbox DSG</li> <li>• rear window wiper</li> <li>• Rearview mirror with auto dip</li> <li>• Isofix admissions for child seat in back seat</li> <li>• License plate light LED</li> <li>• Climatronic air conditioning 2-zone</li> <li>• Head airbag system</li> <li>• Lumbar support front right seat</li> <li>• Steering column (steering wheel ) adjustable (vertical / axial)</li> <li>• Beam Assist ( Coming Home , Leaving Home )</li> <li>• Mild-Hybrid 81 kW (Motor 1,0 Ltr. - 81 kW TSI e-TEC)</li> <li>• Front center armrest</li> </ul>

<ul style="list-style-type: none"> <li>• Otto Particle Filter (OPF)</li> <li>• Radio reception digital (DAB +)</li> <li>• Rear seat backrest split / folding</li> <li>• Heated windshield washer nozzles</li> <li>• Front Side Airbags</li> <li>• power steering</li> <li>• Front right seat height adjustment</li> <li>• SmartLink ( Mirror Link , Apple and Android carplay car )</li> <li>• Socket (12V ) port in the trunk / cargo area</li> <li>• USB interface at the front (2-way, type C)</li> <li>• Lashing luggage / cargo area</li> <li>• Warning system for seat belts , driver / passenger side</li> <li>• Wireless SmartLink (Apple CarPlay)</li> </ul>	<ul style="list-style-type: none"> <li>• emergency call system</li> <li>• Parking brake electronically</li> <li>• Tire Pressure Monitoring System</li> <li>• Low-pollutant according to the Euro 6d emissions standard</li> <li>• LED headlights</li> <li>• Service-System Remote Services</li> <li>• Front left seat height adjustment</li> <li>• Seat relation / upholstery fabric Ambition Black</li> <li>• Start / Stop system</li> <li>• LED daytime running lights</li> <li>• tinted glazing</li> <li>• Rear seat belt warning system</li> <li>• immobilizer</li> <li>• Central locking / starting system Kessy-Go</li> </ul>
---	---

special Features	
<ul style="list-style-type: none"> <li>• Anti-theft alarm system with interior monitoring and tow-away protection</li> <li>• Heated front window</li> <li>• Spare wheel in driving tires</li> </ul>	<ul style="list-style-type: none"> <li>• Park distance control front and rear</li> <li>• Metallic paint</li> <li>• Rear side windows and rear windscreen blackened ( SunSet )</li> </ul>

We remind you that the data provided were taken from the DAT database.\n\nNo liability can be assumed for the completeness and correctness.

General examination	
<b>Subfloor Inspection:</b>	<b>not possible</b> A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
<b>Mileage plausible:</b>	<b>not testable</b> not testable Wartung Fällig
<b>reference:</b>	
<b>Note Road Safe:</b>	

Farbabweichung Plastikteile

Accident injury assessment	
<b>Rep. Predamages / -height gross:</b>	<b>Expertly repaired</b> On a vehicle coating thickness measurement on the body outer skin were noted

repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.

**Layers of paint thickness  
measurement:**

**Out of tolerance**











At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

**Existing collision damage:**

**Not established**

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

**reference:**

Overview conducted technology audit					
<b>Alternator / Generator:</b>			examined limited	<b>Battery / accumulator:</b>	
			in order		
<b>oil loss:</b>			examined limited		
<b>air conditioning:</b>			examined limited	<b>lighting system:</b>	
			examined limited		
<b>coupling:</b>			unavailable	<b>exhaust System:</b>	
			examined limited		
<b>engine running:</b>			examined limited	<b>shock absorber:</b>	
			examined limited		
<b>transmission:</b>			examined limited		

Performed testing technology	
<b>Alternator / Generator:</b>	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
<b>Battery / accumulator:</b>	The battery (accumulator) was examined during the inspection .
<b>oil loss:</b>	The vehicle could be checked only limited to oil leaks .
<b>air conditioning:</b>	The air conditioning system could be tested only restricted during the visit .
<b>lighting system:</b>	The Lichtanlage could be considered limited to the tour date .
<b>coupling:</b>	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
<b>exhaust System:</b>	The exhaust system has been tested only restricted during the visit .
<b>engine running:</b>	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
<b>shock absorber:</b>	The shock absorber could be tested only restricted during the visit .
<b>transmission:</b>	The transmission could be examined in the context of limited test drive / pull test .
<b>reference:</b>	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. hood	Subsequently painted	acceptable
2. A-pillar Front - Left	Subsequently painted	acceptable
3. Roof frame - left	Subsequently painted	acceptable
4. Sidewall - Rear - Left	Subsequently painted	acceptable
5. maintenance	Due	Replace
6. Cargo cover	Missing	Replace
7. hood	Deformed	Refurbish and paint
8. Front door - left	Scratch(es)	Smart repair
9. Sitzreihe Hinten	Dirty	
10. Sidewall - Rear - Left	Deformed	Refurbish and paint
11. tailgate	Damaged	Refurbish and paint
12. Door Rear - right	Damaged	Refurbish and paint
13. Türeinstieg Hinten - Rechts	Scratch(es)	Paint
14. Front fender - right	Scratch(es)	
15. Mittelkonsole	Dirty	

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable ( small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims




rims



engine compartment



service book



Others



1. hood



2. A-pillar Front - Left



3. Roof frame - left



4. Sidewall - Rear - Left



7. hood



7. hood



8. Front door - left



9. Sitzreihe Hinten



9. Sitzreihe Hinten



10. Sidewall - Rear - Left



10. Sidewall - Rear - Left



10. Sidewall - Rear - Left



11. tailgate



11. tailgate



12. Door Rear - right



12. Door Rear - right



13. Türeinstieg Hinten - Rechts



14. Front fender - right



15. Mittelkonsole



15. Mittelkonsole



15. Mittelkonsole