



SKODA Octavia Octavia 1.6 Combi

VIN NO TMBJX21U898852852
Registration Number U898852852



MOT Date

2026-11-01

Last Service



Number of Owners

2

Last Service Mileage



Number of Keys

1

First Registration Date

2009-05-28

Odometer Reading

117824 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250925115034
Inspection Date / Place	2025-09-25 / BCA Oberndorf	Cosmetic Grade	4


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1595
Engine Size	1.6	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	173
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Remote adjusting wing mirrors	Split folding rear seats	Central locking
Anti-lock braking	Roof rails	CD Player	Radio

Equipment Details


Air Conditioning	No	Seat Heating	No
------------------	----	--------------	----

Wheels & Tyres


Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage

11 Schäden




3 Schäden



Component		Damage	Comments
1	Hood	Bodywork / Dent / Dent	
2	Bumper / Front	Paint / Scratch / Scuff	
3	Roof	Bodywork / Dent / Dent	
4	Bumper / Front	Paint / Stone Chip	
5	Fender / Front Left	Paint / Scratch / Line	
6	Steering Wheel / Front	Interior / Scratched	
7	Seat / Front Left	Interior / Dirty	
8	Fender / Back Left	Bodywork / Dent / Dent	
9	Bumper / Back	Bodywork / Dent / Dent	
10	Fender / Back Right	Bodywork / Dent / Dent	
11	Door / Back Right	Paint / Scratch / Line	
12	Door / Front Right	Bodywork / Dent / Dent	


13	Mirror / Front Right	Paint / Scratch / Scuff
14	Aeration Grid / Front Center	Interior / Not Working



1. Hood
Bodywork / Dent / Dent -




2. Bumper / Front
Paint / Scratch / Scuff -



3. Roof
Bodywork / Dent / Dent -



4. Bumper / Front
Paint / Stone Chip -



5. Fender / Front Left
Paint / Scratch / Line -



6. Steering Wheel / Front
Interior / Scratched -



7. Seat / Front Left
Interior / Dirty -



8. Fender / Back Left
Bodywork / Dent / Dent -



9. Bumper / Back
Bodywork / Dent / Dent -



10. Fender / Back Right
Bodywork / Dent / Dent -



11. Door / Back Right
Paint / Scratch / Line -



12. Door / Front Right
Bodywork / Dent / Dent -



13. Mirror / Front Right
Paint / Scratch / Scuff -



14. Aeration Grid / Front Center
Interior / Not Working -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓		

Equipments Test

Central Locking	❗	Audio Equipment	✓
Other Equipments	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	❗
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Clutch

Clutch Functioning

Brake

Brake System Anomaly

General

Test Driven Status Not Performed

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)