



status report

customer:	BCA Autoauktionen GmbH
reference:	

vehicle data			
Å koda Kodiaq			
Vehicle identification number	TMBLK9NSXK8016216	mileage read:	107996 km
First Registration / construction year:	19.11.2018 / 0	Visit Date / place of birth:	16.05.2025 Hoppegarten
Bodywork:	cars	Re - import:	no
Body type:	station wagon	KBA no. :	8004//ARX
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1968 ccm / 140 kW (190 PS)	Engine:	four-wheel
paint:	blue	Number of previous owners:	3
Doors / seats:	5 / 5	number keys:	3
Next HU / AU:	01.2027 / 01.2027	cushion type:	Leather / Alcantara
Service book available:	-	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	For example, I \u0026 II For example,	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	3	- / -	- / -
<input checked="" type="checkbox"/> AHK key	<input checked="" type="checkbox"/> AHK removable	<input checked="" type="checkbox"/> AHK fixed	<input checked="" type="checkbox"/> AHK swivel
<input checked="" type="checkbox"/> Fernbed . entertainment	<input checked="" type="checkbox"/> Fernbed . Auxiliary heating	<input checked="" type="checkbox"/> headphone	<input checked="" type="checkbox"/> LED headlights
<input checked="" type="checkbox"/> Load compartment cover	<input checked="" type="checkbox"/> navigation system	<input checked="" type="checkbox"/> Persenning	<input checked="" type="checkbox"/> partition net
<input checked="" type="checkbox"/> Wind Deflector	<input checked="" type="checkbox"/> Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	All season tires	aluminum
1st axis - Left / states .	Continental	235/50/R19/103W 6 mm
1st axis - right / states .	Continental	235/50/R19/103W 6 mm
2nd axis - Left / states .	Continental	235/50/R19/103W 6 mm
2nd axis - right / states .	Continental	235/50/R19/103W 6 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

Unmounted tires		
Tyre / wheel type:	summer tires	without rim
1st axis - Left / states .	-	235/50/R19/103W 5 mm
1st axis - right / states .	-	235/50/R19/103W 5 mm
2nd axis - Left / states .	-	235/50/R19/103W 5 mm
2nd axis - right / states .	-	235/50/R19/103W 5 mm
traffic Safety:	roadworthy	

standard equipment

special Features

standard equipment	
<ul style="list-style-type: none"> • ABS • Power side mirrors . • Power windows • Climate Control • Fog Lights • panoramic roof • cruise control 	<ul style="list-style-type: none"> • four-wheel • board computer • air Conditioning • Multifunction steering wheel • PDC / H • power steering • central locking

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	

Note Road Safe:

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit

Alternator / Generator:	✓ in order	Battery / accumulator:	✓ in order
oil loss:	✓ in order		
air conditioning:	✓ in order	lighting system:	✓ in order
coupling:	✗ unavailable	exhaust System:	✓ in order
engine running:	✓ in order	shock absorber:	✓ examined limited
transmission:	✓ examined limited		

Performed testing technology

Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle was inspected during the visit to an oil leak .
air conditioning:	A function of the air conditioning was found to visiting time .
lighting system:	The lighting system was to tour date in order.
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested and apparently acoustically during the tour .
engine running:	A field test of the engine was performed.
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*

damage



component	Damage	Rep kind
1. Rear door - left	Subsequently painted	acceptable
2. Front door - left	Subsequently painted	acceptable
3. Felge vorne links	Scratch(es)	Refurbish and paint
4. Felge vorne rechts	Scratch(es)	Refurbish and paint
5. Tür hinten links Kantenschutz abgebrochen	Breakage	Replace
6. maintenance	Missing	Replace
7. proof of maintenance	Missing	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside




inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims




engine compartment



service book



Others



Navigation system



1. Rear door - left



2. Front door - left



3. Felge vorne links



3. Felge vorne links



4. Felge vorne rechts



4. Felge vorne rechts



5. Tür hinten links Kantenschutz abgebrochen



5. Tür hinten links Kantenschutz abgebrochen