



status report

customer:	Bank 11, Neuss
contract number:	1145161030
reference:	

vehicle data			
Skoda Kodiaq Style 4x4			
Vehicle identification number	TMBLN7NS9P8524020	mileage read:	76904 km
∴			
First Registration / construction year:	18.01.2024 / 2022	Visit Date / place of birth:	05.06.2025 Dorfmark
Bodywork:	SUV	Re - import:	no
Body type:	Road /	KBA no. :	8004//AVW
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1968 ccm / 147 kW (200 PS)	Engine:	four-wheel
paint:	white	Number of previous owners:	1
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	Imitation leather / fabric
Service book available:	digital	Interior Color:	Multicolor
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle	Eg II (veh - letter)	state outside:	4 - moderate
documents:			
visit condition:	-	condition inside:	4 - moderate
state general:	4 - moderate		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	2	maintained:	- / -
		digital / -	
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	polished aluminum
1st axis - Left / states .	Hankook	235/50/R19/99V 3 mm
1st axis - right / states .	Hankook	235/50/R19/99V 3 mm
2nd axis - Left / states .	Hankook	235/50/R19/99V 5 mm
2nd axis - right / states .	Hankook	235/50/R19/99V 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• 3rd brake light • Storage bag on front seat backrests • Airbag switched off • Anti- lock braking system (ABS) • Drive all-wheel drive • Power side mirrors . adjustable and heated, both • brake Assist • goggle pocket • Durchladeeinrichtung (rear center armrest) • Electron. Transverse differential lock (XDS) • Driving Assistance System Collision Warning with City Emergency Braking (Front Radar Assistant) • Driving Assistance System for automatic start driving lights (headlight assistant) • Electric windows front + rear • Load compartment cover • Belt tensioner rear • rear window wiper • Isofix admissions for child seat in back seat • Knee airbag , driver's side • Head airbag system • Front head restraints • Lumbar support front left seat • Steering wheel (leather - 2 spokes) with multifunction • Steering column (steering wheel) longitudinally adjustable • Front center armrest • Engine 2.0 Ltr. - 147 kW TDI • Fog Lights • Phonebox	• • Airbag passenger side • Airbag driver side • Acceleration skid control (ASR) • Power side mirrors . folding , all mirror with auto dip <i>Innenspiegel mit Abblendautomatik</i> • Body color door mirrors • Brake Energy Regeneration • Anodized roof rails <i>Chromzierleisten an Seitenfenstern</i> • Park distance control front and rear • Electron. Stability Program (ESP) • Driving Assistance System Hill Start Assist (Hill Holder) • Driving Assistance System Multi Collision Brake • Control for central locking • Transmission 7 - speed dual - clutch gearbox DSG • Taillights LED (crystal glass optics) <i>Kennzeichenbeleuchtung LED</i> • Interior decorative inlays Linear Diamonds • Body 5-door • Comfort Handsfree Bluetooth without voice control • Rear headrests • Backrest of the rear seat back in the trunk • Lumbar support front right seat • Steering column (steering wheel) adjustable in height • Matrix LED headlights <i>Fahrassistenz-System: Fernlichtassistent</i> • model refinement • Multi-function display

• Wheelbase 2791 mm • Rußpartikelfilter • Low-pollutant according to the Euro 6d emissions standard • Heated windshield washer nozzles • Windscreen wipers with rain sensor • Closing / starting system KESSY • Power steering electronically (Servotronic) • Front right seat height adjustment • Electric front seats . adjustable (with memory) • SmartLink (Mirror Link , Apple and Android carplay car) • Sun visor with mirror right • Start / Stop system • Socket (12V connection) in front center console • LED daytime running lights • tinted glazing • Warning system for seat belts , driver / passenger side • Wireless SmartLink (Apple CarPlay)	• emergency call system • Radio reception digital (DAB +) • Tire Pressure Monitoring System • Rear seat folding 1 / 3-2 / 3 • Gearshift / selector lever leather • Aero windscreen wipers , front • Headlight cleaning system (SRA) • Front Side Airbags • Front left seat height adjustment • • Heated front seats • Sun visor with mirror left • • Socket (12V) port in the trunk / cargo area • Body color bumpers • Exterior door handles body color • Lashing luggage / cargo area • immobilizer • Central
---	---

special Features	
• Ambient lighting LED • Driver assistance package Traveler Plus <i>Fahrassistenz-System: Verkehrszeichenerkennung, Fahrassistenz-System: Parklenkassistent, Fahrassistenz-System: Autom. Distanzregelung (ACC) mit Frontradar-Assistent (bis 210 km/h), Fahrassistenz-System: aktiver Spurhalteassistent (Lenkunterstützung)</i> • Luggage compartment partition (net) • Folding tables integrated in driver and front passenger seat back • Instrument cluster digital (virtual cockpit) • LM-Felgen 7x19 (Triglav) • Pearl effect paint • backup camera	• • Driving Assistance System fatigue detection sensor • Infotainment package Amundsen <i>Audio-Navigationssystem Amundsen</i> • Climatronic air conditioning 3-zone • Comfort opening for elec. Tailgate / lids • Variable load floor • Tire repair kit • Rear side windows and rear windscreen blackened (SunSet)

We remind you that the data provided were taken from the DAT database.\r\nNo liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible

	A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Kombiinstrument Fehlermeldung

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	found At the unrepaired vehicle accident damage were observed on visual examination on the body skin .
reference:	Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine Demontagearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			examined limited		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen Kombiinstrument Fehlermeldung Fehlerdiagnose durchführen lassen Unfallschaden Stoßfänger vorne rechts Schaden und Kosten Erweiterung möglich

damage



component	Damage	Rep kind
1. maintenance	Due	Replace
2. proof of maintenance	Missing	Replace
3. instrument cluster	Error message	Carry out a fault diagnosis
4. Rear bumper	Scrape	Replace
5. Rear door - left	Damaged	Refurbish and paint
6. roof	Dented	Smart repair
7. Front bumper	Accident damage	Replace
8. Rim front - right	Damaged	Replace
9. Türgriff VR	Scrape	Smart repair
10. exterior body	Surface scratch(es)	
11.	Wear and tear	acceptable
12.	Dirty (animal hair)	
13.	Odour	Ozone treatment
14.	Damaged	Replace
15. Cargo cover	Missing	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims




rims



engine compartment



service book



Others



Navigation system



3. instrument cluster



3. instrument cluster



4. Rear bumper



4. Rear bumper



4. Rear bumper



5. Rear door - left



5. Rear door - left




5. Rear door - left



6. roof



6. roof



6. roof



6. roof



7. Front bumper



7. Front bumper



7. Front bumper



7. Front bumper



7. Front bumper



7. Front bumper



7. Front bumper



7. Front bumper



7. Front bumper



7. Front bumper



8. Rim front - right



8. Rim front - right



9. Türgriff VR



9. Türgriff VR



10. exterior body



11.



11.



12.



12.



12.



12.



12.



12.



14.



14.



15. Cargo cover