



Hüsges Gruppe®
Die Gutachter

status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

Suzuki Vitara

| | | | |
|--|----------------------------------|------------------------------|---|
| Vehicle identification number | TSMLYED1S00C74873 | mileage read: | 17685 km |
| .. | | | |
| First Registration / construction year: | 21.03.2024 / 2022 | Visit Date / place of birth: | 18.09.2025 Riedstadt- Goddelau |
| Bodywork: | SUV | Re - import: | unknown |
| Body type: | Road / | KBA no. : | 8306//ACR |
| Fuel / emission class: | gasoline / - | transmission type: | manual transmission |
| Displacement / power: | 1373 ccm / 95 kW (129 PS) | Engine: | four-wheel |
| paint: | beige | Number of previous owners: | 2 |
| Doors / seats: | 5 / 5 | number keys: | 2 |
| Next HU / AU: | - / - | cushion type: | Leather / Alcantara |
| Service book available: | yes | Interior Color: | black |
| smoking vehicle: | yes | Last service km / on the: | 7876 / 21.03.2025 |
| Vehicle roadworthy: | yes | Vehicle roadworthy: | yes |
| Submitted vehicle | - | state outside: | 3 - Average |
| documents: | | | |
| visit condition: | - | condition inside: | 3 - Average |
| state general: | 3 - Average | | |

Accessories (presented to the visiting time)

| | | | |
|--------------------------|-----------------------|--------------------------------|------------------------------|
| GPS sat nav disk: | Fzg.Schlüssel: | Service book provided / | Last service at / on: |
| - | 2 | maintained: | 7876 / 21.03.2025 |
| | | yes / - | |

| | | | |
|---|--|--|--|
| <input checked="" type="checkbox"/> AHK key | <input checked="" type="checkbox"/> AHK removable | <input checked="" type="checkbox"/> AHK fixed | <input checked="" type="checkbox"/> AHK swivel |
| <input checked="" type="checkbox"/> Fernbed . entertainment | <input checked="" type="checkbox"/> Fernbed . Auxiliary heating | <input checked="" type="checkbox"/> headphone | <input checked="" type="checkbox"/> LED headlights |
| <input checked="" type="checkbox"/> Load compartment cover | <input checked="" type="checkbox"/> navigation system | <input checked="" type="checkbox"/> Persenning | <input checked="" type="checkbox"/> partition net |
| <input checked="" type="checkbox"/> Wind Deflector | <input checked="" type="checkbox"/> Xenon headlights | | |

☒ **available**

☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

| | | |
|-----------------------------|---------------------|----------------------------|
| Tyre / wheel type: | Winter tires | steel |
| 1st axis - Left / states . | Falken | 215/55/R17/98V 5 mm |
| 1st axis - right / states . | Falken | 215/55/R17/98V 5 mm |
| 2nd axis - Left / states . | Falken | 215/55/R17/98V 5 mm |
| 2nd axis - right / states . | Falken | 215/55/R17/98V 5 mm |
| traffic Safety: | roadworthy | |
| spare wheel: | Tirefit | |
| state spare wheel: | Vollwertig | |

special Features

standard equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • ABS • board computer • Power windows • Climate Control • Mult-function Comfort seat front right • Multimedia modules • side airbags • Heated seats | <ul style="list-style-type: none"> • four-wheel • ESP • Driver and passenger airbags • Mult-function Comfort seat front left • Multifunction steering wheel • PDC / H • power steering • central locking |
|---|--|

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

| | |
|-----------------------------|---|
| Subfloor Inspection: | not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available . |
| Mileage plausible: | yes yes |
| reference: | |
| Note Road Safe: | |

Farbabweichung Plastikteile

Accident injury assessment

| | |
|---|--|
| Rep. Predamages / -height gross: | no detectable As part of a paint film thickness measuring the body outer skin no previous damage |
|---|--|

**Layers of paint thickness
measurement:**

could be detected .

Within the tolerances











At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

| Overview conducted technology audit | | | | | |
|-------------------------------------|--|---|------------------|-------------------------------|--|
| Alternator / Generator: | |  | examined limited | Battery / accumulator: | |
| | |  | in order | | |
| oil loss: | |  | examined limited | | |
| air conditioning: | |  | examined limited | lighting system: | |
| | |  | examined limited | | |
| coupling: | |  | examined limited | exhaust System: | |
| | |  | examined limited | | |
| engine running: | |  | examined limited | shock absorber: | |
| | |  | examined limited | | |
| transmission: | |  | examined limited | | |

| Performed testing technology | |
|--------------------------------|--|
| Alternator / Generator: | The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster . |
| Battery / accumulator: | The battery (accumulator) was examined during the inspection . |
| oil loss: | The vehicle could be checked only limited to oil leaks . |
| air conditioning: | The air conditioning system could be tested only restricted during the visit . |
| lighting system: | The Lichtenlange could be considered limited to the tour date . |
| coupling: | The clutch could be tested only limited within the test drive / pull test . |
| exhaust System: | The exhaust system has been tested only restricted during the visit . |
| engine running: | Checking the engine running was limited. Here no audible or visual abnormalities were noted . |
| shock absorber: | The shock absorber could be tested only restricted during the visit . |
| transmission: | The transmission could be examined in the context of limited test drive / pull test . |
| reference: | *Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen. |

damage



| component | Damage | Rep kind |
|---------------------|---------|--------------|
| 1. Sitz Vorne Links | Damaged | Smart repair |
| 2. headlining | Damaged | Smart repair |

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right




rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims




rims



engine compartment



service book



Others



1. Sitz Vorne Links



1. Sitz Vorne Links



2. headlining