



status report

customer: Bank 11, Neuss
contract number: 1161993730
reference:

vehicle data

Kia Sportage Spirit 2WD

Vehicle identification number	U5YPH814AGL072021	mileage read:	107346 km
First Registration / construction year:	10.06.2016 / 2016	Visit Date / place of birth:	01.09.2025 Neuss
Bodywork:	SUV	Re - import:	unknown
Body type:	hatchback	KBA no. :	1260//ADX
Fuel / emission class:	gasoline / € 6	transmission type:	manual transmission
Displacement / power:	1591 ccm / 97 kW (132 PS)	Engine:	front-wheel drive
paint:	(WD) CARRARAWEISS	Number of previous owners:	-
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	Leather / fabric
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	3 - Average
documents:		condition inside:	3 - Average
visit condition:	-		
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	no / -	- / -

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Barum	225/60/R17/99V 5 mm
1st axis - right / states .	Barum	225/60/R17/99V 5 mm
2nd axis - Left / states .	Kumho	225/60/R17/99V 5 mm
2nd axis - right / states .	Kumho	225/60/R17/99V 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• 3rd brake light • Airbag Driver / passenger side • Anti- lock braking system (ABS) • Gauges supervision with LCD display • Power side mirrors . anklappbar • Power side mirrors . adjustable , both • Bi -xenon headlights <i>Dynamisches Kurvenlicht, Scheinwerfer-Reinigungsanlage (SRA)</i> • board computer • Chrome side window surround • roof spoiler • Off switch for headlights • Driving Assistance System hill descent assist • Driving assistance system City emergency braking function • Driving Assistance System Traffic Sign Recognition • handsfree Bluetooth • Level indicator windshield washer • Cruise control system (cruise control) • Rear cupholder • LED Taillights • rear window wiper • Isofix admissions for child seat • 2-zone automatic climate control <i>Automatisches Antibeschlag-System</i> • Load compartment cover • Steering wheel (leather) • Steering column (steering wheel) height / longitudinally adjustable • Air vents in the rear center	• Airbag switched off • Active Brake Light (ESS) • Drive Front Wheel Drive • Audio navigation system KIA (8 inches) <i>Touchscreen-Farbdisplay (8,0 Zoll)</i> • Power side mirrors . adjustable and heated, both • Body color door mirrors • Indicator integrated into mirrors • brake Assist • roof rails • rear Parking Sensors • Electron. Stability Program (ESP / ESC) • Driving Assistance System Hill Start Assist • Driving Assistance System High-Beam Assistant • Electric windows front + rear • Doormats • Counter- steering assist (Vehicle Stability Management , VSM) • Transmission 6-speed • Belt pretensioners with force limiters • heated rear window • Rearview mirror with auto dip • Body 5-door • Head airbag system , front and rear • Lumbar support front left seat • heated steering wheel • • Rear center armrest • Engine 1.6 ltr. - 97 kW GDI KAT • Fog Lights • Tire Repair

• Front center armrest • Multifunction for steering wheel • Wheelbase 2670 mm • Tire Pressure Monitoring System • Rear seat backrest split / folding • Gearshift / selector lever leather • Windscreen wipers with rain sensor • side airbags • Seat belts front height adjustable • Seat cover / upholstery fabric / leather • Heated front seats • Sound System • Socket (12V) port in center console • subwoofer • Door handles outside with LED lighting • Underride guard, front • USB port center console • immobilizer	• Rear View Camera • Low emissions Euro 6 emissions standard • Shift Indicator • Close / start system smart key • power steering • Front left seat height adjustment • Heated rear • Sun visors with mirrors (illuminated) • Start / Stop System (ISG) • Body color bumpers • LED daytime running lights • Door handles on the outside chrome • USB + AUX - IN connection • Glazing behind darkened • Central locking with remote control
---	--

special Features

We remind you that the data provided were taken from the DAT database.\r\nNo liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle
---	--

	valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	- -
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
oil loss:			examined limited	 examined limited	
air conditioning:			examined limited	lighting system:	
coupling:			examined limited	 examined limited	
engine running:			examined limited	exhaust System:	
transmission:			examined limited	shock absorber:	
				 not possible	

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could not be checked during the inspection .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Das Fahrzeug hat Laufleistungs und Altersbedingte Gebrauchsspuren. Kosten und Schadensenerweiterung sind möglich. Die Lackschichtdicke ist erhöht. Im Innenraum ist eine sehr unangenehm Geruch. Schäden und Folgeschäden sind nicht ausgeschlossen (kein Zigaretten Geruch).

damage



component	Damage	Rep kind
1. tailgate	Subsequently painted	acceptable
2.	Odour	Ozone treatment
3. maintenance	Due	Replace
4. proof of maintenance	Missing	Replace
5. Rückfahrkamera	Corroded	Replace
6. Door trim Front - right	Damaged	Replace
7. tailgate	Deformed	Refurbish and paint
8. Rückleuchte Mitte	Scrape	Replace
9. Rear bumper	Damaged	Refurbish and paint
10.	Damaged	Replace
11. Sitz - Hinten - Mitte: Lehne (Leder)	Damaged	Replace
12. Front door - left	Scratch(es)	Paint
13. Türeinstieg Vorne - Links	Damaged	Refurbish and paint
14. Front door seal - left	Damaged	Replace
15.	Damaged	Replace
16.	Scrape	Replace
17. roof	Delle	Refurbish and paint
18. Windshield	Chipping from stones in field of view	Replace
19. Bi xenon headlights - left	Damaged	Replace
20. Bi xenon headlights - Right	Damaged	Replace
21. exterior body	Dirty	
22. Outside mirror - left	Scrape	Paint
23.	Scrape	Replace
24. Front door - right	Scratch(es)	Paint
25. Türeinstieg Vorne - Rechts	Damaged	Refurbish and paint
26. Door Rear - right	Deformed	Refurbish and paint
27.	Wear and tear	acceptable
28. Türeinstieg Hinten - Rechts	Deformed	Refurbish and paint
29. flooring	Burn hole	Replace
30. Heckklappenschalter	Damaged	Replace
31. instrument cluster	Scratch(es)	Replace
32. Diffusor	Scrape	Replace
33.	Scrape	Replace
34. spoiler	Scrape	Replace
35.	Scratch(es)	Smart repair

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,rlnand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims



rims



engine compartment



service book



Others



Navigation system



1. tailgate



5. Rückfahrkamera




6. Door trim Front - right



6. Door trim Front - right



7. tailgate



7. tailgate



8. Rückleuchte Mitte




8. Rückleuchte Mitte



9. Rear bumper



9. Rear bumper




10.




10.



10.



11. Sitz - Hinten - Mitte: Lehne (Leder)



11. Sitz - Hinten - Mitte: Lehne (Leder)



12. Front door - left



12. Front door - left



13. Türeinstieg Vorne - Links




13. Türeinstieg Vorne - Links



13. Türeinstieg Vorne - Links



14. Front door seal - left



14. Front door seal - left



15.



15.



16.



16.




17. roof



17. roof



18. Windshield



18. Windshield



19. Bi xenon headlights - left



19. Bi xenon headlights - left



19. Bi xenon headlights - left



20. Bi xenon headlights - Right



21. exterior body



22. Outside mirror - left



22. Outside mirror - left



23.



23.



24. Front door - right



24. Front door - right



24. Front door - right



25. Türeinstieg Vorne - Rechts



25. Türeinstieg Vorne - Rechts



25. Türeinstieg Vorne - Rechts



26. Door Rear - right



26. Door Rear - right



27.




27.



27.



27.



28. Türeinstieg Hinten - Rechts



28. Türeinstieg Hinten - Rechts



29. flooring



30. Heckklappenschalter



31. instrument cluster



31. instrument cluster



32. Diffusor



32. Diffusor



33.



33.



34. spoiler



34. spoiler



35.



35.



35.