



DACIA Duster I 2014 Diesel

Duster 1.5 dci Laureate 4x2 110cv

VIN NO UU1HSDADF53185784

Registration Number EZ063PW



MOT Date

2025-05-14

Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date

2015-06-16

Odometer Reading

224985 km

Country First Registered

Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250917152745
Inspection Date / Place	2025-09-17 / BCA Lodi	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Grey	Engine Size (cc)	1461
Engine Size	1.5	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	127

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Alloys wheels	Satellite navigation	Remote adjusting wing mirrors
Trip Computer	Stability control	Power assisted steering	Digital Radio
Parcel Shef	Remote central locking	Tyre Mobility Kit	

Wheels & Tyres


Mounted Tires

Tyre / Wheel Type	Four Seasons	
	HANKOOK HANKOOK-KINERGY 4S 2 H750	215/65//R16 - 102V / 2 mm
	HANKOOK HANKOOK-KINERGY 4S 2 H750	215/65//R16 - 102V / 3 mm
	HANKOOK HANKOOK-KINERGY 4S 2 H750	215/65//R16 - 102V / 3 mm
	HANKOOK HANKOOK-KINERGY 4S 2 H750	215/65//R16 - 102V / 3 mm

Cosmetic Damage


24 Danni

7 Danni



Component		Damage	Comments
1	Steering Wheel / Front	Interior / Worn - out	
2	Dashboard / Front	Interior / Broken	
3	Center Console	Interior / Broken	
4	Seat Cushion / Front Left	Interior / Ripped	
5	Seat Cushion / Front Left	Interior / Ripped	
6	Floor Carpet	Interior / Ripped	
7	Windshield / Front	Glass Break / Impact	
8	Hood	Bodywork / Dent	
9	Hood	Bodywork / Dent	
10	Bumper / Front	Bodywork / Dent	
11	Rim / Front Left	Out of Bodywork / Scratch	
12	Fender / Front Left	Paint / Chipping	

13	Fender / Front Left	Bodywork / Poor Previous Repair
14	Mirror Shell / Front Left	Paint / Scratch / Line
15	Door / Front Left	Bodywork / Dent
16	Door / Back Left	Bodywork / Dent
17	Fender / Back Left	Bodywork / Dent
18	Rim / Back Left	Out of Bodywork / Scratch
19	Bumper / Back	Bodywork / Dent
20	Tailgate	Bodywork / Dent
21	Rear Window / Back	Glass Break / Scratch
22	Fender / Back Right	Bodywork / Dent
23	Rim / Back Right	Out of Bodywork / Scratch
24	Door / Back Right	Bodywork / Dent
25	Door / Front Right	Bodywork / Dent
26	Mirror Shell / Front Right	Paint / Scratch / Line
27	Fender / Front Right	Bodywork / Dent
28	Roof	Bodywork / Dent / Hail Area
29	Roof Upholstery	Interior / Ripped
30	Other	Bodywork / Poor Previous Repair
31	Rim / Front Right	Out of Bodywork / Scratch



1. Steering Wheel / Front
Interior / Worn - out -



2. Dashboard / Front
Interior / Broken -




3. Center Console
Interior / Broken -



4. Seat Cushion / Front Left
Interior / Ripped -



5. Seat Cushion / Front Left
Interior / Ripped -



6. Floor Carpet
Interior / Ripped -



7. Windshield / Front
Glass Break / Impact -



8. Hood
Bodywork / Dent -



9. Hood
Bodywork / Dent -



10. Bumper / Front
Bodywork / Dent -




11. Rim / Front Left
Out of Bodywork / Scratch -



12. Fender / Front Left
Paint / Chipping -



13. Fender / Front Left
Bodywork / Poor Previous Repair -




14. Mirror Shell / Front Left
Paint / Scratch / Line -



15. Door / Front Left
Bodywork / Dent -



16. Door / Back Left
Bodywork / Dent -



17. Fender / Back Left
Bodywork / Dent -



18. Rim / Back Left
Out of Bodywork / Scratch -



19. Bumper / Back
Bodywork / Dent -



20. Tailgate
Bodywork / Dent -



21. Rear Window / Back
Glass Break / Scratch -



22. Fender / Back Right
Bodywork / Dent -



23. Rim / Back Right
Out of Bodywork / Scratch -



24. Door / Back Right
Bodywork / Dent -



25. Door / Front Right
Bodywork / Dent -



26. Mirror Shell / Front Right
Paint / Scratch / Line -



27. Fender / Front Right
Bodywork / Dent -



28. Roof
Bodywork / Dent / Hail Area -



29. Roof Upholstery
Interior / Ripped -



30.
Bodywork / Poor Previous Repair -



31. Rim / Front Right
Out of Bodywork / Scratch -

Mechanical Condition

Equipments Test

AC / Heating System



Other Equipments



Engine

Vehicle Start - up



Engine Starts



Engine Leak Visible



Clutch

Clutch Functioning



Levels

Brakes Fluid



Coolant Fluid



Test Drive Inspection

Other Checks

Steering



Brakes



Suspension



Equipments Test

Steering | Noise / Anomaly



Engine

Power Loss



Fume Quantity



Engine Noise



Gearbox

Manual Gearbox



General

Test Driven Status




Test Drive Comment

A/C NON RAFFREDDA.

 **No troubles detected, good condition or correct tests, according to vehicle age and mileage**

 **Damages or malfunction detected that requires repairs by the buyer**

 **Not applicable**

 **Not tested**