



DACIA DUSTER  
Duster 1.5 dCi 110 4x4 Ambiance

VIN NO UU1HSDADG52012089

Registration Number DS616KV



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



2015-06-17

Odometer Reading



146743 km

Country First Registered



Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20251001163205
Inspection Date / Place	2025-10-01 / BCA SOLOGNE	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Light Grey	Engine Size (cc)	1461
Engine Size	1.5	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive switchable
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	135

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment


Central locking	Alloys wheels	Tow ball	Power assisted steering
Radio	Stability control	Front fog lamps	Roof rails

Equipment Details


Seat Heating	No	Air Conditioning	Yes
--------------	----	------------------	-----

Cosmetic Damage

11 Dommages



7 Dommages



Component		Damage	Comments
1	Seat / Front Left	Interior / Ripped	
2	Floor Carpet	Interior / Dirty	
3	Panel Filling / Front Left	Interior / Dirty	
4	Dashboard / Front	Interior / Dirty	
5	Seat / Back Center	Interior / Dirty	
6	Trunk Carpet	Interior / Dirty	
7	Seat / Front Right	Interior / Dirty	
8	Roof	Paint / Scratch / Line	
9	Roof	Bodywork / Dent / Dent	
10	Fender / Back Right	Bodywork / Dent / Deformation	
11	Fender / Back Right	Bodywork / Dent / Dent	
12	Fender / Front Right	Bodywork / Dent / Deformation	

13	Shield / Front	Bodywork / Dent / Deformation
14	Windshield / Front	Glass Break / Impact
15	Fender / Back Left	Bodywork / Dent / Deformation
16	Back Light / Right	Bodywork / Breakage / Crack
17	Door / Back Right	Bodywork / Dent / Dent
18	Back Light / Left	Bodywork / Breakage





1. Seat / Front Left  
Interior / Ripped -



2. Floor Carpet  
Interior / Dirty -



3. Panel Filling / Front Left  
Interior / Dirty -



4. Dashboard / Front  
Interior / Dirty -



5. Seat / Back Center  
Interior / Dirty -



6. Trunk Carpet  
Interior / Dirty -





7. Seat / Front Right  
Interior / Dirty -



8. Roof  
Paint / Scratch / Line -



9. Roof  
Bodywork / Dent / Dent -



10. Fender / Back Right  
Bodywork / Dent / Deformation -



11. Fender / Back Right  
Bodywork / Dent / Dent -



12. Fender / Front Right  
Bodywork / Dent / Deformation -





13. Shield / Front  
Bodywork / Dent / Deformation -



14. Windshield / Front  
Glass Break / Impact -




15. Fender / Back Left  
Bodywork / Dent / Deformation -



16. Back Light / Right  
Bodywork / Breakage / Crack -



17. Door / Back Right  
Bodywork / Dent / Dent -



18. Back Light / Left  
Bodywork / Breakage -

Mechanical Condition


Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

*The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.*