

DACIA DUSTER Duster TCe 125 4x2 Prestige Edition 2016



VIN NO UU1HSDCW654013443 Registration Number DY737YR

MOT Date

Number of Keys

Odometer Reading

☆-

:::-

P1

2 127300 km

Last Service

Last Service Mileage

Number of Owners

First Registration Date

Country First Registered

2016-01-18

=-

Inspection Report Summary

| Customer | BCAuto Encheres | Report Number | P20250901144714 |
|-------------------------|---------------------------------|----------------|-----------------|
| Inspection Date / Place | 2025-09-01 / BCA GUERLESQUIN | Cosmetic Grade | 4 |

Vehicle Summary

| Vehicle Condition | Non-Runner | VAT Type | Exempt Rate |
|-------------------|-----------------------|------------------------|-------------|
| Fuel Type | Petrol | Gearbox Type | Manual |
| Colour | Black | Engine Size (cc) | 1197 |
| Engine Size | 1.2 | No of Doors | 5 |
| Body Type | Stationwagon / Estate | Drive Train | Front |
| Seat Colour | | No of Seats | 5 |
| Charging Cables | | NEDC CO2 Rating (q/km) | 138 |

Vehicle History & Documents

| Service Book Available | Present | Next Service Mileage | km |
|------------------------|------------|----------------------|----|
| Previous Usage | Normal Use | Imported | No |
| Manufacturer Warrenty | | | |




























Equipment

| Central locking | Rear parking sensors | Stability control | Front fog lamps |
|-------------------------|----------------------|-------------------|-----------------|
| Roof rails | Radio | Alloys wheels | Cruise control |
| Power assisted steering | | | |

Equipment Details

| Seat Heating | No | Air Conditioning | Yes |
|--------------|------------------|------------------|-----|
| Sunroof Type | Tilt/Slide Steel | | |

Cosmetic Damage



| | Component | Damage | Comments |
|----|-------------------------|-------------------------|----------|
| 1 | Fender / Front Left | Paint / Scratch / Scuff | |
| 2 | Fender / Front Left | Bodywork / Breakage | |
| 3 | Fender / Front Left | Paint / Stone Chip | |
| 4 | Fender / Front Left | Bodywork / Dent / Dent | |
| 5 | Side Panel / Back Right | Paint / Scratch / Scuff | |
| 6 | Side Panel / Back Right | Bodywork / Dent / Dent | |
| 7 | Side Panel / Back Right | Paint / Scratch / Line | |
| 8 | Fender / Front Right | Paint / Stone Chip | |
| 9 | Fender / Front Right | Paint / Scratch / Line | |
| 10 | Fender / Front Right | Paint / Chipping | |
| 11 | Hood | Paint / Scratch / Scuff | |
| 12 | Hood | Paint / Stone Chip | |
| 12 | НООО | Paint / Stone Unip | |



1. Fender / Front Left Paint / Scratch / Scuff -

2. Fender / Front Left Bodywork / Breakage -




3. Fender / Front Left Paint / Stone Chip -

4. Fender / Front Left Bodywork / Dent / Dent -



5. Side Panel / Back Right Paint / Scratch / Scuff -

6. Side Panel / Back Right Bodywork / Dent / Dent -



7. Side Panel / Back Right Paint / Scratch / Line -

8. Fender / Front Right Paint / Stone Chip -



9. Fender / Front Right Paint / Scratch / Line -

10. Fender / Front Right Paint / Chipping -



11. Hood Paint / Scratch / Scuff -

12. Hood Paint / Stone Chip -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut



- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- Not tested

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.