



status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

Dacia Dokker Stepway

Vehicle identification number	UU1K6720164200706	mileage read:	75797 km
First Registration / construction year:	21.11.2019 / 2019	Visit Date / place of birth:	26.06.2025 Riedstadt-Goddelau
Bodywork:	cars	Re - import:	yes
Body type:	VAN / MPV	KBA no. :	8212//AEU
Fuel / emission class:	gasoline / € 6	transmission type:	manual transmission
Displacement / power:	1332 ccm / 96 kW (131 PS)	Engine:	front-wheel drive
paint:	BEIGE DUNE	Number of previous owners:	Unbekannt
Doors / seats:	5 / 5	number keys:	1
Next HU / AU:	- / -	cushion type:	substance
Service book available:	yes	Interior Color:	gray
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	Eg II (veh - letter)	state outside:	3 - Average
documents:		condition inside:	3 - Average
visit condition:	-		
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	1	yes / -	- / -
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	All season tires	steel
1st axis - Left / states .	Nexen	195/55/R16/91V 5.5 mm
1st axis - right / states .	Nexen	195/55/R16/91V 5.5 mm
2nd axis - Left / states .	Nexen	195/55/R16/91V 5.5 mm
2nd axis - right / states .	Nexen	195/55/R16/91V 5.5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment

- | | |
|---|---|
| <ul style="list-style-type: none"> • Storage compartment in the roof lining • Airbag switched off • Anti- lock braking system (ABS) • <i>Radioempfang Digital (DAB), Audio-/Radio-Fernbedienung am Lenkrad, Freisprecheinrichtung Bluetooth</i> • Mirrors titanium look • board computer • roof rails • rear Parking Sensors • Electron. Stability Program (ESP) • Cruise control system (cruise control) <i>Geschwindigkeits-Begrenzeranlage</i> • Lockable glove compartment • heated rear window • Heating with air recirculation • Body 5-door • <i>Sitz vorn links höhenverstellbar, Lenksäule (Lenkrad) höhenverstellbar</i> • • Air vents in the rear • model refinement • Fog Lights • Smokers Package • Tire Pressure Monitoring System • Low pollutant according to the Euro 6d-TEMP emissions standard • Sliding left with vent windows • Protection moldings laterally • power steering | <ul style="list-style-type: none"> • Airbag • Airbag driver • Anti -Slip Regulation (ASR) • Power side mirrors . adjustable and heated • Outside temperature display • brake Assist • Eco Mode (driving mode switch) • Electr . Brakeforce Distribution • Electric windows front • Transmission 6-speed • Rear wing doors with glazing • rear window wiper • Isofix admissions for child seat in back seat • Sound lu0026 Climate Package <i>Audiosystem: Radio-CD (MP3-fähig) mit AUX-IN, USB-Anschluss und Bluetooth (Dacia Plug & Radio), Audio-/Radio-Fernbedienung am Lenkrad, Freisprecheinrichtung Bluetooth, Klimaanlage</i> • Plastic floor in the boot / load compartment • LM rims • Front center armrest • • • Tire Repair • Back seat (2nd row) divided , foldable (1/3 - 2/3) • Shift Indicator • Sliding door right with opening window • Front Side Airbags • Seat belts front height adjustable • • Body color bumpers |
|---|---|

• Seat cover / upholstery fabric • Socket (12V connection) in 2.Sitzreihe • SUV package • Door lock automatically • tinted glazing • Central locking with remote control	• Daytime running lights • Underrun protection Satin Chrome • Immobilizer with transponder
---	--

special Features	
• Metallic paint	

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	yes yes
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
oil loss:			examined limited		
air conditioning:			in order	lighting system:	
coupling:			examined limited		
engine running:			examined limited	exhaust System:	
transmission:			examined limited		
				shock absorber:	
					
				examined limited	

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	A function of the air conditioning was found to visiting time .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. Fehlermeldungen, Schaden erweiterung möglich	Error message	Carry out a fault diagnosis
2.	Not okay	Replace
3.	Dirty	
4. Sidewall - Rear - Left	Scratch(es)	Smart repair
5. Rear door - left	Scratch(es)	Smart repair
6. spoiler	Scratch(es)	Replace
7.	Burn hole	Replace
8. Glove compartment	Damaged	Replace
9.	Damaged	Replace
10.	Damaged	Replace
11. maintenance	Due	Replace
12. key	Missing	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims




engine compartment



service book



Others



Navigation system



1. Fehlermeldungen, Schaden erweiterung möglich



1. Fehlermeldungen, Schaden erweiterung möglich



1. Fehlermeldungen, Schaden erweiterung möglich



1. Fehlermeldungen, Schaden erweiterung möglich




2.



2.



2.



2.




2.




2.



2.



2.



2.



2.



2.



4. Sidewall - Rear - Left




4. Sidewall - Rear - Left



4. Sidewall - Rear - Left



4. Sidewall - Rear - Left



5. Rear door - left



5. Rear door - left



5. Rear door - left



5. Rear door - left



6. spoiler



6. spoiler



6. spoiler



6. spoiler



6. spoiler



6. spoiler



6. spoiler



7.



7.



7.



7.



8. Glove compartment



8. Glove compartment



8. Glove compartment



8. Glove compartment



9.



9.



9.



9.



9.



9.



10.



10.



10.



10.



10.