



RENAULT CAPTUR
Captur TCe 120 Energy Intens

VIN NO VF12R031657357351
Registration Number ES403FT



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	2	115948 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2025-03-24	106369	2017-11-27	-

Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250929075211
Inspection Date / Place	2025-09-29 / BCA NANTES	Cosmetic Grade	3


Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Petrol	Gearbox Type	Manual
Colour	Orange	Engine Size (cc)	1197
Engine Size	1.2	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	125

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Rear parking sensors	Stability control	Front fog lamps
Satellite navigation	Radio	Alloys wheels	Cruise control
Power assisted steering			

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Wheels & Tyres


Left Rear Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	6	Right Front Tyre Depth	6

Cosmetic Damage

15 Dommages



0 Dommages



Component		Damage	Comments
1	Corner Bumper / Front Right	Paint / Scratch / Line	
2	Shield / Front	Paint / Scratch / Line	
3	Rim / Front Left	Out of Bodywork / Scratch	
4	Door / Front Left	Bodywork / Dent / Dent	
5	Door / Front Left	Paint / Scratch / Line	
6	Rim	Out of Bodywork / Scratch	
7	Corner Bumper / Back Right	Paint / Scratch / Line	
8	Rim Brake pads	Out of Bodywork / Scratch	
9	Door / Back Right	Bodywork / Dent / Deformation	
10	Wing Stick / Back Right	Paint / Scratch / Line	
11	Door / Back Right	Paint / Scratch / Line	
12	Door / Back Right	Paint / Scratch / Line	

13	Door / Front Right	Bodywork / Dent / Dent
14	Rim	Out of Bodywork / Scratch
15	Hood	Bodywork / Dent / Deformation



1. Corner Bumper / Front Right
Paint / Scratch / Line -



2. Shield / Front
Paint / Scratch / Line -



3. Rim / Front Left
Out of Bodywork / Scratch -




4. Door / Front Left
Bodywork / Dent / Dent -



5. Door / Front Left
Paint / Scratch / Line -




6. Rim
Out of Bodywork / Scratch -




7. Corner Bumper / Back Right
Paint / Scratch / Line -



8. Rim Brake pads
Out of Bodywork / Scratch -




9. Door / Back Right
Bodywork / Dent / Deformation -




10. Wing Stick / Back Right
Paint / Scratch / Line -



11. Door / Back Right
Paint / Scratch / Line -




12. Door / Back Right
Paint / Scratch / Line -



13. Door / Front Right
Bodywork / Dent / Dent -



14. Rim
Out of Bodywork / Scratch -



15. Hood
Bodywork / Dent / Deformation -

Mechanical Condition

Levels

Oil - Condition	✓	Level - Oil	✓
Coolant Fluid - Condition	✓	Coolant Fluid	✓
Brakes Fluid	✓		

Engine

Cross Member	NA	Control Liquid Leak	✓
Serpentine Belt	✓		

Equipments Test

Dump / Trail / Tail Gate Lift	NA	Main & Spare Keys Functioning	✓
Central Locking	✓	Electric Windows	✓
Audio Equipment	✓	Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	NA
AC / Heating System	✓	Parking Sensors / Cameras Functioning	✓
Navigation System	✓		

Tyres

Presence Anti-Theft Lock Nut	✓
------------------------------	---

Dashboard Lights

Dashboard Working	✓	ABS Warning Light	✓
Transmission Warning Light	NA	Diesel Particulate Filter Light	NA
ESP Fault/Traction Control Malfunction Light	✓	4WD Light	NA
Service Light	✓	Engine Light	!
Oil Pressure Warning Light	✓	Airbag Warning Light	✓
Brake Warning Light	✓	Level - Fuel / Battery	60
Steering Fluid Level	NA		

Hybrid/EV

Charge Port Condition	NA	Charge lead 1 condition /Charge lead 2 condition	NA
-----------------------	----	--	----

Test Drive Inspection

Test Drive			
Engine functioning	✓	Engine / Aux Belt / Pulley Noise	✓
Steering Noise/Gripping	✓	Vehicle Starts	✓
Engine Power	✓	Smoke Quantity	✓
Transmission	✓	Clutch Functioning	✓
Steering	✓	Brakes Functioning	✓
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.