



Hüsge Gruppe®
Die Gutachter

status report

customer: BCA Autoauktionen GmbH

reference:

vehicle data

Renault Twingo Limited

Vehicle identification number	VF1AH000863505917	mileage read:	122175 km
..			
First Registration / construction year:	08.07.2019 / 2019	Visit Date / place of birth:	30.09.2025 Hoppegarten
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	3333//BLU
Fuel / emission class:	gasoline / € 6	transmission type:	manual transmission
Displacement / power:	999 ccm / 54 kW (73 PS)	Engine:	rear-wheel drive
paint:	CRYSTAL WEISS	Number of previous owners:	2
Doors / seats:	5 / 4	number keys:	1
Next HU / AU:	- / -	cushion type:	substance
Service book available:	yes	Interior Color:	gray
smoking vehicle:	yes	Last service km / on the:	19972 / 01.06.2020
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	Eg II (veh - letter)	state outside:	5 - neglected
documents:			
visit condition:	-	condition inside:	4 - moderate
state general:	5 - neglected		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	1	yes / no	19972 / 01.06.2020
<input checked="" type="checkbox"/> Fernbed . Auxiliary heating	<input checked="" type="checkbox"/> partition net	<input checked="" type="checkbox"/> Wind Deflector	<input checked="" type="checkbox"/> AHK fixed
<input checked="" type="checkbox"/> AHK removable	<input checked="" type="checkbox"/> AHK swivel	<input checked="" type="checkbox"/> AHK key	<input checked="" type="checkbox"/> Fernbed . entertainment
<input checked="" type="checkbox"/> headphone	<input checked="" type="checkbox"/> Load compartment cover	<input checked="" type="checkbox"/> LED headlights	<input checked="" type="checkbox"/> navigation system
<input checked="" type="checkbox"/> Persenning	<input checked="" type="checkbox"/> Xenon headlights		

☒ available

☒ not available

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	All season tires	Steel with wheel cover
1st axis - Left / states .	Kleber	165/65/R15/81H 5 mm
1st axis - right / states .	Kleber	165/65/R15/81H 5 mm
2nd axis - Left / states .	Kleber	185/60/R15/88H 5 mm
2nd axis - right / states .	Kleber	185/60/R15/88H 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • 2 tweeters • Airbag Driver / passenger side • Anti -Slip Regulation (ASR) • board computer • Electron. Stability Program (ESP) • Driving Assistance System Crosswind Assist • Speed ??Begrenzeranlage • Belt tensioners • rear spoiler • Body 5-door • Head airbag system front • Integrated headrests • Steering column (steering wheel) adjustable in height • model refinement • R&GO + Climate-Package combination <i>Audiosystem: Radio R&GO (Bluetooth), Audio-/Radio-Fernbedienung am Lenkrad, Freisprecheinrichtung Bluetooth, USB-Anschluss inkl. AUX-IN-Anschluss (Plug & Music), Klimaanlage</i> • Tire repair kit • Rear seat backrest split / folding • Front Side Airbags • power steering • Front right seat folded down • Special paintwork Pyrénées white • Steel wheels , front / rear 5x15 / 5,5x15 • LED daytime running lights • Provision theft alarm system / alarm | <ul style="list-style-type: none"> • Airbag switched off • Anti- lock braking system (ABS) • Mirrors mech. adjustable from inside , both • Brake Assist • Driving Assistance System Hill Start Assist (HSA) • Electric windows front • Transmission 5-speed • Glove compartment with flap • Isofix admissions for child seat • Kofferraumabdeckung • Rear headrests • Steering wheel (leather) + gearshift / selector lever leather • • Motor 1,0 Ltr. - 54 kW SCe • hubcaps • Tire Pressure Monitoring System • Low emissions according to Euro 6d TEMP emission standard • Side moldings • Front left seat height adjustment • Seat cover / upholstery fabric • Limited edition <i>Außenspiegel schwarz hochglänzend, Dekor-/Zierstreifen Luxe, Klimaanlage</i> • Start / Stop system • Exterior door handles body color • Central locking with remote control |
|---|--|

special Features

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	no no
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	- -
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			examined limited		
oil loss:			examined limited		
air conditioning:			not possible	lighting system:	
			examined limited		
coupling:			Out of order	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning could not be checked during the inspection . **Due to weather conditions not possible examination.
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The clutch was wrong for visiting time . *demnächst Verschleißgrenze erreicht
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*

damage



	component	Damage	Rep kind
1.	key	Missing	Replace
2.	maintenance	Missing	Replace
3.		Wear and tear	acceptable
4.	Rear bumper	Scrape	Paint
5.	Taillight right	Damaged	Replace
6.	Sidewall - Rear - right	Damaged	Refurbish and paint
7.	Door Rear - right	Deformed	Refurbish and paint
8.	roof		Paint
9.		Dirty (strong)	
10.		Wear and tear	acceptable
11.	side skirt - right	Deformed	Replace
12.	Front bumper	Scrape	Paint
13.	Front door - left	Deformed	Refurbish and paint
14.	side skirt - left	Deformed (slightly)	Refurbish and paint
15.		Damaged	Replace
16.	Front door seal - left	Damaged	Replace
17.	Türeinstieg Vorne - Links	Damaged	Refurbish and paint
18.	Front door - right	Deformed (slightly)	Refurbish and paint
19.	coupling	Not okay	Carry out a fault diagnosis

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



3.



3.



4. Rear bumper



4. Rear bumper



5. Taillight right



6. Sidewall - Rear - right




7. Door Rear - right



8. roof



8. roof



9.



9.



9.



9.



10.



11. side skirt - right



12. Front bumper



13. Front door - left



13. Front door - left



14. side skirt - left



15.



16. Front door seal - left



17. Türeinstieg Vorne - Links



18. Front door - right