



RENAULT MÉGANE

Mégane 1.6 16V Luxe Dynamique

VIN NO VF1BM1R0H34986764
Registration Number 8950WT62



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20251008175145
Inspection Date / Place	2025-10-08 / BCA BETHUNE	Cosmetic Grade	2

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Petrol	Gearbox Type	Manual
Colour	Red	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	4
Family	Passenger Car	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	163
Engine Rating CV		Metalic Colour	Yes
Accident Damage	No	Euro Emission	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			



Equipment


Central locking	Radio	Cruise control	Power assisted steering
Electrically folding wing mirrors	Rear parking sensors	Front fog lamps	

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Cosmetic Damage

20 Dommages



4 Dommages



Component		Damage	Comments
1	Floor Carpet	Interior / Dirty	
2	Floor Carpet	Interior / Dirty	
3	Roof Upholstery	Interior / Loose	
4	Corner Bumper / Front Right	Paint / Scratch / Scuff	
5	Roof Upholstery	Interior / Loose	
6	Bumper / Back	Paint / Scratch / Scuff	
7	Corner Bumper / Front Right	Paint / Scratch / Scuff	
8	Bumper / Front	Paint / Scratch / Scuff	
9	Door / Back Right	Paint / Scratch / Line	
10	Fender / Front Left	Paint / Scratch / Line	
11	Corner Bumper / Back Left	Paint / Scratch / Scuff	
12	Rim / Front Left	Out of Bodywork / Scratch	À plat

13	Corner Bumper / Back Right	Paint / Scratch / Scuff	
14	Door / Front Right	Paint / Scratch / Line	
15	Rim / Front Right	Out of Bodywork / Scratch	
16	Rim / Back Left	Out of Bodywork / Scratch	À plat
17	Door / Back Left	Paint / Scratch / Line	
18	Rim / Back Right	Out of Bodywork / Scratch	À plat
19	Mirror / Front Left	Paint / Scratch / Scuff	
20	Hood	Paint / Chipping	
21	Fender / Front Right	Paint / Scratch / Scuff	
22	Side Panel / Back Left	Paint / Scratch / Scuff	
23	Mirror / Front Right	Bodywork / Breakage	
24	Side Panel / Back Left	Bodywork / Dent / Dent	




1. Floor Carpet
Interior / Dirty -



2. Floor Carpet
Interior / Dirty -




3. Roof Upholstery
Interior / Loose -



4. Corner Bumper / Front Right
Paint / Scratch / Scuff -



5. Roof Upholstery
Interior / Loose -




6. Bumper / Back
Paint / Scratch / Scuff -




7. Corner Bumper / Front Right
Paint / Scratch / Scuff -




8. Bumper / Front
Paint / Scratch / Scuff -




9. Door / Back Right
Paint / Scratch / Line -




10. Fender / Front Left
Paint / Scratch / Line -




11. Corner Bumper / Back Left
Paint / Scratch / Scuff -




12. Rim / Front Left
Out of Bodywork / Scratch -
À plat



13. Corner Bumper / Back Right
Paint / Scratch / Scuff -




14. Door / Front Right
Paint / Scratch / Line -



15. Rim / Front Right
Out of Bodywork / Scratch -




16. Rim / Back Left
Out of Bodywork / Scratch -
À plat



17. Door / Back Left
Paint / Scratch / Line -




18. Rim / Back Right
Out of Bodywork / Scratch -
À plat




19. Mirror / Front Left
Paint / Scratch / Scuff -



20. Hood
Paint / Chipping -




21. Fender / Front Right
Paint / Scratch / Scuff -



22. Side Panel / Back Left
Paint / Scratch / Scuff -



23. Mirror / Front Right
Bodywork / Breakage -



24. Side Panel / Back Left
Bodywork / Dent / Dent -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.