



RENAULT Megane

Megane ENERGY TCe 115 Start & Stop

VIN NO VF1BZ110650548519
Registration Number 0650548519



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-08-01	2	2	69489 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2014-08-28	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251002085538
Inspection Date / Place	2025-10-02 / BCA Berlin	Cosmetic Grade	5

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Unknown
Colour	Red	Engine Size (cc)	1198
Engine Size	1.2	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	119
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trip Computer	Anti-lock braking	Cruise control	Front parking sensors
Remote adjusting wing mirrors	Satellite navigation	CD Player	Keyless Entry
Rear parking sensors	Airbag Status	Bluetooth telephone interface	Digital Radio
Heated wing mirrors	Remote central locking	Stability control	Electrically folding wing mirrors
Rain sensitive windscreen wipers			


Equipment Details

Air Conditioning	Dual Zone Climate Control	Extra Wheel / Tyre Set	Summer Tyres - Alloy
Seat Heating	Front		


Wheels & Tyres

Extra Wheel - 1 Tyre Depth	5	Extra Wheel - 2 Tyre Depth	5
Extra Wheel - 3 Tyre Depth	5	Extra Wheel - 4 Tyre Depth	5
Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6


15 Schäden



Schäden

6/12 - Report Number P20251002085538

13	Door / Front Right	Paint / Scratch / Scuff
14	Bumper / Front	Paint / Scratch / Scuff
15	Bumper / Front	Paint / Scratch / Scuff




1. Hood
Bodywork / Dent / Dent -




2. Door / Front Left
Paint / Scratch / Scuff -



3. Door / Back Left
Paint / Scratch / Scuff -



4. Door / Back Left
Paint / Scratch / Scuff -



5. Roof
Paint / Scratch / Scuff -



6. Fender / Back Left
Paint / Scratch / Scuff -



7. Bumper / Back
Bodywork / Breakage / Crack -




8. Bumper / Back
Paint / Scratch / Scuff -




9. Bumper / Back
Paint / Scratch / Scuff -



10. Side Panel / Back Right
Paint / Scratch / Scuff -



11. Side Panel / Back Right
Paint / Scratch / Scuff -



12. Door / Front Right
Paint / Scratch / Scuff -



13. Door / Front Right
Paint / Scratch / Scuff -



14. Bumper / Front
Paint / Scratch / Scuff -



15. Bumper / Front
Paint / Scratch / Scuff -

Mechanical Condition

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	✓
Tire Pressure Monitoring System	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Other Equipments	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Brake

Brake System Anomaly ✓

Steering Wheel

Steering | Noise / Anomaly ✓

Engine

Engine Noise ✓ The Gears Scratch / Skip / Abnormal Operation ✓

Fume Quantity ✓ Power Loss ✓

Clutch

Clutch Functioning ✓

General

Test Driven Status ✓

- ✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage
- ! Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- ☐ Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)