


Vehicle details

VIN	VF1FL0002 66381923	Brand	RENAULT	Maintenance date	-
Licence Plate	VH-X1-2K	Model	TRAFIC L2H1 T29 ENERGY 2.0 dCi 120 Business	Maintenance mileage	-
Registration date	11/01/2021	Year	2021	Exterior Color	White Solid
Odometer	108 029 km	Engine size	1997	interior Color	Grey
Fuel	Petrol	Body Type	Panel van	Next technical inspection	-
Seats	3	Transmission	Manual	CO2	-
Doors	4	Gears	-		

Inspection Details

Inspection date	07/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Tow	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓


Removable element

Spare wheel (wheel & tyre)	✓
----------------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Bridgestone 205/65/16 Summer 3.6 mm		Bridgestone 205/65/16 Summer 3.2 mm	
Bridgestone 205/65/16 Summer 5.6 mm		Bridgestone 205/65/16 Summer 6.8 mm	

Exterior

3		Part	Bumper	4		Part	Exterior door mirror shell
		Position	Front			Position	Front right
		Damages	Broken			Damages	Broken
		Severity	-			Severity	-
		Repair mode	Replace			Repair mode	Replace

5		Part Position Damages Severity Repair mode	Wheelcap 16" Front right Missing - For info	6		Part Position Damages Severity Repair mode	Bonnet - Dent & Chips Diameter (mm) > 20 Repair
7		Part Position Damages Severity Repair mode	Exterior door mirror shell Front left Scratched Length (cm) > 10 Repair	8		Part Position Damages Severity Repair mode	Door Front left Dented Diameter (mm) > 20 Repair
9		Part Position Damages Severity Repair mode	Wing Back left Dent & Chips Diameter (mm) > 20 Repair	10		Part Position Damages Severity Repair mode	Bumper Back left Scratched Length (cm) > 10 Repair
11		Part Position Damages Severity Repair mode	Bumper Back Dented - Replace	12		Part Position Damages Severity Repair mode	Bumper Back right Scratched Length (cm) > 10 Repair
13		Part Position Damages Severity Repair mode	Rear light Back right Broken - Replace	14		Part Position Damages Severity Repair mode	Tailgate / Boot door Back left Dented Diameter (mm) > 20 Repair
15		Part Position Damages Severity Repair mode	Wing Back right Dent & Chips Diameter (mm) > 20 Repair	16		Part Position Damages Severity Repair mode	Side protection bar Right Dent & Chips - Lumpsum replacement
17		Part Position Damages Severity Repair mode	Door Right Dent & Chips Diameter (mm) > 20 Repair	18		Part Position Damages Severity Repair mode	Door moulding Right Broken - Replace

Interior damage

1



Part	Fabric seat
Position	Front left
Damages	Broken
Severity	-
Repair mode	Replace

2



Part	Carpet
Position	Front left
Damages	Broken
Severity	-
Repair mode	Replace