

RENAULT Kangoo Kangoo Rapid (ENERGY) dCi 90



VIN NO VF1FW51J161780863 Registration Number J161780863

MOT Date

Number of Keys

Odometer Reading

2026-01-01

3 1

P2

72251 km

Last Service

Last Service Mileage

Number of Owners

First Registration Date

Country First Registered

2025-01-16 67156 2019-02-28

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250924115243
Inspection Date / Place	2025-09-24 / BCA Berlin	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	Unknown
Colour	White	Engine Size (cc)	1461
Engine Size	1.5	No of Doors	4
Body Type	Box Wagon	Drive Train	Front
Seat Colour		No of Seats	2
Seat Covering Name	anthrazit	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	112
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







































Equipment

Tinted Glass	Anti-lock braking	Remote adjusting wing mirrors	Stability control
Radio	Airbag Status	Cruise control	Remote central locking
CD Player			


Equipment Details

Air Conditioning Yes	Air Conditioning	Yes	
----------------------	------------------	-----	--

Wheels & Tyres

Left Front Tyre Depth	7	Right Rear Tyre Depth	7
Left Rear Tyre Depth	7	Right Front Tyre Depth	7

Cosmetic Damage




	Component	Damage	Comments
1	Antenna Rod	Out of Bodywork / Breakage	
2	Hood	Bodywork / Dent / Dent	
3	Fender / Front Right	Paint / Scratch / Scuff	
4	Side Panel / Back Left	Bodywork / Dent / Dent	
5	Door / Front Left	Bodywork / Dent / Dent	
6	Tailgate Upholstery / Back	Interior / Broken	
7	Roof	Paint / Corrosion	



1. Antenna Rod Out of Bodywork / Breakage -

2. Hood Bodywork / Dent / Dent -




3. Fender / Front Right Paint / Scratch / Scuff -

4. Side Panel / Back Left Bodywork / Dent / Dent -



5. Door / Front Left Bodywork / Dent / Dent -

6. Tailgate Upholstery / Back Interior / Broken -



7. Roof Paint / Corrosion -

Mechanical Condition

Control Lights		
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light
Airbag Warning Light	•	Oil Pressure Warning Light
Brake Warning Light	•	Alternator / Battery
No Dashboard Lights	•	Display Defect
Engine		
Engine Status / EML	•	Engine Leak Visible
Engine Starts	•	
Equipments Test		
Electric Windows	•	Audio Equipment
AC / Heating System	•	Main & Spare Keys Functioning ✓
Other Equipments	•	
Levels		
Brakes Fluid	②	Coolant Fluid

Test Drive Inspection

Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss Brake Brake System Anomaly** Clutch **Clutch Functioning** General **Test Driven Status** No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

User Guide