



RENAULT TRAFIC COMBI
Trafic L2 dCi 170 Energy S&S EDC Intens

VIN NO VF1JL000172821570
Registration Number GW828FR



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	1	45296 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2024-04-04	France

Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20251008143149
Inspection Date / Place	2025-10-08 / BCA BETHUNE	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Not Movable	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Automatic
Colour	White	Engine Size (cc)	1997
Engine Size	2.0	No of Doors	4
Body Type	Platform Cab	Drive Train	Front
Seat Colour		No of Seats	9
Charging Cables		WLTP CO2 Emissions	
Metalic Colour	Blanc Glacier opaque	Electric Consumption	
Accident Damage	Yes	Euro Emission	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			



Equipment


Central locking	Radio	Power assisted steering	Electrically adjustable seats
Rear parking sensors			

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Cosmetic Damage

19 Dommages



20 Dommages



Component	Damage	Comments
1 Floor Carpet	Interior / Dirty	
2 Floor Carpet	Interior / Dirty	
3 Corner Bumper / Back Right	Paint / Scratch / Scuff	
4 Roof	Bodywork / Poor Previous Repair	Ruban adhésif (dégât sous réserve de diagnostic)
5 Hubcap / Front Right	Out of Bodywork / Scratch	
6 Corner Bumper / Back Left	Paint / Scratch / Scuff	
7 Bumper / Front	Missing Part	
8 Mirror / Front Right	Paint / Scratch / Scuff	
9 Hubcap / Back Left	Out of Bodywork / Scratch	
10 Bumper / Back	Paint / Scratch / Scuff	
11 Hubcap / Front Left	Out of Bodywork / Scratch	
12 Door / Back Right	Paint / Scratch / Line	

13 Hubcap / Back Right	Out of Bodywork / Scratch
14 Side Panel / Back Left	Paint / Scratch / Line
15 Side Panel / Back Left	Bodywork / Dent / Deformation
16 Hood	Bodywork / Dent / Deformation
17 Mirror / Front Left	Missing Part
18 Door Handle / Front Left	Missing Part
19 Door / Back Left	Bodywork / Dent / Deformation
20 Door / Back Left	Bodywork / Dent / Deformation
21 Door Handle / Front Left	Bodywork / Dent / Deformation



1. Floor Carpet
Interior / Dirty -



2. Floor Carpet
Interior / Dirty -



3. Corner Bumper / Back Right
Paint / Scratch / Scuff -



4. Roof
Bodywork / Poor Previous Repair -
Ruban adhésif (dégât sous réserve de diagnostic)



5. Hubcap / Front Right
Out of Bodywork / Scratch -



6. Corner Bumper / Back Left
Paint / Scratch / Scuff -



7. Bumper / Front
Missing Part -



8. Mirror / Front Right
Paint / Scratch / Scuff -



9. Hubcap / Back Left
Out of Bodywork / Scratch -



10. Bumper / Back
Paint / Scratch / Scuff -




11. Hubcap / Front Left
Out of Bodywork / Scratch -




12. Door / Back Right
Paint / Scratch / Line -



13. Hubcap / Back Right
Out of Bodywork / Scratch -



14. Side Panel / Back Left
Paint / Scratch / Line -




15. Side Panel / Back Left
Bodywork / Dent / Deformation -



16. Hood
Bodywork / Dent / Deformation -




17. Mirror / Front Left
Missing Part -




18. Door Handle / Front Left
Missing Part -



19. Door / Back Left
Bodywork / Dent / Deformation -



20. Door / Back Left
Bodywork / Dent / Deformation -



21. Door Handle / Front Left
Bodywork / Dent / Deformation -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.