



RENAULT MÉGANE

Mégane Estate III 1.9 dCi 130 FAP eco2 Dynamique Euro 5

VIN NO VF1KZ1S0644721564
Registration Number BG486ZV



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250808150511
Inspection Date / Place	2025-08-08 / BCA GUERLESQUIN	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Light Grey	Engine Size (cc)	1870
Engine Size	1.9	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	135

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warranty			





Equipment


Central locking	Stability control	Front fog lamps	Roof rails
Radio	Cruise control	Power assisted steering	Satellite navigation

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Cosmetic Damage

27 Dommages



1 Dommages




Component		Damage	Comments
1	Seat Cushion / Front Left	Interior / Burn	
2	Fender / Front Left	Paint / Scratch / Scuff	
3	Fender / Front Left	Paint / Scratch / Scuff	
4	Fender / Front Left	Paint / Chemical Damage	
5	Fender / Front Left	Paint / Stone Chip	
6	Fender / Front Left	Paint / Scratch / Scuff	
7	Side Panel / Back Left	Paint / Scratch / Line	
8	Side Panel / Back Left	Paint / Scratch / Scuff	
9	Side Panel / Back Left	Paint / Scratch / Scuff	
10	Side Panel / Back Left	Paint / Scratch / Line	
11	Side Panel / Back Left	Bodywork / Dent / Dent	
12	Side Panel / Back Left	Paint / Stone Chip	
13	Tailgate	Paint / Scratch / Scuff	

14	Tailgate	Bodywork / Dent / Dent
15	Tailgate	Bodywork / Dent / Dent
16	Side Panel / Back Right	Paint / Scratch / Line
17	Side Panel / Back Right	Paint / Scratch / Scuff
18	Side Panel / Back Right	Paint / Scratch / Line
19	Side Panel / Back Right	Paint / Scratch / Line
20	Fender / Front Right	Paint / Scratch / Line
21	Fender / Front Right	Paint / Scratch / Scuff
22	Fender / Front Right	Paint / Scratch / Line
23	Fender / Front Right	Paint / Scratch / Scuff
24	Hood	Paint / Scratch / Scuff
25	Hood	Paint / Scratch / Line
26	Hood	Bodywork / Dent / Deformation
27	Hood	Paint / Stone Chip
28	Hood	Paint / Scratch / Scuff



1. Seat Cushion / Front Left
Interior / Burn -



2. Fender / Front Left
Paint / Scratch / Scuff -



3. Fender / Front Left
Paint / Scratch / Scuff -



4. Fender / Front Left
Paint / Chemical Damage -



5. Fender / Front Left
Paint / Stone Chip -



6. Fender / Front Left
Paint / Scratch / Scuff -



7. Side Panel / Back Left
Paint / Scratch / Line -



8. Side Panel / Back Left
Paint / Scratch / Scuff -



9. Side Panel / Back Left
Paint / Scratch / Scuff -



10. Side Panel / Back Left
Paint / Scratch / Line -



11. Side Panel / Back Left
Bodywork / Dent / Dent -



12. Side Panel / Back Left
Paint / Stone Chip -



13. Tailgate
Paint / Scratch / Scuff -



14. Tailgate
Bodywork / Dent / Dent -



15. Tailgate
Bodywork / Dent / Dent -



16. Side Panel / Back Right
Paint / Scratch / Line -



17. Side Panel / Back Right
Paint / Scratch / Scuff -



18. Side Panel / Back Right
Paint / Scratch / Line -



19. Side Panel / Back Right
Paint / Scratch / Line -




20. Fender / Front Right
Paint / Scratch / Line -



21. Fender / Front Right
Paint / Scratch / Scuff -



22. Fender / Front Right
Paint / Scratch / Line -



23. Fender / Front Right
Paint / Scratch / Scuff -



24. Hood
Paint / Scratch / Scuff -



25. Hood
Paint / Scratch / Line -



26. Hood
Bodywork / Dent / Deformation -



27. Hood
Paint / Stone Chip -



28. Hood
Paint / Scratch / Scuff -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.