



RENAULT MASTER FOURGON

MASTER FGN PROP R3500 L4H3 BLUE DCI

145 GRAND CONFORT

VIN NO VF1MA000369202400
Registration Number GH448DR



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCA Auto Encheres	Report Number	P20250528110501
Inspection Date / Place	2025-07-30 / BCA TOULOUSE	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	White	Engine Size (cc)	2299
Engine Size	2.3	No of Doors	4
Body Type	Box Wagon	Drive Train	Rear
Seat Colour		No of Seats	3
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warranty			





Equipment

Central locking	Rear parking sensors	Cruise control	Satellite navigation
Radio	Stability control	Power assisted steering	

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Wheels & Tyres


Left Rear Tyre Depth	9	Left Front Tyre Depth	8
Right Rear Tyre Depth	9	Right Front Tyre Depth	8

Cosmetic Damage

9 Dommages




2 Dommages



Component		Damage	Comments
1	Seat Cushion / Front Right	Interior / Dirty	
2	Seat Cushion / Front Left	Interior / Dirty	
3	Side Panel / Back Left	Paint / Scratch / Line	
4	Tailgate	Bodywork / Dent / Deformation	
5	Bumper / Back	Paint / Scratch / Line	
6	Wing Stick / Back Right	Missing Part	
7	Vent Glass / Back Right	Missing Part	
8	Side Panel	Bodywork / Dent / Deformation	
9	Door / Back Right	Missing Part	
10	Door / Front Right	Paint / Scratch / Line	
11	Bumper / Front	Bodywork / Breakage / Hole	




1. Seat Cushion / Front Right
Interior / Dirty -



2. Seat Cushion / Front Left
Interior / Dirty -



3. Side Panel / Back Left
Paint / Scratch / Line -



4. Tailgate
Bodywork / Dent / Deformation -




5. Bumper / Back
Paint / Scratch / Line -




6. Wing Stick / Back Right
Missing Part -




7. Vent Glass / Back Right
Missing Part -



8. Side Panel
Bodywork / Dent / Deformation -



9. Door / Back Right
Missing Part -



10. Door / Front Right
Paint / Scratch / Line -













11. Bumper / Front
Bodywork / Breakage / Hole -

Mechanical Condition








Tyres

Presence Anti-Theft Lock Nut 


Dashboard Lights

4WD Light	NA	Dashboard Working	
Engine Light		Oil Pressure Warning Light	
Airbag Warning Light		Brake Warning Light	
Level - Fuel / Battery	45	Transmission Warning Light	
Diesel Particulate Filter Light		ESP Fault/Traction Control Malfunction Light	
Service Light		Steering Fluid Level	NA
ABS Warning Light			


Equipments Test

Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	NA	Dump / Trail / Tail Gate Lift	NA
Main & Spare Keys Functioning		Central Locking	
Electric Windows		Audio Equipment	
Navigation System		AC / Heating System	
Parking Sensors / Cameras Functioning			

Levels

Oil - Condition		Level - Oil	
Coolant Fluid - Condition		Coolant Fluid	
Brakes Fluid			

Engine

Cross Member		Serpentine Belt	
Control Liquid Leak			

Comments

Comments Recharge Clim à prévoir

Hybrid/EV

Charge Port Condition	NA	Charge lead 1 condition /Charge lead 2 condition	NA
Hybrid System Fault	NA		

Test Drive Inspection

Test Drive

Vehicle Starts	✓	Engine functioning	✓
Engine / Aux Belt / Pulley Noise	✓	Steering Noise/Gripping	✓
Smoke Quantity	✓	Transmission	✓
Engine Power	✓	Clutch Functioning	✓
Steering	✓	Brakes Functioning	✓

✓ **No troubles detected, good condition or correct tests, according to vehicle age and mileage**

❗ **Damages or malfunction detected that requires repairs by the buyer**

NA **Not applicable**

☐ **Not tested**

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.