



RENAULT MASTER FOURGON

MASTER FGN TRAC F3300 L2H2 DCI 135

GRAND CONFORT

VIN NO VF1MA000966517672
Registration Number FX497DH



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250826132110
Inspection Date / Place	2025-08-26 / BCA AUNAY	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Not Movable	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	White	Engine Size (cc)	2300
Engine Size	2.3	No of Doors	4
Body Type	Box Wagon	Drive Train	Front
Seat Colour		No of Seats	3
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Other	Imported	
Manufacturer Warrenty			





Equipment


Central locking	Rear parking sensors	Radio	Cruise control
-----------------	----------------------	-------	----------------

Equipment Details


Seat Heating	No	Air Conditioning	Yes
--------------	----	------------------	-----

Cosmetic Damage

22 Dommages




2 Dommages




Component		Damage	Comments
1	Bumper / Front	Bodywork / Breakage / Crack	
2	Hood	Bodywork / Dent / Dent	
3	Fender / Front Right	Bodywork / Dent / Dent	
4	Mirror / Front Right	Bodywork / Breakage / Hole	
5	Panoramic Roof	Bodywork / Dent / Dent	
6	Door / Front Right	Paint / Scratch / Line	
7	B Pillar / Center Right	Bodywork / Dent / Dent	
8	Door / Back Right	Paint / Scratch / Line	
9	Door Side Molding / Front Right	Bodywork / Breakage / Hole	
10	Side Panel / Back Right	Bodywork / Dent / Dent	
11	Bumper / Back	Paint / Scratch / Line	
12	Tailgate Light / Back - Right	Bodywork / Breakage / Hole	
13	Tailgate	Paint / Scratch / Line	

14	Bumper / Back	Paint / Scratch / Line
15	Bumper / Back	Bodywork / Breakage / Hole
16	Tailgate Light / Back - Left	Bodywork / Breakage / Hole
17	Side Panel / Back Left	Paint / Scratch / Line
18	Door Side Molding / Front Left	Bodywork / Breakage / Hole
19	Door / Front Left	Paint / Scratch / Line
20	Fender / Front Left	Paint / Scratch / Line
21	Mirror / Front Left	Bodywork / Breakage / Hole
22	Wiper / Front Left	Bodywork / Breakage / Hole
23	Interior door handle Front left	Interior / Broken
24	Window Switch / Front Left	Interior / Broken



1. Bumper / Front
Bodywork / Breakage / Crack -



2. Hood
Bodywork / Dent / Dent -




3. Fender / Front Right
Bodywork / Dent / Dent -




4. Mirror / Front Right
Bodywork / Breakage / Hole -



5. Panoramic Roof
Bodywork / Dent / Dent -



6. Door / Front Right
Paint / Scratch / Line -



7. B Pillar / Center Right
Bodywork / Dent / Dent -



8. Door / Back Right
Paint / Scratch / Line -



9. Door Side Molding / Front Right
Bodywork / Breakage / Hole -



10. Side Panel / Back Right
Bodywork / Dent / Dent -



11. Bumper / Back
Paint / Scratch / Line -



12. Tailgate Light / Back - Right
Bodywork / Breakage / Hole -



13. Tailgate
Paint / Scratch / Line -



14. Bumper / Back
Paint / Scratch / Line -



15. Bumper / Back
Bodywork / Breakage / Hole -



16. Tailgate Light / Back - Left
Bodywork / Breakage / Hole -



17. Side Panel / Back Left
Paint / Scratch / Line -



18. Door Side Molding / Front Left
Bodywork / Breakage / Hole -




19. Door / Front Left
Paint / Scratch / Line -



20. Fender / Front Left
Paint / Scratch / Line -



21. Mirror / Front Left
Bodywork / Breakage / Hole -



22. Wiper / Front Left
Bodywork / Breakage / Hole -



23. Interior door handle Front left
Interior / Broken -



24. Window Switch / Front Left
Interior / Broken -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.