



Hüsge Gruppe®
Die Gutachter

status report

customer: BCA Autoauktionen GmbH

reference:

vehicle data

Renault Master III Kasten L2H2 HKa 3,5t

Vehicle identification number	VF1MAF4SC56045620	mileage read:	126169 km
First Registration / construction year:	26.08.2016 / 2016	Visit Date / place of birth:	04.06.2025 Hoppegarten
Bodywork:	transporter	Re - import:	unknown
Body type:	van	KBA no. :	3333//AXK
Fuel / emission class:	diesel / € 5	transmission type:	manual transmission
Displacement / power:	2299 ccm / 92 kW (125 PS)	Engine:	front-wheel drive
paint:	GLETSCHERWEISS	Number of previous owners:	-
Doors / seats:	4 / 3	number keys:	1
Next HU / AU:	- / -	cushion type:	substance
Service book available:	yes	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	42938 / 25.09.2020
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	Eg II (veh - letter)	state outside:	4 - moderate
visit condition:	-	condition inside:	3 - Average
state general:	4 - moderate		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	1	yes / 6	42938 / 25.09.2020
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsge GmbH
Ein Unternehmen der Hüsge Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsge
Dipl.- Ing. (FH) Bernd Hüsge

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	steel
1st axis - Left / states .	Anderer	225/65/16/112/110R 3 mm
1st axis - right / states .	Anderer	225/65/16/112/110R 3 mm
2nd axis - Left / states .	Dunlop	225/65/16/112/110T 3 mm
2nd axis - right / states .	Dunlop	225/65/16/112/110T 3 mm
traffic Safety:	not roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• filing Gallery • Anti- lock braking system (ABS) • Power side mirrors . adjustable and heated • brake Assist • Electr . Brakeforce Distribution • Electric windows front • Transmission 6-speed • Body / Structure box high room • Steering column (steering wheel) adjustable in height • Engine 2.3 ltr. - 92 kW dCi diesel KAT • Smokers Package • Rußpartikelfilter • Shift Indicator • Side moldings • Seat cover / upholstery fabric • Height adjustable seats in the cab driver's seat <i>Sitze im Fahrerhaus: Fahrersitz mit Armlehne</i> • immobilizer • Central locking with remote control	• Airbag driver • Drive Front Wheel Drive • Outside temperature display • Rev counter • Electron. Stability Program (ESP) <i>Antriebs-Schlupfregelung (ASR)</i> • Generator 150 A • pollen filter • Fuel tank 105 ltr. • facelift • Wheelbase 3682 mm • Tire Repair • Low emissions Euro 5 emissions standard • Sliding load / passenger compartment right • power steering • Seats in the cab passenger double seat multifunctional • Lashing load floor • Wärmeschutzverglasung • Perm. Total weight of 3.50 t

special Features	
• Airbag Beifahrerseite • Heckscheibe heizbar • Klimaanlage • Radvollabdeckungen • Trittstufe hinten	• Heckflügeltüren mit Verglasung • Holzfussboden im Laderaum • Laderaumtrennwand mit Fenster (vergittert) • Sitze im Fahrerhaus Lendenwirbelstütze Fahrersitz • Verzurrösen im Laderaum seitlich

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	no no
reference:	
Note Road Safe:	Riss Frontscheibe

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	- -
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			examined limited		
air conditioning:			Out of order	lighting system:	
			examined limited		
coupling:			examined limited	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning was not okay for visiting time . **No cooling effect. Further diagnostic required.
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*

damage



	component	Damage	Rep kind
1.	Schlüssel	Missing	Replace
2.	Wartung	Due	Replace
3.	Windshield	Crack	Replace
4.	Motordämmmaterial	Damaged	Replace
5.	Motorraum	Wear and tear	acceptable
6.	Reifen 4x	Not safe for road traffic	Replace
7.	Laderaum	Wear and tear	acceptable
8.	Hecktür li.	Damaged	Replace
9.	Hecktür re.	Damaged	Replace
10.	Taillight left	Damaged	Replace
11.	Door Rear - right	Damaged	Replace
12.	B-pillar center - right	Hole	Refurbish and paint
13.	hood	Damaged	Refurbish and paint
14.	Front bumper	Wear and tear	acceptable
15.	Außenspiegel li.	Damaged	Replace
16.	Sidewall - Rear - Left	Wear and tear	acceptable
17.	Front door - left	Wear and tear	acceptable
18.	Türeinstieg v.l.	Scrape	Paint
19.	Fahrersitz	Burn hole	Replace
20.	air conditioning	Not okay	Carry out a fault diagnosis

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted , and for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right




rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment




service book



Others



2. Wartung



3. Windshield



4. Motordämmmaterial



5. Motorraum



6. Reifen 4x



7. Laderaum



7. Laderaum



7. Laderaum



7. Laderaum



8. Hecktür li.



8. Hecktür li.



9. Hecktür re.



9. Hecktür re.



10. Taillight left



11. Door Rear - right



12. B-pillar center - right



13. hood



13. hood



14. Front bumper




15. Außenspiegel li.




15. Außenspiegel li.



16. Sidewall - Rear - Left



16. Sidewall - Rear - Left



17. Front door - left



18. Türeinstieg v.l.



19. Fahrersitz