


Vehicle details

VIN	VF1R87003 64175044	Brand	RENAULT	Maintenance date	-
Licence Plate	G7-18-ZS	Model	Captur Energy TCe 90 ActieAuto 5d Limited APL	Maintenance mileage	-
Registration date	22/02/2020	Year	2020	Exterior Color	Gold Metallic
Odometer	55 206 km	Engine size	898	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	22/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓


Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Pirelli 205/60/16 Summer 5.5 mm		Pirelli 205/60/16 Summer 5.5 mm	
Bridgestone 205/60/16 Summer 6.0 mm		Bridgestone 205/60/16 Summer 6.0 mm	

Exterior

5



●●●

Part	Door
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

6



●●

Part	Door entry seal
Position	Front left
Damages	Worn out
Severity	-
Repair mode	Replace

7



●●

Part	Step plate
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	For info

8



●●

Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair


9



●●

Part	Bumper
Position	Back right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair


10



●●

Part	Fuel filler flap
Position	Back right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

11



●●

Part	Wing
Position	Back right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

12



●●

Part	Door
Position	Back right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

13



●●

Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

14



●●●

Part	Bonnet
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

Interior damage

1



●●

Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Smart Repair

2



●●

Part	Radio with Sat Nav
Position	-
Damages	Scratched
Severity	-
Repair mode	Replace

3



●●

Part	Fabric seat
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

4



●

Part	Fabric seat
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning