



Hüsges Gruppe®
Die Gutachter

status report

customer: Bank 11, Neuss
contract number: 807114430
reference:

vehicle data

Renault Kadjar Intens

Vehicle identification number	VF1RFE00366887150	mileage read:	62435 km
First Registration / construction year:	26.04.2021 / 2020	Visit Date / place of birth:	12.05.2025 Dorfmark
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	3333//BJU
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	1332 ccm / 103 kW (140 PS)	Engine:	front-wheel drive
paint:	white	Number of previous owners:	Unbekannt
Doors / seats:	5 / 5	number keys:	1
Next HU / AU:	06.2026 / 06.2026	cushion type:	Imitation leather / fabric
Service book available:	yes	Interior Color:	Multicolor
smoking vehicle:	yes	Last service km / on the:	33406 / 13.10.2023
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	1	yes / -	33406 / 13.10.2023

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	All season tires	polished aluminum
1st axis - Left / states .	Goodyear	215/60/R17/96V 5 mm
1st axis - right / states .	Continental	215/60/R17/96H 7 mm
2nd axis - Left / states .	Goodyear	215/60/R17/96H 5 mm
2nd axis - right / states .	Goodyear	215/60/R17/96H 5 mm
traffic Safety:	roadworthy	
spare wheel:	Notrad	
state spare wheel:	Gebraucht	

standard equipment	
• Airbag switched off • Ambient lighting in the center console • Anti -Slip Regulation (ASR) • Audio navigation system R-Link 2 with touch screen color display <i>Freisprecheinrichtung Bluetooth, USB-Anschluss inkl. AUX-IN-Anschluss (Plug & Music)</i> • Mirrors, aspheric, left • Power side mirrors . adjustable and heated • LED turn signals integrated into outside mirrors • Coming home lighting function • Chrome roof rails • Driving Assistance System Hill Start Assist (HSA) • Driver assistance system High beam assistant • Driving assistance system Traffic sign recognition with speed warning display • Window moldings chromed • Speed ??Begrenzeranlage • Transmission 7-speed - dual-clutch transmission • Rearview mirror with auto dip • Body 5-door • Comfort Package • Head airbag system front • Steering wheel (leather) • Steering column (steering wheel) longitudinally adjustable • • Front center armrest • Modularity package <i>Mittelarmlehne hinten mit Getränkehalter, Sitzbezug / Polsterung: Kunstleder / Stoff, Sitz vorn rechts</i>	• Airbag Driver / passenger side • Anti- lock braking system (ABS) • Drive Front Wheel Drive • Audio System 3D Sound by Arkamys • Power side mirrors . anklappbar • Mirrors black high-gloss • Brake Assist • Gray headliner • Electron. Stability Program (ESP) • Driving Assistance System Parking assistance front and rear with rear-view camera <i>Rückfahrkamera</i> • Driver assistance system Lane change warning system • Electric windows front + rear • Luggage compartment cover / shade • Cruise control system (cruise control) • Taillights LED • Isofix admissions for child seat • Automatic climate control with 2-zone automatic . Recirculated air control <i>Innenraumfilter: Geruchs- und Allergenfilter</i> • Head airbag system at the rear • Lumbar support front left seat • Steering column (steering wheel) adjustable in height • Light and rain sensor • Air vents in the rear • model refinement • Motor 1.3 Ltr. - 103 kW TCE • Otto particle filter (GPF)

<i>höhenverstellbar, Sitz vorn rechts umklappbar, Rücksitzbank geteilt/klappbar (1/3-2/3)</i> • • Parking brake electrically • Wheelbase 2646 mm • Tire Pressure Monitoring System • Gearshift / selector lever leather • Front Side Airbags • Controlled power steering electronically • Seat cover / upholstery fabric • Start / Stop system • LED daytime running lights • Underrun protection painted front and rear <i>Unterfahrschutz hinten</i>	• Radio reception digital (DAB) • Smokers Package • Low in emissions according to the Euro 6d emissions standard • Headlamp Full-LED • Side moldings with chrome inserts • Front left seat height adjustment • Sun visors with mirrors (illuminated) • Socket (12V connection) 2.Sitzreihe • Touchscreen (7.0 inches) • Central / Starter System Handsfree Entry \u0026 Drive
--	--

special Features	
• Metallic paint • Spare wheel as an emergency wheel	• Panorama roof fixed (glass)

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.

**Layers of paint thickness
measurement:**

Existing collision damage:

reference:

Out of tolerance

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

found

At the unrepaired vehicle accident damage were observed on visual examination on the body skin .

Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine Demontagearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
oil loss:			examined limited	 examined limited	
air conditioning:			examined limited	lighting system:	
coupling:			unavailable	 examined limited	
engine running:			examined limited	exhaust System:	
transmission:			examined limited	 examined limited	

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen Marderbiss Motorraum Unfallschaden Stoßfänger vorne Schaden und Kosten Erweiterung möglich

damage



component	Damage	Rep kind
1. Roof frame - left	Subsequently painted	acceptable
2. Sidewall - Rear - Left	Subsequently painted	acceptable
3. Rear door - left	Subsequently painted	acceptable
4. A-pillar Front - Left	Subsequently painted	acceptable
5. maintenance	Due	Replace
6. Key with remote control	Missing	Replace
7. Rear bumper	Scrape	Replace
8. Front door - left	Deformed	Refurbish and paint
9. Rim front - left	Damaged	Replace
10. Front bumper	Accident damage	Replace
11. hood	Deformed	Refurbish and paint
12. Rim front - right	Damaged	Replace
13. exterior body	Surface scratch(es)	
14.	Wear and tear	acceptable
15.	Dirty	
16.	Odour	Ozone treatment
17.	Burn hole	Replace
18. flooring	Burn hole	Replace
19.	Damaged	Replace
20.	Damaged	Replace
21. Türeinstieg Vorne - Links	Damaged	Smart repair
22. headlining	Burn hole	Replace
23. Verkleidung A-säule links	Burn hole	Replace
24.	Dirty (animal hair)	
25. Cargo cover	Missing	Replace
26. Türeinstieg Hinten - Rechts	Scratch(es)	Smart repair
27. Türeinstieg Vorne - Rechts	Damaged	Smart repair
28.	Damaged	Replace
29. Ladeluftschlauch		Replace
30.	Damaged	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted , and for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims




rims



engine compartment



service book



Others



Navigation system



1. Roof frame - left



2. Sidewall - Rear - Left




3. Rear door - left



4. A-pillar Front - Left



7. Rear bumper



7. Rear bumper



8. Front door - left



8. Front door - left



9. Rim front - left



9. Rim front - left



10. Front bumper




10. Front bumper



11. hood



11. hood



11. hood



11. hood



12. Rim front - right




12. Rim front - right



13. exterior body



14.



14.



15.



15.



17.



17.



18. flooring



18. flooring



19.



19.



20.




20.




21. Türeinstieg Vorne - Links




21. Türeinstieg Vorne - Links



22. headlining




22. headlining



22. headlining



23. Verkleidung A-säule links




23. Verkleidung A-säule links



24.



24.



24.



24.



25. Cargo cover



26. Türeinstieg Hinten - Rechts



26. Türeinstieg Hinten - Rechts



27. Türeinstieg Vorne - Rechts



27. Türeinstieg Vorne - Rechts



28.



28.



29. Ladeluftschlauch



29. Ladeluftschlauch



30.



30.