



RENAULT CLIO  
Clio E-Tech full hybrid 145 GSR2 Techno

VIN NO VF1RJA00474678522  
Registration Number HC965ZM



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	0	1 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2025-04-11	-

Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250723153511
Inspection Date / Place	2025-07-23 / BCA GARONS	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Not Movable	VAT Type	Qualified - Normal Rate
Fuel Type	Hybrid Electric Vehicle Petrol	Gearbox Type	Automatic
Colour	Black	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	5
Body Type	Hatchback	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		WLTP CO2 Emissions	
Accident Damage	Yes	Euro Emission	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			







Equipment


Rear parking sensors	Alloys wheels
----------------------	---------------

Equipment Details

Seat Heating	No	Air Conditioning	No
--------------	----	------------------	----



## 12 Dommages



5/13 - Report Number P20250723153511

13	Tailgate Upholstery / Back	Interior / Missing
14	Tailgate Upholstery / Back	Interior / Missing
15	Seat / Back Center	Interior / Missing
16	Seat / Front Left	Interior / Missing
17	Seat / Front Right	Interior / Missing
18	Panel Filling / Front Left	Interior / Missing
19	Floor Carpet	Interior / Ripped
20	Tire / Front Left	Tire
21	Rim / Front Left	Out of Bodywork / Scratch
22	Hood	Paint / Scratch / Line
23	Windshield / Front	Glass Break
24	Bumper / Front	Bodywork / Dent / Deformation
25	Bumper / Front	Missing Part
26	Bumper / Front	Bodywork / Breakage / Crack
27	Rim / Front Right	Out of Bodywork / Scratch
28	Tire / Front Right	Tire
29	Side Window / Front Right	Glass Break
30	Panel Filling / Front Right	Interior / Missing
31	Tire / Back Right	Tire
32	Side Window / Front Left	Glass Break






1. Reflector / Back Right  
Missing Part -




2. Back Light / Right  
Missing Part -



3. Tailgate  
Missing Part -



4. Back Light / Left  
Missing Part -



5. Reflector / Back Left  
Missing Part -



6. Outside Sensor / Back  
Bodywork / Breakage / Crack -





7. Tire / Back Left  
Tire -



8. Door / Front Left  
Paint / Scratch / Line -



9. Dashboard / Front  
Interior / Missing -



10. Digital Combined Instrument Panel  
Interior / Missing -



11. Center Console  
Interior / Missing -



12. Tailgate Upholstery / Back  
Interior / Missing -





13. Tailgate Upholstery / Back Interior / Missing -



14. Tailgate Upholstery / Back Interior / Missing -




15. Seat / Back Center Interior / Missing -



16. Seat / Front Left Interior / Missing -



17. Seat / Front Right Interior / Missing -




18. Panel Filling / Front Left Interior / Missing -





19. Floor Carpet  
Interior / Ripped -



20. Tire / Front Left  
Tire -



21. Rim / Front Left  
Out of Bodywork / Scratch -



22. Hood  
Paint / Scratch / Line -



23. Windshield / Front  
Glass Break -




24. Bumper / Front  
Bodywork / Dent / Deformation -





25. Bumper / Front  
Missing Part -



26. Bumper / Front  
Bodywork / Breakage / Crack -



27. Rim / Front Right  
Out of Bodywork / Scratch -



28. Tire / Front Right  
Tire -



29. Side Window / Front Right  
Glass Break -



30. Panel Filling / Front Right  
Interior / Missing -





31. Tire / Back Right  
Tire -




32. Side Window / Front Left  
Glass Break -



Mechanical Condition


Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

*The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.*