


**Vehicle details**

VIN	VF1RJB007 66055145	Brand	RENAULT	Maintenance date	-
Licence Plate	K5-39-DH	Model	Captur TCe 100 Zen 5d APL	Maintenance mileage	-
Registration date	27/11/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	81 457 km	Engine size	999	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

**Inspection Details**

Inspection date	21/11/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------




Generic equipment	
Manual air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓
Led lighting	✓

Removable element	
Spare wheel kit	✓

Technical Document	
User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

**Tyres**



**Exterior**

<p>2</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door	Position	Front left	Damages	Dented	Severity	-	Repair mode	Repair	<p>3</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Wing moulding</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Broken</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Wing moulding	Position	Back left	Damages	Broken	Severity	-	Repair mode	Replace
Part	Door																						
Position	Front left																						
Damages	Dented																						
Severity	-																						
Repair mode	Repair																						
Part	Wing moulding																						
Position	Back left																						
Damages	Broken																						
Severity	-																						
Repair mode	Replace																						
<p>4</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) &gt; 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Bonnet	Position	-	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair	<p>5</p>  <p>● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Roof	Position	-	Damages	Dented	Severity	-	Repair mode	Repair
Part	Bonnet																						
Position	-																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						
Part	Roof																						
Position	-																						
Damages	Dented																						
Severity	-																						
Repair mode	Repair																						

**Interior damage**

<p>1</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </table>	Part	Interior cleaning	Position	Front left	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning
Part	Interior cleaning										
Position	Front left										
Damages	Stained/dirty										
Severity	-										
Repair mode	Cleaning										