



PEUGEOT 5008

5008 1.6 HDi 115ch FAP BVM6 Style 5pl

VIN NO VF30E9HD8FS038978

Registration Number GM081PZ



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCA Auto Encheres	Report Number	P20251009163448
Inspection Date / Place	2025-10-09 / BCA BETHUNE	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Grey	Engine Size (cc)	1560
Engine Size	1.6	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	7
Charging Cables		NEDC CO2 Rating (q/km)	124
Engine Rating CV	6	Metalic Colour	Yes
Accident Damage	No	Euro Emission	

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			



Equipment


Central locking	Radio	Alloys wheels	Front fog lamps
Roof rails	Electrically folding wing mirrors	Rear parking sensors	Cruise control
Power assisted steering	Satellite navigation		

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Fixed Panoramic		

Cosmetic Damage

12 Dommages



2 Dommages



Component		Damage	Comments
1	Floor Carpet	Interior / Holed	
2	Door / Back Right	Paint / Scratch / Line	
3	Floor Carpet	Interior / Dirty	
4	Door / Front Right	Paint / Scratch / Scuff	
5	Side Panel / Back Right	Paint / Scratch / Scuff	
6	Bumper / Front	Paint / Scratch / Scuff	
7	Bumper / Back	Paint / Scratch / Scuff	
8	Bumper / Front	Paint / Scratch / Scuff	
9	Rim / Front Left	Out of Bodywork / Scratch	
10	Bumper / Back	Paint / Scratch / Scuff	
11	Rim / Back Right	Out of Bodywork / Scratch	
12	Fender / Front Right	Paint / Scratch / Line	

13	Rim / Back Left	Out of Bodywork / Scratch	
14	Rim / Front Right	Out of Bodywork / Scratch	À plat



1. Floor Carpet
Interior / Holed -



2. Door / Back Right
Paint / Scratch / Line -



3. Floor Carpet
Interior / Dirty -



4. Door / Front Right
Paint / Scratch / Scuff -



5. Side Panel / Back Right
Paint / Scratch / Scuff -



6. Bumper / Front
Paint / Scratch / Scuff -



7. Bumper / Back
Paint / Scratch / Scuff -



8. Bumper / Front
Paint / Scratch / Scuff -



9. Rim / Front Left
Out of Bodywork / Scratch -



10. Bumper / Back
Paint / Scratch / Scuff -



11. Rim / Back Right
Out of Bodywork / Scratch -



12. Fender / Front Right
Paint / Scratch / Line -




13. Rim / Back Left
Out of Bodywork / Scratch -



14. Rim / Front Right
Out of Bodywork / Scratch -
À plat

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.