



PEUGEOT 407 COUPE

407 Coupé 2.7 HDi 24v FAP Sport Pack A

VIN NO VF36JUHZJ21334949
Registration Number CM540SM



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCA Auto Encheres	Report Number	P20250701163139
Inspection Date / Place	2025-07-01 / BCA BETHUNE	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Automatic
Colour	Grey	Engine Size (cc)	2720
Engine Size	2.7	No of Doors	2
Body Type	Coupe	Drive Train	Front
Seat Colour		No of Seats	4
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	226

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			



Equipment


Central locking	Radio	Alloys wheels	Cruise control
Power assisted steering	Electrically folding wing mirrors	Rear parking sensors	Stability control
Front fog lamps			

Equipment Details


Seat Heating	No	Air Conditioning	No
Sunroof Type	Tilt/Slide Steel		

Cosmetic Damage

20 Dommages



3 Dommages



Component		Damage	Comments
1	Floor Carpet	Interior / Dirty	
2	Backrest Cover / Front Left	Interior / Holed	
3	Roof Upholstery	Interior / Loose	
4	Corner Bumper / Front Right	Paint / Scratch / Scuff	
5	Bumper / Front	Paint / Scratch / Scuff	
6	Corner Bumper / Front Left	Paint / Scratch / Scuff	
7	Blade/spoiler / Front	Bodywork / Breakage	
8	Fender / Front Left	Paint / Scratch / Line	
9	Rim / Front Left	Out of Bodywork / Scratch	
10	Door / Front Left	Paint / Scratch / Line	
11	Rim / Back Left	Out of Bodywork / Scratch	
12	Corner Bumper / Back Left	Paint / Scratch / Scuff	
13	Bumper / Back	Paint / Scratch / Scuff	

14	Tailgate	Paint / Chipping
15	Tailgate	Paint / Scratch / Line
16	Corner Bumper / Back Right	Paint / Scratch / Scuff
17	Corner Bumper / Back Right	Bodywork / Breakage
18	Side Panel / Back Right	Paint / Scratch / Line
19	Rim / Back Right	Out of Bodywork / Scratch
20	Side Panel / Back Right	Paint / Scratch / Line
21	Mirror / Front Right	Paint / Scratch / Scuff
22	Fender / Front Right	Paint / Scratch / Line
23	Rim / Front Right	Out of Bodywork / Scratch



1. Floor Carpet
Interior / Dirty -




2. Backrest Cover / Front Left
Interior / Holed -



3. Roof Upholstery
Interior / Loose -



4. Corner Bumper / Front Right
Paint / Scratch / Scuff -



5. Bumper / Front
Paint / Scratch / Scuff -



6. Corner Bumper / Front Left
Paint / Scratch / Scuff -



7. Blade/spoiler / Front
Bodywork / Breakage -



8. Fender / Front Left
Paint / Scratch / Line -




12. Corner Bumper / Back Left
Paint / Scratch / Scuff -



13. Bumper / Back
Paint / Scratch / Scuff -



14. Tailgate
Paint / Chipping -



15. Tailgate
Paint / Scratch / Line -



16. Corner Bumper / Back Right
Paint / Scratch / Scuff -



17. Corner Bumper / Back Right
Bodywork / Breakage -



18. Side Panel / Back Right
Paint / Scratch / Line -



19. Rim / Back Right
Out of Bodywork / Scratch -



20. Side Panel / Back Right
Paint / Scratch / Line -



21. Mirror / Front Right
Paint / Scratch / Scuff -



22. Fender / Front Right
Paint / Scratch / Line -



23. Rim / Front Right
Out of Bodywork / Scratch -

Mechanical Condition


Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.