



PEUGEOT 308 SW: 1YMN516			
Vinnumber:	VF3LCYHYPLS239560	Versionname:	1.5 BlueHdi 100 DPf S&S Active Pack
First Registrationdate:	20/10/2020	Fiscalpower:	
Expertise Mileage:	142813	Power Kw:	75
Bodytype:		Body colour	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1116
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Options			
Number of keys total	2	Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Tyres			
Summer tyres:	205/55/16/92 H		
	Fr.L.	Continental: 5 mm	Fr.R. Michelin: 5 mm
	Re.L.	Continental: 5 mm	Re.R. Michelin: 5 mm
Tyre profile depth FL			5.0
Tyre profile depth FR			5.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			205/55 R 16 92 H
Tyre size FR			205/55 R 16 92 H
Tyre size RL			205/55 R 16 92 H
Tyre size RR			205/55 R 16 92 H
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			256
Tyre make FR			261
Tyre make RL			256
Tyre make RR			261
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			3020,77
Floor covering FL, Damaged, Smart repair			113,74



Seat cover FL, Burned, Replace 354,12



Bumper F, Scratch(es), Repair and paint (complete) 289,07



Bonnet, Stone chip(s), Acceptable 0,00




Wing RL, Dent(s), Acceptable 0,00



Alloy rim RL, Scratch(es), Repair and paint (complete) 129,66



Door RL, Dent(s), Acceptable 0,00




Door FL, Dent(s) and scratch(es), Repair and paint (complete) 434,50



Alloy rim FL, Scratch(es), Repair and paint (complete) 129,66



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete) 423,79



Step L, Dent(s) and scratch(es), Repair and paint (complete)	157,71
--	--------



Luggage compartment cover, Damaged, Smart repair	113,74
--	--------




Bumper R, Scratch(es), Repair and paint (complete)	289,07
--	--------




Rear window, Scratch(es), Replace	326,39
-----------------------------------	--------




Alloy rim FR, Scratch(es), Repair and paint (complete)	129,66
--	--------




Door FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Door RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim RR, Scratch(es), Repair and paint (complete)	129,66
--	--------



Wing RR, Bad repair, Check	0,00
----------------------------	------



Roof, Scratch(es), Acceptable	0,00
-------------------------------	------

