



Hüsge Gruppe®
Die Gutachter

status report

customer: Bank 11, Neuss
contract number:
reference:

vehicle data

Peugeot 308 SW Style

Vehicle identification number	VF3LRHNSTKS240512	mileage read:	86875 km
First Registration / construction year:	10.07.2019 / 2019	Visit Date / place of birth:	25.09.2025 Riedstadt-Goddelau
Bodywork:	cars	Re - import:	unknown
Body type:	hatchback	KBA no. :	3003//ATM
Fuel / emission class:	gasoline / € 6	transmission type:	manual transmission
Displacement / power:	1199 ccm / 96 kW (131 PS)	Engine:	front-wheel drive
paint:	LACKIERUNG PLATINIUM-GRAU/METALLIC-LACKIERUNG	Number of previous owners:	2
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	yes	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	26489 / 20.04.2021
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	3 - Average
documents:		condition inside:	3 - Average
visit condition:	-		
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	yes / -	26489 / 20.04.2021
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsge GmbH
Ein Unternehmen der Hüsge Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsge
Dipl.- Ing. (FH) Bernd Hüsge

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Michelin	225/45/R17/91W 4 mm
1st axis - right / states .	Michelin	225/45/R17/91W 4 mm
2nd axis - Left / states .	Michelin	225/45/R17/91W 4 mm
2nd axis - right / states .	Michelin	225/45/R17/91W 4 mm
traffic Safety:	roadworthy	
spare wheel:	Notrad	
state spare wheel:	Vollwertig	

standard equipment	
• 3rd brake light • Airbag Driver / passenger side • Display engine oil level • Audio system WIP Sound (Radio) <i>Audiobedienung am Lenkrad, Audiosystem mit 6 Lautsprecher, Freisprecheinrichtung Bluetooth, USB-Schnittstelle</i> • Body color door mirrors • board computer • Braking force regulator • Rev counter • Electr . Brakeforce Distribution • Driving Assistance System hill start assist • Window frame with chrome surround • Cruise control system (cruise control) incl. Speed ??Begrenzeranlage • belt force limiters • Handbrake grip Leather • Glove compartment with cooling function • heated rear window • dust and pollen filter • Body 5-door • Parental control electrically • Comfort Package <i>Mittelarmlehne hinten, Durchladeeinrichtung (Mittelarmlehne hinten)</i> • Rear headrests (3- fold) • black grille • Steering wheel (leather) • Steering column (steering wheel) adjustable • Front center armrest	• Airbag switched off • Anti- lock braking system (ABS) • • Autom. Accompaniment function of the illumination • Indicator integrated into mirrors • brake Assist • Roof rails (aluminum) • rear Parking Sensors <i>Einparkhilfe akustisch</i> • Electron. Stability Program (ESP, Bosch) <i>Antischlupfregelung (ASR)</i> • Electric windows front + rear with comfort control <i>Fensterheber elektr. mit Einklemmschutz</i> • Windscreen laminated glass • Transmission 6-speed • Belt tensioners • Illuminated glove compartment • LED Taillights • rear window wiper • Isofix admissions for child seat • Map pocket on front seats • Climate control, separately adjustable driver's / passenger's side • Head airbag system • Adjustable front head restraints • Lumbar support front • Steering wheel with multifunction • Headlamp leveling • model refinement • Multifunction display with touchscreen color display • Tire Pressure Monitoring System

• Engine 1.2 ltr. - 96 kW 12V e - THP • Panorama roof (glass) • backup camera • • Shift Indicator • Side Impact Protection • Visibility Package <i>Einschaltautomatik für Fahrlicht, Scheibenwischer mit Regensensor, Innenspiegel mit Abblendautomatik</i> • Front right seat height adjustment • Start / Stop system • Body color bumpers • Exterior door handles body color • Warning system for safety • WIP Bluetooth <i>Freisprecheinrichtung Bluetooth</i>	• Rear seat folding 1 / 3-2 / 3 • Gearshift / selector lever leather • Side airbags (dual) • Controlled power steering electronically • Front left seat height adjustment • Seat cover / upholstery fabric • 12V socket center console • LED daytime running lights • tinted glazing <i>Heckscheibe getönt, Seitenscheiben hinten und Heckscheibe getönt</i> • Immobilizer with transponder • Central locking with remote control
---	--

special Features	
• City Package Plus <i>Mobile Online Dienste Mirror Screen, Rückfahrkamera mit 180° Umgebungsansicht</i> • Metallic paint • <i>CD-Laufwerk in der Mittelkonsole</i> • style pack <i>Sitzheizung vorn, Parkbremse elektrisch, LM-Felgen, Reserverad als Notrad</i>	• Luggage compartment partition (net) • Navigation System Plus •

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable Wartung Fällig
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross: Expertly repaired

On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.

Layers of paint thickness measurement:

Out of tolerance

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit

Alternator / Generator:	✓ examined limited	Battery / accumulator:	✓ in order
oil loss:	✓ examined limited		
air conditioning:	✓ examined limited	lighting system:	✓ examined limited
coupling:	✓ examined limited	exhaust System:	✓ examined limited
engine running:	✓ examined limited	shock absorber:	✓ examined limited
transmission:	✓ examined limited		

Performed testing technology

Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*

damage



component	Damage	Rep kind
1. Front fender - left	Subsequently painted	acceptable
2. Rim front - left	Damaged	Replace
3. Rim rear - left	Damaged	Replace
4. Rim rear - right	Damaged	Replace
5. Rim front - right	Damaged	Replace
6.	Dirty	
7. steering wheel	Damaged	Smart repair
8. maintenance	Due	Replace
9. Cargo cover	Damaged	Smart repair
10. Front bumper	Scrape	Paint
11. hood	Wear and tear	acceptable
12. Windshield	Wear and tear	acceptable
13. Front fender - left	Deformed	Refurbish and paint
14. Front door - left	Scratch(es)	Paint
15. Rear door - left	Scratch(es)	Paint
16. Sitzreihe Hinten	Dirty	
17. Sidewall - Rear - Left	Deformed	Refurbish and paint
18. headlining	Dirty	
19. tailgate trim	Wear and tear	acceptable
20. Sidewall - Rear - right	Deformed	Refurbish and paint
21. Door Rear - right	Damaged	Refurbish and paint
22. Front door - right	Scratch(es)	Paint
23. Türeinstieg Vorne - Rechts	Scratch(es)	Paint

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



page: 10 from 17



2. Rim front - left



2. Rim front - left



3. Rim rear - left



3. Rim rear - left



4. Rim rear - right



4. Rim rear - right



5. Rim front - right



5. Rim front - right



6.



7. steering wheel



9. Cargo cover



9. Cargo cover



10. Front bumper



11. hood




12. Windshield



12. Windshield



12. Windshield




13. Front fender - left




14. Front door - left



14. Front door - left




15. Rear door - left



15. Rear door - left



15. Rear door - left



16. Sitzreihe Hinten



16. Sitzreihe Hinten



17. Sidewall - Rear - Left



17. Sidewall - Rear - Left



17. Sidewall - Rear - Left



18. headlining



19. tailgate trim



20. Sidewall - Rear - right



20. Sidewall - Rear - right



21. Door Rear - right



21. Door Rear - right



21. Door Rear - right



22. Front door - right



22. Front door - right



23. Türeinstieg Vorne - Rechts



23. Türeinstieg Vorne - Rechts



23. Türeinstieg Vorne - Rechts