

PEUGEOT 3008 3008 THP 165 EAT6 Stop & Start



VIN NO VF3M45GZWHS278570 Registration Number ZWHS278570

MOT Date

Number of Keys

Odometer Reading

2026-11-01

23: 1

P2

119127 km

Last Service

Last Service Mileage

Number of Owners

First Registration Date

Country First Registered

2022-08-08

76041

2017-11-17

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250331081644
Inspection Date / Place	2025-03-31 / HARTMANN Compound-Professionals GmbH Dorfmark	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Red	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	136
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Incomplete	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			

















































Equipment

Tinted Glass	USB Socket	Anti-lock braking	Digitaldashboard
Remote adjusting wing mirrors	Reversing Camera	Satellite navigation	Central locking
Electrictailgate	Radio	Trip Computer	Airbag Status
Bluetooth telephone interface	e Front parking sensors	Remote central locking	Roof rails
Stability control	Electrically folding wing mirrors	Leather steering wheel	Rear parking sensors

Equipment Details

Left Front Tyre Depth

Right Rear Tyre Depth

5


Air Conditioning	Dual Zone Climate Control	Seat Heating	Front
Wheels & Tyres			
Extra Wheel - 1 Tyre Depth	3	Extra Wheel - 2 Tyre Depth	3
Extra Wheel - 3 Tyre Depth	2	Extra Wheel - 4 Tyre Depth	2

Right Front Tyre Depth

Left Rear Tyre Depth

5

Cosmetic Damage





1. Seat Cushion / Front Left Interior / Worn - out -

2. Panel Filling / Front Left Interior / Worn - out -



3. Panel Filling / Back Left Interior / Scraped -

4. Door / Back Right Paint / Scratch / Line -



5. Bumper / Back Paint / Scratch / Scuff -

6. Corner Bumper / Back Left Paint / Scratch / Line -




7. Side Panel / Back Left Paint / Scratch / Scuff -

8. Side Panel / Back Left Paint / Scratch / Scuff -




9. Door / Back Left Paint / Scratch / Scuff -

10. Door / Front Left Paint / Scratch / Scuff -



11. Door Handle / Front Left Paint / Poor Previous Repair -

12. Hood Bodywork / Dent / Dent -




13. Hood Paint / Poor Previous Repair -

Mechanical Condition

Control Lights			
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	•
Airbag Warning Light	•	Oil Pressure Warning Light	•
Brake Warning Light	•	Power Steering Warning Light	⊘
Alternator / Battery	•	No Dashboard Lights	⊘
Display Defect	⊘	Service Light	•
Tire Pressure Monitoring System	⊘		
Engine			
Engine Status / EML	•	Engine Starts	•
Engine Leak Visible	•		
Gearbox			
Gear Box	•		
Equipments Test			
Central Locking	•	Main & Spare Keys Functioning	⊘
Electric Windows	•	Navigation System	•
Audio Equipment	•	AC / Heating System	•
Other Equipments	•		
Levels			
Brakes Fluid	•	Coolant Fluid	②
Hybrid/EV			

Test Drive Inspection



Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

User Guide