

PEUGEOT 3008 3008 THP 165 EAT6 Stop & Start



VIN NO VF3M45GZWHS278570 Registration Number ZWHS278570

MOT Date

Number of Keys

Odometer Reading

2026-11-01

23: 1

P2

119127 km

Last Service

Last Service Mileage

Number of Owners

First Registration Date

Country First Registered

2022-08-08

76041

2017-11-17

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250331081644
Inspection Date / Place	2025-03-31 / HARTMANN Compound-Professionals GmbH Dorfmark	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Red	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	136
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Incomplete	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			

















































Equipment

Tinted Glass	USB Socket	Anti-lock braking	Digitaldashboard
Remote adjusting wing mirrors	Reversing Camera	Satellite navigation	Central locking
Electrictailgate	Radio	Trip Computer	Airbag Status
Bluetooth telephone interface	e Front parking sensors	Remote central locking	Roof rails
Stability control	Electrically folding wing mirrors	Leather steering wheel	Rear parking sensors


Equipment Details

Air Conditioning	Dual Zone Climate Control	Seat Heating	Front

Wheels & Tyres

Left Front Tyre Depth	6	Right Front Tyre Depth	6
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5
Extra Wheel - 1 Tyre Depth	3	Extra Wheel - 2 Tyre Depth	3
Extra Wheel - 3 Tyre Depth	2	Extra Wheel - 4 Tyre Depth	2

Cosmetic Damage



6/11 - Report Number P20250331081644



1. Seat Cushion / Front Left Interior / Worn - out -

2. Panel Filling / Front Left Interior / Worn - out -



3. Panel Filling / Back Left Interior / Scraped -

4. Door / Back Right Paint / Scratch / Line -



5. Bumper / Back Paint / Scratch / Scuff -

6. Corner Bumper / Back Left Paint / Scratch / Line -




7. Side Panel / Back Left Paint / Scratch / Scuff -

8. Side Panel / Back Left Paint / Scratch / Scuff -




9. Door / Back Left Paint / Scratch / Scuff -

10. Door / Front Left Paint / Scratch / Scuff -



11. Door Handle / Front Left Paint / Poor Previous Repair -

12. Hood Bodywork / Dent / Dent -



13. Hood Paint / Poor Previous Repair -

Mechanical Condition

Control Lights			
Display Defect	⊘	Service Light	•
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	⊘
Airbag Warning Light	•	Oil Pressure Warning Light	⊘
Brake Warning Light	•	Power Steering Warning Light	•
Alternator / Battery	•	No Dashboard Lights	•
Tire Pressure Monitoring System	•		
Equipments Test			
Central Locking	•	Main & Spare Keys Functioning	⊘
Electric Windows	•	Navigation System	⊘
Audio Equipment	⊘	AC / Heating System	•
Other Equipments	⊘		
Engine			
Engine Status / EML	•	Engine Leak Visible	⊘
Engine Starts	⊘		
Gearbox			
Gear Box	•		
Levels			
Brakes Fluid	•	Coolant Fluid	⊘
Hybrid/EV			
Hybrid System Fault	•		

Test Drive Inspection

description.

