

Vehicle details

VIN	VF3MRHNSU MS189917	Brand	PEUGEOT	Maintenance date	-
Licence Plate	N5-96-FR	Model	3008 Blue Lease Active PureTech 130 S;S EAT8 5d	Maintenance mileage	-
Registration date	05/10/2021	Year	2021	Exterior Color	Blue Metallic
Odometer	168 170 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	05/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓


Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres



Exterior

1



Part

Bumper

Position

Back

Damages

Scratched

Severity

-

Repair mode

Repair

2



Part

Bumper

Position

Back left

Damages

Chemical deposit

Severity

-

Repair mode

Lumpsum repair

3



Part

Rear door strip

Position

Back

Damages

Scratched

Severity

-

Repair mode

Repair

4



Part

Rear windscreen

Position

Damages

Scratched

Severity

-

Repair mode

For info

5



Part

Door

Position

Back right

Damages

Dent & Chips

Severity

-

Repair mode

Repair

7



Part

Roof

Position

-

Damages

Chemical deposit

Severity

-

Repair mode

Lumpsum repair

8



Part

Door

Position

Front right

Damages

Dented

Severity

Number > 2

Repair mode

Smart Repair

9



Part

Door moulding

Position

Front right

Damages

Scratched

Severity

-

Repair mode

Repair

10



Part

Exterior door mirror shell

Position

Right

Damages

Chemical deposit

Severity

-

Repair mode

Lumpsum repair

11



Part

Bumper

Position

Front

Damages

Scratched

Severity

-

Repair mode

Repair

12



Part

Door

Position

Front left

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

13



Part

Door

Position

Back left

Damages

Dented

Severity

Number > 2

Repair mode

Smart Repair

15



Part

Step plate

Position

Back left

Damages

Scratched

Severity

-

Repair mode

For info

Interior damage

6



Part	Fabric seat
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

14



Part	Fabric seat
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

16



Part	Interior tailgate lining
Position	-
Damages	Scratched
Severity	-
Repair mode	Smart Repair