



Hüsge Gruppe®
Die Gutachter

status report

customer:	Bank 11, Neuss
contract number:	1066482330-INSO
reference:	

vehicle data			
Peugeot Expert Kombi L2			
Vehicle identification number	VF3VAYHVKJZ116434	mileage read:	210591 km
First Registration / construction year:	10.04.2019 / 2018	Visit Date / place of birth:	07.03.2025 Neuss
Bodywork:	transporter	Re - import:	unknown
Body type:	other	KBA no. :	3003//AZY
Fuel / emission class:	diesel / € 6	transmission type:	manual transmission
Displacement / power:	1499 ccm / 88 kW (120 PS)	Engine:	front-wheel drive
paint:	LACK WEISS	Number of previous owners:	2
	BANQUISE/TYP		
	AUSSENVERKLEIDUNG		
	SPIEGEL FLACH		
	STANDARD		
Doors / seats:	4 / 8	number keys:	1
Next HU / AU:	- / -	cushion type:	substance
Service book available:	yes	Interior Color:	gray
smoking vehicle:	no	Last service km / on the:	177413 / 07.03.2023
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	3 - Average
documents:		condition inside:	3 - Average
visit condition:	-		
state general:	3 - Average		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	1	yes / -	177413 / 07.03.2023
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

Hüsge GmbH
Ein Unternehmen der Hüsge Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsge
Dipl.- Ing. (FH) Bernd Hüsge

 **available**

 **not available**

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



mounted tires		
Tyre / wheel type:	All season tires	steel
1st axis - Left / states .	Anderer	215/65/16/109/107R 7.7 mm
1st axis - right / states .	Anderer	215/65/16/109/107R 7.7 mm
2nd axis - Left / states .	Anderer	215/65/16/109/107R 9.1 mm
2nd axis - right / states .	Anderer	215/65/16/109/107R 9.1 mm
traffic Safety:	roadworthy	
spare wheel:	vorhanden	
state spare wheel:	Vollwertig	

standard equipment	
• Airbag Driver / passenger side • Drive Front Wheel Drive • board computer • Electron. Stability Program (ESP, Bosch) <i>Antischlupfregelung (ASR)</i> • Electric windows front <i>Fensterheber elektrisch vorn links, Fensterheber elektrisch vorn rechts</i> • Transmission 6-speed • air Conditioning • 1.5 Ltr Motor. - 88 kW Blue-HDI FAP • Tire Pressure Monitoring System • • SCR (AdBlue technology) • Electric Power Steering • • Steel rims 7x17 • Daytime running lights • Central locking with remote control	• Anti- lock braking system (ABS) • Passenger single seat • roof antenna • Driving Assistance System hill start assist • Cruise control system (cruise control) incl. Speed ??Begrenzeranlage • Body / Construction Estate • Head airbag system • Wheelbase 3275 mm • Rußpartikelfilter • Sliding door right with window <i>Schiebetür rechts</i> • Front Side Airbags • Front left seat height adjustment • <i>Sitzbezug / Polsterung: Stoff, Rücksitzbank (2.Reihe) Dreiersitzbank, klappbar</i> • Start / Stop system • Automatic door unlocking (in the event of an accident)

special Features	
• Audio navigation system NAC 3-D, DAB with color display <i>Radioempfang digital (DAB), Multifunktionsanzeige mit Touchscreen-Farbdisplay</i> • Electrical package <i>Außenspiegel elektr. verstell- und heizbar, Fensterheber elektrisch vorn, Fensterheber elektrisch vorn links, Fensterheber elektrisch vorn rechts, Steckdose (12V-Anschluß) im Koffer-/Laderaum</i>	• rear Parking Sensors <i>Einparkhilfe akustisch</i> • Rear wing doors with glazing (opening angle 180 degrees) <i>Heckscheibenwischer, Heckscheibe heizbar, Heckflügeltüren mit Verglasung</i> • • Sliding window loading / passenger compartment at the front (2nd row of seats)

- Fog Lights
- Spare wheel

Seitenscheiben hinten und Heckscheibe dunkel getönt

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	yes yes
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit

Alternator / Generator:	✓ in order	Battery / accumulator:	✓ in order
oil loss:	✓ in order		
air conditioning:	✗ not possible	lighting system:	✓ in order
coupling:	✓ in order	exhaust System:	✓ in order
engine running:	✓ in order	shock absorber:	✗ not checked
transmission:	✓ in order		

Performed testing technology

Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle was inspected during the visit to an oil leak .
air conditioning:	The air conditioning could not be checked during the inspection . **Due to weather conditions not possible examination.
lighting system:	The lighting system was to tour date in order.
coupling:	The coupling was examined during the test drive / pull test .
exhaust System:	The exhaust system has been tested and apparently acoustically during the tour .
engine running:	A field test of the engine was performed.
shock absorber:	The shocks were not examined during the inspection .
transmission:	The transmission was examined during the test drive / pull test .
reference:	*Nutzfahrzeug typische Gebrauchsspuren und Beschädigungen.

damage



component	Damage	Rep kind
1. Sidewall - Rear - Left		Smart repair
2. Sliding door - right	Scrape	Refurbish and paint
3. Polster Fahrgastraum	Formation of mould	
4. maintenance	Due	Replace
5. key	Missing	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others




Navigation system



1. Sidewall - Rear - Left




1. Sidewall - Rear - Left



1. Sidewall - Rear - Left



1. Sidewall - Rear - Left



2. Sliding door - right



2. Sliding door - right



2. Sliding door - right



3. Polster Fahrgastraum



3. Polster Fahrgastraum




3. Polster Fahrgastraum



3. Polster Fahrgastraum



3. Polster Fahrgastraum



3. Polster Fahrgastraum



3. Polster Fahrgastraum