



PEUGEOT BOXER (30)

BOXER CC 435 L4 BLUEHDI 130 S&S PRO SR

VIN NO VF3YD2MAU12H02574
Registration Number FC850LC



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCAauto Encheres	Report Number	P20251014091745
Inspection Date / Place	2025-10-14 / BCA MONTMARTIN	Cosmetic Grade	9

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	White	Engine Size (cc)	1997
Engine Size	2.0	No of Doors	2
Body Type	Platform Cab	Drive Train	Front
Seat Colour		No of Seats	3
Charging Cables		NEDC CO2 Rating (q/km)	169
Accident Damage	No	Euro Emission	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			





Equipment


Central locking	Electric Tailgate	Cruise control	Power assisted steering
Radio	Stability control	Front fog lamps	Satellite navigation

Equipment Details


Seat Heating	No	Air Conditioning	Yes
--------------	----	------------------	-----

Cosmetic Damage

10 Dommages



2 Dommages



Component		Damage	Comments
1	Roof Upholstery	Interior / Stained	
2	Rim / Back Left	Out of Bodywork / Scratch	
3	Rim / Back Right	Out of Bodywork / Scratch	
4	Rim / Front Left	Out of Bodywork / Scratch	
5	Seat Cushion / Front Left	Interior / Stained	
6	Rim / Front Right	Out of Bodywork / Scratch	
7	Mirror / Front Right	Bodywork / Breakage / Hole	
8	Side Panel / Back Left	Bodywork / Breakage	
9	Side Panel / Back Right	Bodywork / Dent / Deformation	
10	Mirror / Front Left	Bodywork / Breakage	
11	Fender / Front Right	Bodywork / Dent / Deformation	
12	Side Panel / Back Right	Bodywork / Breakage	



1. Roof Upholstery
Interior / Stained -



2. Rim / Back Left
Out of Bodywork / Scratch -



3. Rim / Back Right
Out of Bodywork / Scratch -



4. Rim / Front Left
Out of Bodywork / Scratch -



5. Seat Cushion / Front Left
Interior / Stained -



6. Rim / Front Right
Out of Bodywork / Scratch -



7. Mirror / Front Right
Bodywork / Breakage / Hole -



8. Side Panel / Back Left
Bodywork / Breakage -



9. Side Panel / Back Right
Bodywork / Dent / Deformation -



10. Mirror / Front Left
Bodywork / Breakage -




11. Fender / Front Right
Bodywork / Dent / Deformation -



12. Side Panel / Back Right
Bodywork / Breakage -

Mechanical Condition


Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.