



CITROEN C4 Cactus 2014 Diesel

C4 Cactus 1.6 e-hdi Shine 92cv etg6

VIN NO VF70B9HPGEE546069

Registration Number EX882WJ



MOT Date

2025-01-20

Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date

2015-01-20

Odometer Reading

148961 km

Country First Registered

Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251010092724
Inspection Date / Place	2025-10-10 / BCA Lodi	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Sequential
Colour	Black	Engine Size (cc)	1560
Engine Size	1.6	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour	Brown	No of Seats	5
Seat Covering Name		Seat Covering	Leather
Charging Cables		NEDC CO2 Rating (q/km)	92

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment

Central locking	Rear parking sensors	Digital Radio	Sunroof
Parcel Shef	Remote central locking	Tyre Mobility Kit	Power assisted steering
Alloys wheels	Satellite navigation	Volante multifuncion	Remote adjusting wing mirrors
Trip Computer	Stability control		


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Four Seasons	
	HANKOOK	205/50//R17 - 93W / 2 mm
	HANKOOK	205/50//R17 - 93W / 2 mm
	HANKOOK	205/50//R17 - 93W / 2 mm
	HANKOOK	205/50//R17 - 93W / 2 mm

Cosmetic Damage

19 Danni



7 Danni




Component		Damage	Comments
1	Steering Wheel / Front	Interior / Worn - out	
2	Windshield / Front	Glass Break / Impact	
3	Hood	Bodywork / Dent / Hail Area	
4	Panel Filling / Front Left	Interior / Scratched	
5	Bumper / Front	Paint / Chipping	
6	Bumper / Back	Paint / Scratch / Line	
7	Roof	Bodywork / Dent / Hail Area	
8	Rim / Front Left	Out of Bodywork / Scratch	
9	Aeration Grid / Front Center	Interior / Broken	
10	Fender / Back Right	Bodywork / Poor Previous Repair	
11	Front Light / Front Right	Bodywork / Breakage	
12	Door / Back Right	Paint / Scratch / Line	

13	Rim / Back Left	Out of Bodywork / Scratch
14	Front Light / Front Left	Bodywork / Breakage
15	Rim / Back Right	Out of Bodywork / Scratch
16	Door / Front Right	Paint / Scratch / Line
17	Fender / Front Left	Bodywork / Dent / Hail Area
18	Dashboard / Front	Interior / Non - compliant
19	Rim / Front Right	Out of Bodywork / Scratch
20	Door / Front Left	Paint / Scratch / Line
21	Door / Back Left	Bodywork / Poor Previous Repair
22	Pillar / Front Left	Bodywork / Dent / Hail Area
23	Floor Carpet	Interior / Ripped
24	Seat / Front Left	Interior / Ripped
25	Center Console	Interior / Worn - out
26	Pillar / Front Right	Bodywork / Dent / Hail Area




1. Steering Wheel / Front Interior / Worn - out -



2. Windshield / Front Glass Break / Impact -



3. Hood Bodywork / Dent / Hail Area -



4. Panel Filling / Front Left Interior / Scratched -



5. Bumper / Front Paint / Chipping -



6. Bumper / Back Paint / Scratch / Line -



7. Roof
Bodywork / Dent / Hail Area -



8. Rim / Front Left
Out of Bodywork / Scratch -




9. Aeration Grid / Front Center
Interior / Broken -



10. Fender / Back Right
Bodywork / Poor Previous Repair -




11. Front Light / Front Right
Bodywork / Breakage -



12. Door / Back Right
Paint / Scratch / Line -




13. Rim / Back Left
Out of Bodywork / Scratch -




14. Front Light / Front Left
Bodywork / Breakage -



15. Rim / Back Right
Out of Bodywork / Scratch -



16. Door / Front Right
Paint / Scratch / Line -



17. Fender / Front Left
Bodywork / Dent / Hail Area -




18. Dashboard / Front
Interior / Non - compliant -




19. Rim / Front Right
Out of Bodywork / Scratch -




20. Door / Front Left
Paint / Scratch / Line -



21. Door / Back Left
Bodywork / Poor Previous Repair -



22. Pillar / Front Left
Bodywork / Dent / Hail Area -



23. Floor Carpet
Interior / Ripped -



24. Seat / Front Left
Interior / Ripped -



25. Center Console
Interior / Worn - out -



26. Pillar / Front Right
Bodywork / Dent / Hail Area -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	⚠
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

General			
Test Driven Status	✓	Test Drive Comment	A/C NON RAFFREDDA
Other Checks			
Steering	✓	Brakes	✓
Suspension	⚠		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	✓		
Gearbox			
Manual Gearbox	✓		

✓ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

⚠ *Damages or malfunction detected that requires repairs by the buyer*

NA *Not applicable*

☐ *Not tested*