



CITROEN C4 CACTUS

C4 Cactus PureTech 110 S&S BVM6 Shine



VIN NO VF70PHNPMKE537942

Registration Number FK889WL

MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250731140512
Inspection Date / Place	2025-07-31 / BCA BETHUNE	Cosmetic Grade	1

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Petrol	Gearbox Type	Manual
Colour	Grey	Engine Size (cc)	1199
Engine Size	1.2	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	104

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No

Manufacturer Warrenty



Equipment


Central locking	Radio	Alloys wheels	Front fog lamps
Power assisted steering	Electrically folding wing mirrors	Rear parking sensors	Cruise control
Front parking sensors	Satellite navigation		

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Cosmetic Damage

15 Dommages



2 Dommages



Component	Damage	Comments
1 Floor Carpet	Interior / Dirty	
2 Floor Carpet	Interior / Dirty	
3 Corner Bumper / Front Right	Paint / Scratch / Scuff	
4 Bumper / Front	Paint / Scratch / Scuff	
5 Corner Bumper / Front Left	Paint / Scratch / Scuff	
6 Rim / Front Left	Out of Bodywork / Scratch	
7 Door / Front Left	Paint / Scratch / Line	
8 Door / Back Left	Paint / Scratch / Line	
9 Rim / Back Left	Out of Bodywork / Scratch	
10 Corner Bumper / Back Left	Paint / Scratch / Scuff	
11 Bumper / Back	Paint / Scratch / Scuff	
12 Corner Bumper / Back Right	Paint / Scratch / Scuff	
13 Rim / Back Right	Out of Bodywork / Scratch	

14	Door / Back Right	Paint / Scratch / Line
15	Door / Front Right	Paint / Scratch / Line
16	Door / Front Right	Paint / Scratch / Line
17	Rim / Front Right	Out of Bodywork / Scratch



1. Floor Carpet
Interior / Dirty -



2. Floor Carpet
Interior / Dirty -



3. Corner Bumper / Front Right
Paint / Scratch / Scuff -



4. Bumper / Front
Paint / Scratch / Scuff -



5. Corner Bumper / Front Left
Paint / Scratch / Scuff -



6. Rim / Front Left
Out of Bodywork / Scratch -




7. Door / Front Left
Paint / Scratch / Line -



8. Door / Back Left
Paint / Scratch / Line -



9. Rim / Back Left
Out of Bodywork / Scratch -



10. Corner Bumper / Back Left
Paint / Scratch / Scuff -



11. Bumper / Back
Paint / Scratch / Scuff -



12. Corner Bumper / Back Right
Paint / Scratch / Scuff -




13. Rim / Back Right
Out of Bodywork / Scratch -



14. Door / Back Right
Paint / Scratch / Line -



15. Door / Front Right
Paint / Scratch / Line -



16. Door / Front Right
Paint / Scratch / Line -



17. Rim / Front Right
Out of Bodywork / Scratch -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut



 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.