

status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

Citroën C4 Picasso/Spacetourer Shine

Vehicle identification number	VF73DBHZTHJ820271	mileage read:	165140 km
First Registration / construction year:	15.02.2018 / 2016	Visit Date / place of birth:	22.08.2025 Mücke-Atzenhain
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	3001//AUZ
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1560 ccm / 88 kW (120 PS)	Engine:	front-wheel drive
paint:	LACK WEISS BANQUISE/TYP AUSSENVERKLEIDUNG SPIEGEL FLACH STANDARD	Number of previous owners:	3
Doors / seats:	5 / 5	number keys:	1
Next HU / AU:	- / -	cushion type:	Imitation leather / fabric
Service book available:	no	Interior Color:	gray
smoking vehicle:	no	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
SD Card	1	no / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

 **available**

 **not available**

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



mounted tires		
Tyre / wheel type:	Winter tires	steel
1st axis - Left / states .	Hankook	205/60/R16/92H 2 mm
1st axis - right / states .	Hankook	205/60/R16/92H 2 mm
2nd axis - Left / states .	Hankook	205/60/R16/92H 0 mm
2nd axis - right / states .	Hankook	205/60/R16/92H 0 mm
traffic Safety:	not roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• 3D style package <i>Heckleuchten LED, 3D-Optik, Seitenscheiben hinten und Heckscheibe dunkel getönt</i> • Airbag Driver / passenger side • Anti- lock braking system (ABS) • Audio Navigation System • Power side mirrors . adjustable , heating and folding • board computer • Connecting box <i>Freisprecheinrichtung Bluetooth, USB-Anschluss</i> • Electr . Brakeforce Distribution • • Driving Assistance System Brake Assist • Electric window . behind with Pulse • Luggage compartment cover / shade • Rearview mirror with auto dip • Body 5-door • Climate Control, Driver / front passenger side can be controlled separately • Komfort-Package Selection <i>Kofferraumdeckel / Heckklappe elektrisch betätigt (öffnen + schliessen, sensorgesteuert)</i> • Steering wheel (leather) • model refinement • Fog Lights • <i>Fahrassistenz-System: Park-Assistent (Parklückendetektor), Einparkhilfe vorn, Einparkhilfe hinten, Rückfahrkamera, Fahrassistenz-System: Totwinkel-Assistent</i> • A pyrotechnic pretensioner • Rußpartikelfilter	• Airbag switched off • Ambiente-Paket Hype Gray <i>Lounge-Paket (inkl. Sitzbezug / Polsterung: Stoff/Leder), Sitze vorn mit Massagefunktion, Lendenwirbelstütze Sitz vorn links und rechts, elektr. verstellbar, Fußmatten, Sitzbezug / Polsterung: Stoff/Leder, Sitz vorn rechts höhenverstellbar</i> • Armrest on front seats • Audio system Radio with CD Player incl. MP3 playback function <i>Audiobedienung am Lenkrad</i> • Bi -xenon headlamps with active light • CD drive in the glove box • Off switch for headlights • Electron. Stability Program (ESP) <i>Antischlupfregelung (ASR)</i> • Driving Assistance System hill start assist • Driving Assistance System Rescue and Assistance System (CITROEN Connect) • Electric window . forward with pulse • Automatic transmission - (6-speed) • Isofix admissions for child seat in back seat • Children package <i>Sonnenschutzrollo an Türscheiben hinten, Rücksitze als Einzelsitze, klappbar / verschiebbar, Kinderspiegel (zusätzlicher Innenspiegel für den Fond), Klapptisch in Fahrer- und Beifahrersitzlehne integriert</i> • Kofferraumabdeckung • Head airbag system • LM rims • 1.6 Ltr motor. - 88 kW Blue-HDI FAP • • Parking brake electrically

• Windscreen wipers with rain sensor • SCR (AdBlue technology) • Side windows Acoustic glass • Front left seat height adjustment • Folding front seat backrests • Stop-start system • LED daytime running lights • Provision for Webasto parking heater	• Tire Pressure Monitoring System • Low emissions Euro 6 emissions standard • Drawer / storage compartment under front left seat • Front Side Airbags • Controlled power steering electronically • Heated front seats • socket 230V • Super Remote central locking • Flashlight, removable • Immobilizer with transponder
--	--

special Features	
• Trailer hitch (ball head removable) • Radio reception digital (DAB) • Safety Package 2 <i>Adaptive Geschwindigkeitsregelanlage (ACC), Fahrassistenten-System: Verkehrszeichenerkennung, Fahrassistenten-System: Totwinkel-Assistent, Fahrassistenten-System: aktiver Spurassistent (Lenkunterstützung)</i>	• Panorama glass roof • Spare wheel as an emergency wheel

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Not performed A visit to the underbody of the car was not performed .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Bereifung verschlissen.

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes .

Existing collision damage:

Evidence that points to a repaired accident damage or repainting carried out , were identified.

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit							
Alternator / Generator:			examined limited	Battery / accumulator:			
oil loss:			examined limited			examined limited	
air conditioning:			examined limited	lighting system:			examined limited
coupling:			unavailable	exhaust System:			examined limited
engine running:			examined limited	shock absorber:			examined limited
transmission:			examined limited				

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



	component	Damage	Rep kind
1.	maintenance	Missing	Replace
2.	proof of maintenance	Missing	Replace
3.	Rear bumper	Scratch(es)	Paint
4.	Sidewall - Rear - Left	Surface scratch(es)	
5.	Rear door - left		Smart repair
6.	Front fender - left	Surface scratch(es)	
7.	key	Missing	Replace
8.	Reifenset	Worn	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside




inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims




rims



engine compartment



service book



Others



Navigation system



3. Rear bumper



3. Rear bumper



3. Rear bumper




4. Sidewall - Rear - Left



4. Sidewall - Rear - Left



5. Rear door - left



5. Rear door - left



6. Front fender - left