



status report

customer: BCA Autoauktionen GmbH

reference:

vehicle data

Citroën Berlingo Kasten Business L2

Vehicle identification number	VF77FBHY6GJ786708	mileage read:	142188 km
First Registration / construction year:	16.09.2016 / 2016	Visit Date / place of birth:	17.09.2025 Hoppegarten
Bodywork:	pickup	Re - import:	no
Body type:	van	KBA no. :	3001//AVV
Fuel / emission class:	diesel / € 6	transmission type:	manual transmission
Displacement / power:	1560 ccm / 73 kW (99 PS)	Engine:	front-wheel drive
paint:	LACK WEISS BANQUISE/DECKENDE LACKIERUNG	Number of previous owners:	2
Doors / seats:	4 / 3	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	no	Interior Color:	gray
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	no	Vehicle roadworthy:	no
Submitted vehicle documents:	Eg II (veh - letter)	state outside:	4 - moderate
visit condition:	-	condition inside:	4 - moderate
state general:	4 - moderate		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
-	2	maintained: no / 6	- / -
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		

☒ **available**

☒ **not available**

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	All season tires	steel
1st axis - Left / states .	Falken	195/65/R15/91H 4 mm
1st axis - right / states .	Falken	195/65/R15/91H 4 mm
2nd axis - Left / states .	Falken	195/65/R15/91H 5 mm
2nd axis - right / states .	Falken	195/65/R15/91H 5 mm
traffic Safety:	not roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Storage compartment above the sun visors • Anti- lock braking system (ABS) • Auflastung • Electrical package <i>Außenspiegel elektr. verstell- und heizbar, beide, Fensterheber elektr. vorn mit Impulsgeber, Zentralverriegelung mit Fernbedienung</i> • Ergonomics package <i>Sitz vorn links höhenverstellbar</i> • Transmission 5-speed • Rear wing doors without glazing • Steering column (steering wheel) adjustable • Headlamp leveling • Engine 1.6 ltr. - 73 kW Blue - HDI FAP • • Low emissions Euro 6 emissions standard • Protective strips wide (PVC) • power steering • Panel in the cargo area • immobilizer	• Airbag driver • Drive Front Wheel Drive • Vinyl Flooring • Electron. Stability Program (ESP) <i>Antischlupfregelung (ASR), Antriebs-Schlupfregelung (ASR)</i> • Driving Assistance System Brake Assist • Rubber mat passenger / load compartment • Body / Structure box • Reading light front • model refinement • Wheelbase 2728 mm • Rußpartikelfilter • Right sliding door without window • SCR (AdBlue technology) • Seat cover / upholstery fabric • Warning system for safety

special Features	
• handsfree Bluetooth <i>Audiosystem: Radio mit CD-Player inkl. MP3-Wiedergabefunktion</i> • Load compartment partition half height (grid and hatch) with sound and heat insulation	• air Conditioning <i>Elektro-Paket, Außenspiegel elektr. verstell- und heizbar, beide, Fensterheber elektr. vorn mit Impulsgeber, Zentralverriegelung mit Fernbedienung</i> • Visibility Package <i>Nebelscheinwerfer, Einschaltautomatik für Fahrlicht, Scheibenwischer mit Regensensor, Audiosystem: Radio mit CD-Player inkl. MP3-Wiedergabefunktion, Bordcomputer</i>

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Reifen beschädigt

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	- -
reference:	

Overview conducted technology audit							
Alternator / Generator:			examined limited	Battery / accumulator:			
oil loss:			examined limited			examined limited	
air conditioning:			examined limited	lighting system:			examined limited
coupling:			not checked	exhaust System:			examined limited
engine running:			examined limited	shock absorber:			not checked
transmission:			not checked				

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The clutch was not tested during the visit .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shocks were not examined during the inspection .
transmission:	The transmission has not been tested for visiting time .
reference:	*Fzg. nur bedingt fahrbereit, Reifen beschädigt; Karosserie war beklebt

damage



component	Damage	Rep kind
1. Key with remote control	No functionality	Replace
2.	Missing	Replace
3. proof of maintenance	Missing	Replace
4. maintenance	Due	Replace
5. hood	Rust	Paint
6. Laderaum	Wear and tear	acceptable
7. Tailgate right	Damaged	Refurbish and paint
8. Tailgate left	Damaged	Refurbish and paint
9. Rear bumper	Damaged	Replace
10. Sidewall - Rear - right	Damaged	Refurbish and paint
11. side skirt - right	Deformed	Refurbish and paint
12.	Dirty	
13. roof	Wear and tear	acceptable
14. Front bumper	Wear and tear	acceptable
15. tire front - left	Damaged	Replace
16. Türeinstieg Vorne - Links	Scrape	Paint
17.	Burn hole	Smart repair
18. Front door - left	Wear and tear	acceptable
19. steering wheel	Wear and tear	acceptable
20. Front door - right	Wear and tear	acceptable
21. Türeinstieg Vorne - Rechts	Wear and tear	acceptable

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims




rims



engine compartment



service book



Others



1. Key with remote control



4. maintenance



5. hood



5. hood



6. Laderaum



6. Laderaum



7. Tailgate right



7. Tailgate right



8. Tailgate left



8. Tailgate left



8. Tailgate left



9. Rear bumper



10. Sidewall - Rear - right



10. Sidewall - Rear - right



11. side skirt - right



12.



13. roof



14. Front bumper



15. tire front - left



16. Türeinstieg Vorne - Links



16. Türeinstieg Vorne - Links



17.



18. Front door - left



19. steering wheel



20. Front door - right



21. Türeinstieg Vorne - Rechts