



Hüsges Gruppe®
Die Gutachter

status report

customer: Bank 11, Neuss
contract number: 497215531
reference:

vehicle data

Citroën Berlingo Kombi Selection

Vehicle identification number	VF77JBHY6FJ800076	mileage read:	121684 km
First Registration / construction year:	24.09.2015 / 2015	Visit Date / place of birth:	16.09.2025 Heidenheim
Bodywork:	pickup	Re - import:	no
Body type:	other	KBA no. :	3001//AVF
Fuel / emission class:	diesel / € 6	transmission type:	manual transmission
Displacement / power:	1560 ccm / 73 kW (99 PS)	Engine:	front-wheel drive
paint:	LACK GRAU ARTENSE/ME TALLIC-LACKIERUNG MIT SCHUTZLACK	Number of previous owners:	Unbekannt
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	yes	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	- / -
Vehicle roadworthy:	no	Vehicle roadworthy:	yes
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	5 - neglected
visit condition:	-	condition inside:	4 - moderate
state general:	4 - moderate		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	yes / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	steel
1st axis - Left / states .	Barum	205/65/R15/94T 5 mm
1st axis - right / states .	Barum	205/65/R15/94T 5 mm
2nd axis - Left / states .	Barum	205/65/R15/94T 5 mm
2nd axis - right / states .	Barum	205/65/R15/94T 5 mm
traffic Safety:	not roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Airbag • Airbag driver • Armrest on front seats • rear opening • Black Package • rear Parking Sensors <i>Außenspiegel elektr. verstell- und heizbar, Außenspiegel elektr. verstellbar, links, Außenspiegel elektr. verstellbar, rechts, Außenspiegel elektr. verstellbar, beide, Außenspiegel elektr. verstell- und heizbar, beide, Außenspiegel anklappbar, beide</i> • Individual seats h . <i>Klapptisch in Fahrer- und Beifahrersitzlehne integriert</i> • Electron. Stability Program (ESP) <i>Antischlupfregelung (ASR)</i> • Driving Assistance System Brake Assist • Luggage compartment cover / shade • Cruise control system (cruise control) incl. Speed ??Begrenzeranlage <i>Geschwindigkeits-Begrenzeranlage</i> • Belt pretensioners with force limiters • heated rear window • Isofix admissions for child seat in back seat • air Conditioning • Rear curtain airbag system • Front center armrest • Engine 1.6 ltr. - 73 kW Blue - HDI FAP • A pyrotechnic pretensioner • Tire Pressure Monitoring System • Rear seat folding 1 / 3-2 / 3 • Windscreen wipers with rain sensor	• Airbag switched off • Anti- lock braking system (ABS) • Audio system Radio with CD Player incl. MP3 playback function <i>Audiobedienung am Lenkrad, Bordcomputer</i> • painted mirrors • Connecting box <i>Freisprecheinrichtung Bluetooth, USB-Box</i> • Off switch for headlights • Electr . Brakeforce Distribution • Driving Assistance System hill start assist • Electric window . forward with pulse • Cruise control system (cruise control) • Transmission 5-speed • Tailgate, window fixed • rear window wiper • Body 5-door • Head airbag system • Steering column (steering wheel) mech. height / longitudinally adjustable • model refinement • Fog Lights • Smokers Package • Rußpartikelfilter • Low emissions Euro 6 emissions standard • Sliding left with hinged • SCR (AdBlue technology) • Side moldings • Front left seat height adjustment • Seat cover / upholstery fabric • LED daytime running lights

• Right sliding door with hinged • Front Side Airbags • power steering • Front right seat folded down • Bumper partially painted • immobilizer	• Central locking with remote control
---	---

special Features	
• Metallic paint	•

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	found At the unrepaired vehicle accident damage were observed on visual examination on the body skin .
reference:	Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine Demontagearbeiten durchgeführt, verborgen gebliebene Schäden können nicht



ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert,
Kostenerweiterung möglich.

Overview conducted technology audit					
Alternator / Generator:			in order	Battery / accumulator:	
oil loss:			examined limited	 in order	
air conditioning:			not possible	lighting system:	
coupling:			not possible	 in order	
engine running:			not possible	exhaust System:	
transmission:			not checked	 examined limited	
				shock absorber:	
				 not checked	

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning could not be checked during the inspection . *kein Motorstart
lighting system:	The lighting system was to tour date in order.
coupling:	The coupling could not be checked during the inspection .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine could not be performed *Motorhaube Startet nicht
shock absorber:	The shocks were not examined during the inspection .
transmission:	The transmission has not been tested for visiting time .
reference:	*Nutzfahrzeug typische Gebrauchsspuren und Beschädigungen.

damage



	component	Damage	Rep kind
1.	Front bumper	Damaged	Replace
2.	tire front - right	Damaged	Replace
3.	Fahrzeug Aussen Gebrauch Spuren (Kratzer,dellen)	Damaged	
4.	Rear bumper	Damaged	Replace
5.	Service	Due	Replace
6.	motor	No functionality	Carry out a fault diagnosis
7.		Dirty (strong)	
8.	center console - flap	Damaged	Replace
9.	key	Damaged	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right




rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims




rims



engine compartment



service book



Others



Navigation system



1. Front bumper



1. Front bumper



1. Front bumper



1. Front bumper



2. tire front - right



3. Fahrzeug Aussen Gebrauch Spuren (Kratzer,dellen)



3. Fahrzeug Aussen Gebrauch Spuren (Kratzer,dellen)



3. Fahrzeug Aussen Gebrauch Spuren (Kratzer,dellen)



3. Fahrzeug Aussen Gebrauch Spuren (Kratzer,dellen)



3. Fahrzeug Aussen Gebrauch Spuren (Kratzer,dellen)



3. Fahrzeug Aussen Gebrauch Spuren (Kratzer,dellen)



3. Fahrzeug Aussen Gebrauch Spuren (Kratzer,dellen)



4. Rear bumper



4. Rear bumper



4. Rear bumper



5. Service



6. motor



6. motor



7.



7.



8. center console - flap



9. key