



status report

customer:	Bank 11, Neuss
contract number:	618229170-INSO
reference:	

vehicle data			
Citroën Berlingo Kombi Selection			
Vehicle identification number	VF77JBHY6GJ832162	mileage read:	117178 km
∴			
First Registration / construction year:	04.11.2016 / 2016	Visit Date / place of birth:	18.08.2025 Heidenheim
Bodywork:	pickup	Re - import:	no
Body type:	other	KBA no. :	3001//AVF
Fuel / emission class:	diesel / € 6	transmission type:	manual transmission
Displacement / power:	1560 ccm / 73 kW (99 PS)	Engine:	front-wheel drive
paint:	LACK ONYX SCHWARZ/DECKENDE LACKIERUNG	Number of previous owners:	2
Doors / seats:	5 / 5	number keys:	1
Next HU / AU:	- / -	cushion type:	substance
Service book available:	no	Interior Color:	gray
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	no	Vehicle roadworthy:	yes
Submitted vehicle	Eg II (veh - letter)	state outside:	3 - Average
documents:		condition inside:	3 - Average
visit condition:	-		
state general:	3 - Average		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	1	no / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	summer tires	Steel with wheel cover
1st axis - Left / states .	Kumho	215/55/R16/93V 1.7 mm
1st axis - right / states .	Kumho	215/55/R16/93V 1.7 mm
2nd axis - Left / states .	Kumho	215/55/R16/93V 1.7 mm
2nd axis - right / states .	Kumho	215/55/R16/93V 1.7 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • Airbag Beifahrerseite (26802) Airbag Beifahrerseite abschaltbar (26909) Airbag Fahrerseite (26801) Anti-Blockier-System (ABS) (40000) Armlehnen an Vordersitze (33406) Ausstellfenster hinten (23300) Außenspiegel lackiert (15709) Black-Paket (3349) Einparkhilfe hinten (25802) Außenspiegel elektr. verstell- und heizbar, Außenspiegel elektr. verstellbar, links, Außenspiegel elektr. verstellbar, rechts, Außenspiegel elektr. verstellbar, beide, Außenspiegel elektr. verstell- und heizbar, beide, Außenspiegel anklappbar, beide Einschaltautomatik für Fahrlicht (18604) Einzelsitze hinten (33801) Klapptisch in Fahrer- und Beifahrersitzlehne integriert Elektr. Bremskraftverteilung (40307) Elektron. Stabilitäts-Programm (ESP) (70308) Antischlupfregelung (ASR) Fahrassistenz-System Berganfahrhilfe (70603) Fahrassistenz-System Notbrems-Assistent (40801) Fensterheber elektr. vorn mit Impulsgeber (35107) Gepäckraumabdeckung / Rollo (27400) Geschwindigkeits-Regelanlage (Tempomat) (26708) Geschwindigkeits-Regelanlage (Tempomat) inkl. GeschwindigkeitsBegrenzeranlage (26713) Geschwindigkeits-Begrenzeranlage Getriebe 5-Gang (76501) Gurtstraffer mit Kraftbegrenzer (37303) Heckklappe, Scheibe fest (36007) Heckscheibe heizbar (22800) Heckscheibenwischer (19300) Isofix-Aufnahmen für Kindersitz an Rücksitz (39308) Karosserie 5-türig (10005) Kopf-Airbag-System (26901) Kopf-Airbag-System hinten | <ul style="list-style-type: none"> • Reifendruck-Kontrollsystem (25903) Rußpartikelfilter (77602) Rücksitzbank klappbar 1/3-2/3 (33601) Schadstoffarm nach Abgasnorm Euro 6 (PSA Euro 6.1) (77227) Scheibenwischer mit Regensensor (19101) Schiebetür links mit Ausstellfenster (36109) Schiebetür rechts mit Ausstellfenster (36201) SCR-System (AdBlue-Technologie) (77030) Seitenairbag vorn (26903) Seitenschutzleisten (20008) Servolenkung (69800) Sitz vorn links höhenverstellbar (32704) Sitz vorn rechts umklappbar (33105) Sitzbezug / Polsterung Stoff (30500) Stop-Start-Anlage (77601) Stoßfänger teilweise lackiert (21304) Tagfahrlicht LED (18913) Verglasung hinten abgedunkelt (22202) Wegfahrsperre (38105) Zentralverriegelung mit Fernbedienung (35301) |
|---|--|

(26805) Lenksäule (Lenkrad) mech.
höhen-/längsverstellbar (69502) Mittelarmlehne
vorn (27202) Modellpflege (250) Motor 1,6 Ltr. - 73
kW Blue-HDI FAP (96559) Nebelscheinwerfer
(18300) Pyrotechnischer Gurtstraffer (37302)
Raucher-Paket (4430)

special Features

- | | |
|---|---|
| <ul style="list-style-type: none"> • City-Paket • Kinder-Paket • Reserverad in Fahrbereifung | <ul style="list-style-type: none"> • Fahrassistenz-System Auffahrwarnsystem mit Bremsfunktion • Komfort-Paket |
|---|---|

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit					
Alternator / Generator:			not possible	Battery / accumulator:	
			Out of order		
oil loss:			Out of order		
air conditioning:			not possible	lighting system:	
			not possible		
coupling:			not possible	exhaust System:	
			not checked		
engine running:			not possible	shock absorber:	
			not checked		
transmission:			not possible		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) could not be verified .
Battery / accumulator:	The battery (accumulator) was discharged for visiting time . **Battery deep discharge.
oil loss:	The vehicle was inspected during the visit to an oil leak . **motor.
air conditioning:	The air conditioning could not be checked during the inspection .
lighting system:	The lighting system could not be tested for visiting time . **No power supply.
coupling:	The coupling could not be checked during the inspection .
exhaust System:	The exhaust system was not tested during the visit .
engine running:	A field test of the engine could not be performed
shock absorber:	The shocks were not examined during the inspection .
transmission:	The transmission could not be checked for visiting time .
reference:	*Nutzfahrzeug typische Gebrauchsspuren und Beschädigungen. Fahrzeug startet nicht. Batterie Tiefentladen.

damage



component	Damage	Rep kind
1. Sidewall - Rear - right	Subsequently painted	acceptable
2. Door Rear - right	Subsequently painted	acceptable
3. Front door - right	Subsequently painted	acceptable
4. Service	Due	Replace
5. Rim front - left	Scratch(es)	Paint
6. Türeinstieg Vorne - Links	Scratch(es)	Paint
7. Rear door - left	Scrape	Refurbish and paint
8. Sidewall - Rear - Left	Accident damage	Refurbish and paint
9. Rear bumper	Accident damage	Refurbish and paint
10. tailgate	Scratch(es)	Paint
11. Taillight left	Accident damage	Replace
12. Sidewall - Rear - Left	Wear and tear	acceptable
13. tailgate	Sticker	
14. Sidewall - Rear - right	Scratch(es)	Paint
15. side skirt - right	Scrape	Refurbish and paint
16. Door Rear - right	Scrape	Refurbish and paint
17. Door Rear - right	Scratch(es)	Paint
18. side skirt - right	Subsequently painted	acceptable
19. Outside mirror - right	Scratch(es)	Paint
20. Rim rear - left	Scratch(es)	Paint
21. proof of maintenance	Missing	Replace
22. key	Missing	Replace
23. motor	Not okay	Carry out a fault diagnosis
24. battery	Empty battery	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



Navigation system



1. Sidewall - Rear - right



1. Sidewall - Rear - right



2. Door Rear - right



2. Door Rear - right



3. Front door - right



3. Front door - right



5. Rim front - left



6. Türeinstieg Vorne - Links



6. Türeinstieg Vorne - Links



7. Rear door - left



7. Rear door - left



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



9. Rear bumper



9. Rear bumper



9. Rear bumper



9. Rear bumper



9. Rear bumper



9. Rear bumper




9. Rear bumper



10. tailgate



10. tailgate



11. Taillight left



11. Taillight left



11. Taillight left



12. Sidewall - Rear - Left



12. Sidewall - Rear - Left



12. Sidewall - Rear - Left



13. tailgate



14. Sidewall - Rear - right



14. Sidewall - Rear - right



15. side skirt - right



15. side skirt - right



15. side skirt - right



16. Door Rear - right



16. Door Rear - right



16. Door Rear - right



17. Door Rear - right



17. Door Rear - right



18. side skirt - right



18. side skirt - right



18. side skirt - right



19. Outside mirror - right



20. Rim rear - left