



CITROEN C1 2012 Benzina  
C1 1.0 Exclusive 3p

VIN NO VF7PMCFB4CR535286  
Registration Number ER403CX



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-07-02	-	-	167437 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2013-03-28	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250923142607
Inspection Date / Place	2025-09-23 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Gearbox Type	Manual
Colour	Black	Engine Size (cc)	998
Engine Size	1.0	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour	Black	No of Seats	4
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	99

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment

Central locking	Digital Radio	Tyre Mobility Kit	Power assisted steering
Trip Computer	Stability control		


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Winter	
		155/65//R14 - 75T / 2 mm
		155/65//R14 - 75T / 2 mm
	SAVA	155/65//R14 - 75T / 1 mm
	SAVA	155/65//R14 - 75T / 1 mm

Cosmetic Damage

14 Danni



4 Danni



Component		Damage	Comments
1	Floor Carpet	Interior / Ripped	
2	Panel Filling / Front Left	Interior / Scratched	
3	Seat / Front Left	Interior / Ripped	
4	Luggage Space Cover / Back	Interior / Broken	
5	Fender / Front Right	Paint / Poor Previous Repair	
6	Bumper / Front	Bodywork / Dent	
7	Hood	Bodywork / Dent / Hail Area	
8	Windshield / Front	Glass Break / Scratch	
9	Fender / Front Left	Paint / Scratch / Line	
10	Door / Front Left	Bodywork / Dent	
11	Fender / Back Left	Bodywork / Dent / Hail Area	
12	Pillar / Front Left	Bodywork / Dent / Hail Area	

13	Bumper / Back	Bodywork / Dent
14	Roof	Bodywork / Dent / Hail Area
15	Pillar / Front Right	Bodywork / Dent / Hail Area
16	Fender / Back Right	Bodywork / Dent
17	Rocker Panel / Center Right	Bodywork / Dent
18	Door / Front Right	Paint / Scratch / Line






1. Floor Carpet  
Interior / Ripped -



2. Panel Filling / Front Left  
Interior / Scratched -



3. Seat / Front Left  
Interior / Ripped -



4. Luggage Space Cover / Back  
Interior / Broken -



5. Fender / Front Right  
Paint / Poor Previous Repair -



6. Bumper / Front  
Bodywork / Dent -





7. Hood  
Bodywork / Dent / Hail Area -



8. Windshield / Front  
Glass Break / Scratch -




9. Fender / Front Left  
Paint / Scratch / Line -



10. Door / Front Left  
Bodywork / Dent -



11. Fender / Back Left  
Bodywork / Dent / Hail Area -



12. Pillar / Front Left  
Bodywork / Dent / Hail Area -






13. Bumper / Back  
Bodywork / Dent -



14. Roof  
Bodywork / Dent / Hail Area -



15. Pillar / Front Right  
Bodywork / Dent / Hail Area -



16. Fender / Back Right  
Bodywork / Dent -



17. Rocker Panel / Center Right  
Bodywork / Dent -



18. Door / Front Right  
Paint / Scratch / Line -

## Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

## Test Drive Inspection

Other Checks			
Steering	✓	Brakes	✓
Suspension	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		
Equipments Test			
Steering   Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	!		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			