

CITROEN C3 C3 Picasso VTi 95 Collection



VIN NO VF7SH8FP0BT526300 Registration Number BQ767LA

Number of Owners

MOT Date

•••

Number of Keys

Odometer Reading

₩-

:2: -

P1

110832 km

Last Service

Last Service Mileage

First Registration Date

Country First Registered

-

2011-06-23

=-

Inspection Report Summary

| Customer | BCAuto Encheres | Report Number | P20250930230120 |
|-------------------------|-------------------------------|----------------|-----------------|
| Inspection Date / Place | 2025-09-30 / BCA INGRANDES | Cosmetic Grade | 2 |

Vehicle Summary

| Vehicle Condition | Non-Runner | VAT Type | Exempt Rate |
|-------------------|---------------|------------------------|-------------|
| Fuel Type | Petrol | Gearbox Type | Manual |
| Colour | Beige | Engine Size (cc) | 1397 |
| Engine Size | 1.4 | No of Doors | 5 |
| Family | Passenger Car | Drive Train | Front |
| Seat Colour | | No of Seats | 5 |
| Charging Cables | | NEDC CO2 Rating (q/km) | 149 |
| Engine Rating CV | 6 | Metalic Colour | No |
| Accident Damage | No | Euro Emission | |

Vehicle History & Documents

| Service Book Available | Missing | Next Service Mileage | km |
|------------------------|------------|----------------------|----|
| Previous Usage | Normal Use | Imported | No |
| Manufacturer Warrenty | | | |























Equipment


Central locking Alloys wheels Power assisted steering Radio

Cruise control

Equipment Details

| Seat Heating | No | Air Conditioning | Yes |
|--------------|------------------|------------------|-----|
| Sunroof Type | Tilt/Slide Steel | | |

Cosmetic Damage



| | Component | Damage | Comments |
|----|----------------------------|-------------------------------|----------|
| 1 | Door / Back Left | Paint / Chipping | |
| 2 | Rim / Back Left | Out of Bodywork / Scratch | |
| 3 | Corner Bumper / Back Right | Paint / Scratch / Scuff | |
| 4 | Fender / Back Right | Bodywork / Dent / Dent | |
| 5 | Door / Front Right | Paint / Scratch / Scuff | |
| 6 | Mirror Shell / Front Right | Paint / Chipping | |
| 7 | Rim / Front Right | Out of Bodywork / Scratch | |
| 8 | Corner Bumper / Front Left | Paint / Scratch / Scuff | |
| 9 | Rim / Front Left | Out of Bodywork / Scratch | |
| 10 | Rim / Front Left | Out of Bodywork / Scratch | |
| 11 | Mirror Shell / Front Left | Bodywork / Breakage | |
| 12 | Rocker Panel / Center Left | Bodywork / Dent / Deformation | |

13 Gear Knob Interior / Broken



1. Door / Back Left Paint / Chipping -

2. Rim / Back Left Out of Bodywork / Scratch -



3. Corner Bumper / Back Right Paint / Scratch / Scuff -



4. Fender / Back Right Bodywork / Dent / Dent -



5. Door / Front Right Paint / Scratch / Scuff -



6. Mirror Shell / Front Right Paint / Chipping -



7. Rim / Front Right
Out of Bodywork / Scratch -

8. Corner Bumper / Front Left Paint / Scratch / Scuff -



9. Rim / Front Left Out of Bodywork / Scratch -




10. Rim / Front Left Out of Bodywork / Scratch -



11. Mirror Shell / Front Left Bodywork / Breakage -



12. Rocker Panel / Center Left Bodywork / Dent / Deformation -



13. Gear Knob Interior / Broken -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut



- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- Not tested

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.