



CITROEN C3 Picasso Diesel
C3 Picasso 1.6 e-hdi (airdream) Seduction
90cv cmp

VIN NO VF7SH9HP4ET525108
Registration Number FH546DR



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2024-10-02	-	-	141128 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2014-08-26	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251008114006
Inspection Date / Place	2025-10-08 / BCA Lodi	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Sequential
Colour	Red	Engine Size (cc)	1560
Engine Size	1.6	No of Doors	5
Body Type	MPV	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	112

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Digital Radio	Remote adjusting wing mirrors	Trip Computer
Power assisted steering	Parcel Shef	Remote central locking	Stability control


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Summer	
	FIRESTONE	195/55//R16 - 87H / 1 mm
	FIRESTONE	195/55//R16 - 87H / 1 mm
	KLEBER	195/55//R16 - 87V / 3 mm
	KLEBER	195/55//R16 - 87V / 3 mm

Cosmetic Damage

21 Danni



10 Danni



46

1

Component	Damage	Comments
1 Windshield / Front	Glass Break / Impact	
2 Roof	Bodywork / Dent / Hail Area	
3 Hood	Bodywork / Dent / Hail Area	
4 Pillar / Front Left	Bodywork / Dent / Hail Area	
5 Bumper / Back	Bodywork / Dent	
6 Panel Filling / Back Right	Interior / Scratched	
7 Panel Filling / Front Left	Interior / Scratched	
8 Pillar / Front Right	Bodywork / Dent / Hail Area	
9 Steering Wheel / Front	Interior / Worn - out	
10 Center Console	Interior / Broken	
11 Fender / Front Left	Bodywork / Dent	
12 Luggage Space Cover / Back	Interior / Broken	

13	Side Window / Front Left	Bodywork / Assembly	Alza cristalli NON FUNZIONANTE
14	Bumper / Front	Bodywork / Breakage	
15	Mirror Shell / Front Right	Bodywork / Breakage	
16	Door / Front Right	Bodywork / Dent	
17	Door / Back Right	Bodywork / Dent	
18	Rocker Panel / Center Left	Bodywork / Dent	
19	Door / Back Left	Paint / Scratch / Line	
20	Fender / Back Left	Bodywork / Dent	
21	Floor Carpet	Interior / Ripped	
22	Dashboard / Front	Interior / Broken	
23	Door / Front Left	Bodywork / Dent	
24	Hubcap / Back Right	Out of Bodywork / Scratch	
25	Fender / Back Right	Bodywork / Dent	
26	Ignition Key	Interior / Broken	
27	Hubcap / Front Right	Out of Bodywork / Scratch	
28	Fender / Front Right	Bodywork / Dent	
29	Tailgate	Bodywork / Dent / Dent	
30	Window Switch / Front Left	Interior / Dysfunctional	
31	Window Switch / Front Left	Interior / Broken	




1. Windshield / Front
Glass Break / Impact -



2. Roof
Bodywork / Dent / Hail Area -



3. Hood
Bodywork / Dent / Hail Area -



4. Pillar / Front Left
Bodywork / Dent / Hail Area -



5. Bumper / Back
Bodywork / Dent -



6. Panel Filling / Back Right
Interior / Scratched -



7. Panel Filling / Front Left
Interior / Scratched -




8. Pillar / Front Right
Bodywork / Dent / Hail Area -



9. Steering Wheel / Front
Interior / Worn - out -




10. Center Console
Interior / Broken -



11. Fender / Front Left
Bodywork / Dent -



12. Luggage Space Cover / Back
Interior / Broken -




13. Side Window / Front Left
Bodywork / Assembly -
Alza cristalli NON FUNZIONANTE




14. Bumper / Front
Bodywork / Breakage -




15. Mirror Shell / Front Right
Bodywork / Breakage -




16. Door / Front Right
Bodywork / Dent -




17. Door / Back Right
Bodywork / Dent -



18. Rocker Panel / Center Left
Bodywork / Dent -



19. Door / Back Left
Paint / Scratch / Line -



20. Fender / Back Left
Bodywork / Dent -



21. Floor Carpet
Interior / Ripped -




22. Dashboard / Front
Interior / Broken -




23. Door / Front Left
Bodywork / Dent -



24. Hubcap / Back Right
Out of Bodywork / Scratch -



25. Fender / Back Right
Bodywork / Dent -



26. Ignition Key
Interior / Broken -



27. Hubcap / Front Right
Out of Bodywork / Scratch -



28. Fender / Front Right
Bodywork / Dent -



29. Tailgate
Bodywork / Dent / Dent -



30. Window Switch / Front Left
Interior / Dysfunctional -



31. Window Switch / Front Left
Interior / Broken -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

General			
Test Driven Status	✓		
Other Checks			
Steering	✓	Brakes	✓
Suspension	!		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	!
Engine Noise	!		
Gearbox			
Manual Gearbox	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested