



Hüsges Gruppe®
Die Gutachter

status report

customer: Bank 11, Neuss
contract number: 585175030
reference:

vehicle data

Citroën Spacetourer Shine XL

Vehicle identification number	VF7VEAHHWJZ065628	mileage read:	197281 km
First Registration / construction year:	27.08.2018 / 2017	Visit Date / place of birth:	20.08.2025 Riedstadt-Goddelau
Bodywork:	transporter	Re - import:	no
Body type:	other	KBA no. :	3001//AWN
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1997 ccm / 130 kW (177 PS)	Engine:	front-wheel drive
paint:	brown	Number of previous owners:	2
Doors / seats:	5 / 7	number keys:	1
Next HU / AU:	- / -	cushion type:	leather
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle	-	state outside:	3 - Average
documents:		condition inside:	3 - Average
visit condition:	-		
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	1	no / -	- / -

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Hankook	225/55/R17/101W 2 mm
1st axis - right / states .	Hankook	225/55/R17/101W 2 mm
2nd axis - Left / states .	Hankook	225/55/R17/101W 2 mm
2nd axis - right / states .	Hankook	225/55/R17/101W 2 mm
traffic Safety:	not roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
Airbag Fahrer-/Beifahrerseite (26803) Anti-Blockier-System (ABS) (40000) Antriebsart Frontantrieb (70600) Audio-Navigationssystem Digitalradio DAB, Connecting-Box, Touchscreen (25721) Freisprecheinrichtung Bluetooth, USB-Anschluss, Mobile Online Dienste MirrorLink, TOUCH PAD 7" Außenspiegel lackiert (15709) Bordcomputer (25508) Elektron. Stabilitäts-Programm (ESP) (70308) Antischlupfregelung (ASR) Fahrassistenz-System Berganfahrhilfe (70603) Fahrassistenz-System Notbrems-Assistent (40801) Fensterheber elektrisch vorn (35001) Fußmatten (28399) Gepäckraum-Abtrennung (Netz) (27605) Getriebe Automatik - (6-Stufen) (76523) Head-up-Display (25204) Heckklappe, Scheibe ausstellbar (36008) Heckscheibenwischer, Heckscheibe heizbar Heckscheibe aufstellbar (22902) Karosserie/Aufbau Kombi (10009) Klimaautomatik (28901) Klimaanlage im Fond Kopf-Airbag-System (26901) Kopf-Airbag-System hinten (26805) Lenkrad (Leder) (69009) Lenksäule (Lenkrad) mech. höhen-/längsverstellbar (69502) Licht-Paket (1702) Xenon-Scheinwerfer, Scheinwerfer-Reinigungsanlage (SRA) LM-Felgen 7x17 (48203) Modutop (Dachstausystem) (17206) Panoramadach (Glas) Motor 2,0 Ltr. - 132 kW Blue-HDI FAP (96548) Nebelscheinwerfer mit statischem Abbiegelicht (18617) Radstand 3275 mm (71835) Reifen-Reparaturkit (68802) Reifendruck-Kontrollsystem indirekt (ohne Lokalisierung) (25906) Rußpartikelfilter (77602) Schadstoffarm	Sitze vorn elektr. verstellbar (32607) Sitz vorn links elektr. verstellbar, Sitz vorn rechts elektr. verstellbar Sitze vorn mit Massagefunktion (33124) Sitzheizung vorn (29500) Sitzkombination (1) 5-Sitzer (34632) Sonnenblenden mit Spiegel (beleuchtet) (37905) Sonnenschutzrollo an Türscheiben hinten (27408) Steckdose 230V (38904) Stop-Start-Anlage (77601) Stoßfänger lackiert (21303) Tagfahrlicht LED (18913) Türgriffe außen verchromt (36403) Wegfahrsperre mit Transponder (38104)

nach Abgasnorm Euro 6 (PSA Euro 6.1) (77227)
 Schiebetüren links und rechts elektr. betätigt
 (öffnen schliessen, sensorgesteuert) (36329)
 Zentralverriegelung / Startanlage Keyless System,
 Schiebetür rechts elektr. betätigt, Schiebetür rechts
 elektr. betätigt (öffnen schliessen, sensorgesteuert)
 SCR-System (AdBlue-Technologie) (77030)
 Seitenairbag vorn (26903) Seitenscheiben hinten
 und Heckscheibe dunkel getönt (23103)
 Seitenschutzleisten Wagenfarbe (20009)
 Servolenkung (69800) Sicht-Paket (1906)
 Einschaltautomatik für Fahrlicht, Scheibenwischer
 mit Regensensor, Innenspiegel mit
 Abblendautomatik Sitzbezug / Polsterung Leder
 (30200)

special Features

- | | |
|---|---|
| <ul style="list-style-type: none"> • Allwetter-/ Ganzjahresreifen • Drive-Assist-Paket • Fahrassistenz-System Notruf- und Assistance-System (CITROEN Connect) • Metallic-Lackierung | <ul style="list-style-type: none"> • Anhängerkupplung (Kugelkopf abnehmbar) • Einparkhilfe vorn und hinten inkl. Rückfahrkamera • Gepäckraumabdeckung / Rollo • Sicherheits-Paket 1 |
|---|---|

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed.
Mileage plausible:	not testable not testable Wartungsnachweise fehlen
reference:	
Note Road Safe:	Reifen HL Undicht

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted
---	--

repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.

**Layers of paint thickness
measurement:**

Out of tolerance

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			Out of order	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine had to acoustic or visual defects for visiting time . *Fehlermeldung
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Nutzfahrzeug typische Gebrauchsspuren und Beschädigungen.

damage



component	Damage	Rep kind
1. Front door - right	Subsequently painted	acceptable
2. Door Rear - right	Subsequently painted	acceptable
3. Sidewall - Rear - Left	Subsequently painted	acceptable
4. Rim front - left	Damaged	Replace
5. Rim front - right	Damaged	Replace
6. Sitz Vorne Links	Damaged	Smart repair
7. flooring	Dirty (animal hair)	
8. Zweitschlüssel	Missing	Replace
9. proof of maintenance	Missing	Replace
10. maintenance	Due	Replace
11. Bremslicht	Error message	Carry out a fault diagnosis
12. tire rear - left	Leaky	Replace
13. Halogen headlights - right	Scratch(es)	Replace
14. Front bumper	Scrape	Paint
15. Windshield	Damaged	Replace
16. Front fender - left	Deformed	Refurbish and paint
17. Front door - left	Wear and tear	acceptable
18. Türeinstieg Vorne - Links	Deformed	Refurbish and paint
19. Rear door - left	Scratch(es)	Paint
20. Türeinstieg Hinten - Links	Deformed	Refurbish and paint
21. Sidewall - Rear - Left	Execution defect	Refurbish and paint
22. Rear bumper	Damaged	Replace
23.	Dirty (animal hair)	
24.	Odour	Ozone treatment
25. tailgate trim	Damaged	Smart repair
26. Sidewall - Rear - right	Deformed	Refurbish and paint
27. side skirt - right	Deformed	Refurbish and paint
28. Door Rear - right	Execution defect	Refurbish and paint
29. Türeinstieg Hinten - Rechts	Deformed	Refurbish and paint
30. 3. Sitzreihe Sitze Lehne Links	Damaged	Replace
31. headlining	Damaged	Smart repair
32. Front door - right	Scratch(es)	Paint
33. Türeinstieg Vorne - Rechts	Damaged	Refurbish and paint
34.	Damaged	Smart repair
35. A-pillar Front - right	Delle	Smart repair
36. tailgate	Damaged	Refurbish and paint
37. motor	Error message	Carry out a fault diagnosis

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in

normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



1. Front door - right



2. Door Rear - right



3. Sidewall - Rear - Left



4. Rim front - left



5. Rim front - right



5. Rim front - right



6. Sitz Vorne Links



6. Sitz Vorne Links



7. flooring



7. flooring



10. maintenance



11. Bremslicht



12. tire rear - left



12. tire rear - left



13. Halogen headlights - right



14. Front bumper



15. Windshield



15. Windshield




15. Windshield



16. Front fender - left



17. Front door - left



17. Front door - left



18. Türeinstieg Vorne - Links



18. Türeinstieg Vorne - Links



19. Rear door - left



19. Rear door - left



20. Türeinstieg Hinten - Links



20. Türeinstieg Hinten - Links



21. Sidewall - Rear - Left



21. Sidewall - Rear - Left



21. Sidewall - Rear - Left



22. Rear bumper



22. Rear bumper



23.



23.



23.



25. tailgate trim



25. tailgate trim



26. Sidewall - Rear - right



26. Sidewall - Rear - right



27. side skirt - right



28. Door Rear - right



28. Door Rear - right



29. Türeinstieg Hinten - Rechts




30. 3. Sitzreihe Sitze Lehne Links



30. 3. Sitzreihe Sitze Lehne Links



31. headlining



32. Front door - right



32. Front door - right



33. Türeinstieg Vorne - Rechts



34.



35. A-pillar Front - right



36. tailgate



36. tailgate



36. tailgate



37. motor