



TOYOTA Yaris III 2017 5p Benzina
Yaris 5p 1.5h Cool my18

VIN NO VNKKD3D390A486456
Registration Number FR275WZ



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2024-07-04	-	-	99800 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2018-07-31	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251009104906
Inspection Date / Place	2025-10-09 / BCA Lodi	Cosmetic Grade	3


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Hybrid	Gearbox Type	Automatic
Colour	Red	Engine Size (cc)	1497
Engine Size	1.5	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	84

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment


Central locking	Digital Radio	Parcel Shef	Remote central locking
Tyre Mobility Kit	Power assisted steering	Volante multifuncion	Remote adjusting wing mirrors
Trip Computer	Stability control		

Wheels & Tyres


Mounted Tires

Tyre / Wheel Type	Summer	
	LASSA	175/65//R15 - 84H / 1 mm
	LASSA	175/65//R15 - 84H / 1 mm
	LASSA	175/65//R15 - 84H / 2 mm
	LASSA	175/65//R15 - 84H / 2 mm

16 Danni



1 Danni



5/11 - Report Number P20251009104906

13	Roof	Bodywork / Dent / Small Dent
14	Fender / Front Left	Bodywork / Dent
15	Door / Back Right	Paint / Scratch / Line
16	Mirror Repeater / Right	Bodywork / Breakage
17	Mirror Repeater / Left	Glass Break / Scratch




1. Windshield / Front
Glass Break / Impact -



2. Bumper / Back
Bodywork / Dent -




3. Hood
Paint / Chipping -



4. Bumper / Front
Bodywork / Dent -



5. Luggage Space Cover / Back
Interior / Scratched -




6. Fender / Back Right
Paint / Chipping -




7. Mirror Shell / Front Right
Bodywork / Breakage -



8. Hubcap / Front Right
Out of Bodywork / Scratch -



9. Door / Front Right
Paint / Scratch / Line -



10. Door / Back Left
Paint / Scratch / Line -



11. Fender / Front Right
Bodywork / Poor Previous Repair -




12. Mirror Shell / Front Left
Paint / Scratch / Line -




13. Roof
Bodywork / Dent / Small Dent -



14. Fender / Front Left
Bodywork / Dent -



15. Door / Back Right
Paint / Scratch / Line -



16. Mirror Repeater / Right
Bodywork / Breakage -



17. Mirror Repeater / Left
Glass Break / Scratch -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Hybrid/EV			
Hybrid System Fault	✓		
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

General			
Test Driven Status	✓		
Other Checks			
Steering	✓	Brakes	✓
Suspension	✓		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	✓		
Gearbox			
Manual Gearbox	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

 *Not tested*