


Vehicle details

VIN	VNVK14004 65693433	Brand	NISSAN	Maintenance date	-
Licence Plate	J7-93-JK	Model	MICRA IG-T 100 ActieAuto 5d N-Connecta APL	Maintenance mileage	-
Registration date	20/08/2020	Year	2020	Exterior Color	Silver Metallic
Odometer	81 157 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	27/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 195/55/16 Summer 4.5 mm		Michelin 195/55/16 Summer 4.5 mm	
Michelin 195/55/16 Summer 6.0 mm		Michelin 195/55/16 Summer 6.0 mm	

Exterior

1



PartStep plate

PositionFront right

DamagesDent & Chips

Severity-

Repair modeFor info

2



PartStep plate

PositionBack left

DamagesDent & Chips

Severity-

Repair modeFor info

3



PartStep plate

PositionFront left

DamagesDent & Chips

Severity-

Repair modeFor info

4



PartBumper

PositionFront

DamagesScratched

Severity-

Repair modeRepair

5



PartRoof post A/B/C

PositionLeft

DamagesDented

SeverityNumber > 2

Repair modeSmart Repair

6



PartRoof

Position-

DamagesScratched

Severity-

Repair modeRepair

7



PartDoor

PositionFront left

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair

8



PartSill

PositionLeft

DamagesScratched

Severity-

Repair modeRepair

9



PartWing

PositionBack left

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair

10



PartAlloy wheel 16"

PositionBack left

DamagesScratched

Severity-

Repair modeLumpsum repair

11



PartTailgate / Boot door

PositionBack

DamagesDented

SeverityNumber > 2

Repair modeSmart Repair

12



PartBumper

PositionBack

DamagesScratched

Severity-

Repair modeRepair

13



PartWing

PositionBack right

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair