


Vehicle details

VIN	VNVK14006 62439224	Brand	NISSAN	Maintenance date	-
Licence Plate	XP-53-6D	Model	MICRA IG-T 100 ActieAuto 5d N-Connecta APL	Maintenance mileage	-
Registration date	20/02/2019	Year	2019	Exterior Color	Black Metallic
Odometer	76 532 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	20/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓


Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Pirelli 195/55/16 Summer 6.5 mm		Pirelli 195/55/16 Summer 6.0 mm	
Continental 195/55/16 Summer 5.5 mm		Continental 195/55/16 Summer 5.5 mm	

Exterior

2		Part Position Damages Severity Repair mode	Rocker panel cap Back left Scratched - Smart Repair	4		Part Position Damages Severity Repair mode	Alloy wheel 16" Front left Scratched - Lumpsum repair
5		Part Position Damages Severity Repair mode	Door Front left Dented Diameter (mm) > 20 Repair	6		Part Position Damages Severity Repair mode	Step plate Front left Dent & Chips - For info
7		Part Position Damages Severity Repair mode	Bumper Back Scratched Length (cm) > 10 Repair	8		Part Position Damages Severity Repair mode	Wing Back right Dented Diameter (mm) > 20 Repair
9		Part Position Damages Severity Repair mode	Door Back right Dented Diameter (mm) > 20 Repair	10		Part Position Damages Severity Repair mode	Roof post A/B/C Right Dented Diameter (mm) > 20 Smart Repair
11		Part Position Damages Severity Repair mode	Bumper Front Scratched Length (cm) > 10 Repair	12		Part Position Damages Severity Repair mode	Roof - Dent & Chips Diameter (mm) > 20 Repair

Interior damage

1		Part Position Damages Severity Repair mode	Interior tailgate lining Down Scratched - Smart Repair	3		Part Position Damages Severity Repair mode	Fabric seat Front right Stained/dirty - Cleaning
---	---	--	--	---	--	--	--