

Vehicle details

VIN	VR3ECYHYC LJ873630	Brand	PEUGEOT	Maintenance date	-
Licence Plate	G665US	Model	Rifter Lang Allure 1,5 BlueHDi 100 S&S 75KW	Maintenance mileage	-
Registration date	14/12/2020	Year	1000	Exterior Color	White Solid
Odometer	67 327 km	Engine size	1499	interior Color	Black
Fuel	Diesel	Body Type	Passenger van	Next technical inspection	01/12/2025
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	06/03/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Anti-fog lights	✓
Reversing radars	✓

Removable element


--	--

Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓


Tyres

Winter kit


Continental 215/65/16 H Winter 9.7 mm		Continental 215/65/16 H Winter 9.8 mm	
Bridgestone 215/65/16 H Winter 6.6 mm		Continental 215/65/16 H Winter 8.6 mm	

Exterior

2		Part	Windscreen	3		Part	Bumper moulding
		Position	-			Position	Front left
		Damages	Stone impact			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	Repair

4		Part Position Damages Severity Repair mode	Bumper extension moulding Front right Scratched - Replace	5		Part Position Damages Severity Repair mode	Bonnet - Hail damaged - Repair
6		Part Position Damages Severity Repair mode	Wing Back left Hail damaged - Repair	7		Part Position Damages Severity Repair mode	Bumper moulding Back Scratched - Replace
8		Part Position Damages Severity Repair mode	Wing Back right Scratched - Repair	9		Part Position Damages Severity Repair mode	Wing moulding Back right Scratched - Replace
10		Part Position Damages Severity Repair mode	Exterior door mirror shell Right Scratched - Repair	11		Part Position Damages Severity Repair mode	Roof - Hail damaged - Repair

Interior damage

1		Part Position Damages Severity Repair mode	Remote key - Missing - Replace	12		Part Position Damages Severity Repair mode	Fabric door lining Front right Scratched - Replace
---	---	--	--	----	--	--	--

Others

13		Part Position Damages Severity Repair mode	Paint preparation - - - Paintworks	14		Part Position Damages Severity Repair mode	Paint preparation - - - Plastic paint
----	---	--	--	----	--	--	---